

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6531 1188

**TOYOTA**

Steve (LKK)
 23/9/21, 11:00

WML A.L
 12 djs
 PIP

Stevechen@IKKauto.com

83278813

ESTIMATE

My Belisy

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355			
			Document No.					
			0					
			Document Date					
			22/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFZ28H3800068291		2NRX543415	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES T/P INS. : <i>compac</i> T/P VEH. : GBK5772R ACC DATE : 21.09.21 BY : <i>LKK</i>						50 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#) (REAR WITH CASING)						80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)						200.00
4	B	BP-LAB2 RRSET AND REPROGRAMME ECU.						180.00
5	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.						180.00
6	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.						180.00
7	B	BP-LAB2 REMOVE TAIL-GTAE COMPONENTS TO TRANSFER ONTO NEW DOOR.						360.00
8	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.						450.00
9	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.						300.00
10	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR. (photo)						360.00
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 120462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355		
			Document No.				
			0				
			Document Date				
			22/09/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800068291		2NRX543415	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER AND TAIL-GATE.					183.18 ✓
12	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR. <i>5 x 720</i>					<i>3600</i> 2080.00
13	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. <i>6 x 550</i>					<i>3540</i> 2050.00
14	1	S52159-0U919 COVER, RR BUMPER, L <i>00</i>	1.00	319.20			319.20
15	2	S52151-0D010 EXTENSION, RR BUMPER <i>cut (8kk)</i>	1.00	191.80			191.80
16	3	S52161-0D070 EXTENSION, RR BUMPER <i>?</i>	1.00	130.30			130.30
17	4	S52162-0D040 EXTENSION, RR BUMPER <i>?</i>	1.00	130.30			130.30
18	5	SPC507-0D014 24 BACK SENSOR (1G3,GRAY ME) <i>BR</i>	1.00	174.50			174.50
19	6	S52155-0D110 SUPPORT, RR BUMPER S <i>?</i>	1.00	74.10			74.10
20	7	S52156-0D100 SUPPORT, RR BUMPER S <i>?</i>	1.00	74.10			74.10
21	8	S52575-0D280 RETAINER, RR BUMPER <i>?</i>	1.00	71.10			71.10
22	9	S52576-0D270 RETAINER, RR BUMPER <i>?</i>	1.00	71.10			71.10
23	0	S52161-0K040 PIECE,RR BUMPER <i>acc</i>	4.00	4.10			16.40
24	1	S58307-0D320 PANEL SUB-ASSY, BODY <i>(odr)</i> <i>on (photo)</i>	1.00	438.20			438.20
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Tan Mun Chong Desmond (Chen WenCong)				
		Document No. 0	207 Bishan Street 23 #07-399 Singapore 570207				
		Document Date 22/09/2021	Mobile: 92983355				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800068291		2NRX543415	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
25	2	S64716-0D170 C0 COVER, DECK TRIM, RR	1.00	155.90		155.90	
26	3	S58302-0D010 PANEL SUB-ASSY, LWR (11111) - DO	1.00	702.90		702.90	
27	4	S67005-0D360 PANEL SUB-ASSY, BACK - DO	1.00	1142.50		1142.50	
28	5	S68105-0D261 GLASS SUB-ASSY, BACK - nec (photo)	1.00	1041.50		1041.50	
29	6	S64813-0D330 DAM, BACK WINDOW GLA - nec	2.00	12.50		25.00	
30	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA - nec	2.00	108.00		216.00	
31	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER - nec	1.00	200.00		200.00	
32	9	S76801-0D600 GARNISH SUB-ASSY, BA (chrome) - BR	1.00	231.80		231.80	
33	0	S75431-0M080 EMBLEM LUGGAGE COMPA - nec	1.00	53.90		53.90	
34	1	S75441-0D070 PLATE, BACK DOOR NAM - nec	1.00	53.70		53.70	
35	2	S75442-0D300 PLATE, BACK DOOR NAM - nec	1.00	35.80		35.80	
36	3	T81270-0D120 LAMP ASSY, LICENSE	2.00	66.30		132.60	
37	4	T89997-30100 ANTENNA, ELECTRICAL	1.00	72.60		72.60	
38	5	T81480-52070 LAMP ASSY, RR FOG, - BR	1.00	236.70		236.70	
39	6	S81580-0D240 LAMP ASSY, RR, RH (Tailg) - BR	1.00	137.40		137.40	
40	7	S81590-0D240 LAMP ASSY, RR, LH (") - BR	1.00	137.40		137.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 14,869.98
- To survey before/after spray painting - To display damaged parts during survey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be recovered and is subject to final approval from Insurance Company			Please acknowledge receipt of vehicle		Total		
			Parts 6,266.80		GST 7.00% 1,040.90		
			Labour 8,040.00		Less 0.00		
			Sublet 563.18				
			Lubrication/Fluid 0.00				
Others 0.00		Amount Due 15,910.88					
Acknowledged by Repairer Signature: Date:			Company Copy				

**Borneo Motors**

Inchcape

Co. Reg No. : 196700006Z

GST Reg No. : MR-0500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no. 6631 1188

**TOYOTA****INTERNAL INVOICE**

Account Details			Account No.		Customer Details			
New vehicle preparation PDI ***** For use by BMS PDI *****			i0100001 / NEWVEHIC		Mr MCD Tan 207 Bishan Street 23 #07-399 Singapore 570207			
			Document No. 38053991					
			Document Date 01/02/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	1	58606	69INT/SMW5847R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFZ28H3800068291		2NRX543415	00	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	M	D1068*-PLATINUM SHINEPRO						250.00
		* PSPRO PDI LABOUR FOR PLATINUM SHINE PDI						
		D1068D) Platinum Shine Glass Coating						
2		* PSPRO MAT PDI PLATINUM SHINE SET						
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	250.00
			Please acknowledge receipt of vehicle		Parts	0.00	GST 0.00%	0.00
					Labour	0.00	Less	0.00
					Sublet	0.00		
					Lubrication/Fluid	0.00		
					Others	250.00	Amount Due	250.00

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 1967000862
 GST Reg No. : MR-850000-9
 62 West Coast Ferry Road
 Singapore 126978, Fax 6631 1579

**TOYOTA****INTERNAL INVOICE**

Account Details			Account No.		Customer Details			
New vehicle preparation PDI ***** For use by BMS PDI *****			i0100001 / NEWVEHIC		Mr MCD Tan 207 Bishan Street 23 #07-399 Singapore 570207			
			Document No.					
			52213296					
			Document Date					
			07/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP170R	MWYNKT S4		SMW5847R	1	42997	DL-0031	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFZ28H3800068291		2NRX543415	00	Ng Wan Nee	13/11/2020 0.00		18/11/2020 12.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	S	D781D COMPLIMENTARY SOLAR FILM - CLASSIC FILM 3M (ALL PD1085) Retail Classic Solar Film			0741	1.00	538.00	538.00
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						538.00		
		Please acknowledge receipt of vehicle		Parts 0.00		GST 0.00%		
				Labour 0.00		Less 0.00		
				Sublet 538.00				
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due 538.00		

Company Copy