

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Sep-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1155 P

1 pc	Front o/s head lamp	\$	1,531.57	XSVL
1 pc	Front bumper	\$	811.11	XSVL
1 pc	Front bumper emblem	\$	27.80	XNN
2 pcs	Front bumper o/s side bracket @ \$32.51	\$	65.02	XNN
1 pc	Front bumper o/s upper bracket	\$	92.60	XNN
1 pc	Front bumper o/s support bracket	\$	37.01	XNN
1 pc	Front o/s fender	\$	514.02	DD
1 pc	Front o/s fender inner shield	\$	176.72	?
1 pc	Front o/s fender signal lamp	\$	32.10	CRK
1 pc	Front o/s mud flap	\$	47.45	?
1 pc	Front o/s rim	\$	246.00	XSVL
1 pc	Front o/s door	\$	1,723.60	DD
2 pcs	Front o/s door hinges @ \$36.10	\$	72.20	?
1 pc	o/s mirror assy	\$	742.49	CRK
		\$	6,119.69	
Less 20%		\$	1,223.94	
		\$	4,895.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/NETT

1 set	Front bumper clips	\$	48.00	XNN
1 pc	Front o/s fender sticker	\$	30.00	NEC
1 pc	o/s door stickers	\$	100.00	NEC
1 pc	16" Tyre (Tyre Brand: Hankook)	\$	200.00	XNN

Sundry \$ 50.00 XNN

Towing Fee \$ 50.00

To focus/check front n/s & o/s head lamps \$ 60.00 XNN

To check front o/s wheel alignment \$ 80.00 ?

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 XNN

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, o/s rocker panel, etc \$ 1,200.00 540 460

To putty and spray painting on front bumper, front o/s fender, front o/s door, o/s rocker panel \$ 800.00 540 460

To apply rustproofing on the repaired and replaced panels. \$ 150.00 50

\$ 7,843.75

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK

24/9/2021 1735

LIS

4 DAYS

CHECK ITEM

PHOTO

AFTER REPAIR

PHOTO

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Sep-21

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1155 P

1 pc	o/s rocker panel		R	\$	1,935.09
		Less 20%		\$	387.02
				\$	<u>1,548.07</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**