

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Sep-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1155 P

1 pc	Front o/s head lamp	\$	1,531.57	XSVL
1 pc	Front bumper	\$	811.11	XSVL
1 pc	Front bumper emblem	\$	27.80	XNN
2 pcs	Front bumper o/s side bracket @ \$32.51	\$	65.02	XNN
1 pc	Front bumper o/s upper bracket	\$	92.60	XNN
1 pc	Front bumper o/s support bracket	\$	37.01	XNN
1 pc	Front o/s fender	\$	514.02	DD
1 pc	Front o/s fender inner shield	\$	176.72	?
1 pc	Front o/s fender signal lamp	\$	32.10	CRK
1 pc	Front o/s mud flap	\$	47.45	?
1 pc	Front o/s rim	\$	246.00	XSVL
1 pc	Front o/s door	\$	1,723.60	DD
2 pcs	Front o/s door hinges @ \$36.10	\$	72.20	?
1 pc	o/s mirror assy	\$	742.49	CRK
		\$	6,119.69	
Less 20%		\$	1,223.94	
		\$	4,895.75	

S/NETT

1 set	Front bumper clips	\$	48.00	XNN
1 pc	Front o/s fender sticker	\$	30.00	NEC
1 pc	o/s door stickers	\$	100.00	NEC
1 pc	16' Tyre (Tyre Brand: Hankook)	\$	200.00	XNN
Sundry		\$	50.00	XNN
Towing Fee		\$	50.00	
To focus/check front n/s & o/s head lamps		\$	60.00	XNN
To check front o/s wheel alignment		\$	80.00	?
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	XNN
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, o/s rocker panel, etc		\$	1,200.00	540 460
To putty and spray painting on front bumper, front o/s fender, front o/s door, o/s rocker panel		\$	800.00	540 460
To apply rustproofing on the repaired and replaced panels.		\$	150.00	50
		\$	7,843.75	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

NA2 LKX
4/19/2021 1735
LIS

4 DAYS
CHECK ITEM
PHOTO)
AFTER REPAIR
PHOTO)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Sep-21

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1155 P

1 pc	o/s rocker panel	R	\$	1,935.09
		Less 20%	\$	387.02
			\$	<u>1,548.07</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**

Repair days 04.

P = ~~473012.21~~ - 20% = ~~47309.76~~

SK = ~~47130.00~~

L = ~~471260.00~~

473799.76 - 20% = ~~473050.76~~

After

PREMEIR AUTOMOTIVE SERVICE PTE LTD

Work Order ID

SHD1155P

Name

AFTER

Technician

YAO

Date

2021-September-28 08:13p.m.

Hyundai : i30/Elantra Neos

2017- (PDe) Independent Rear Suspension : Rest of World

Left Front					Right Front			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-0°25'	-0°24'	1°00'	0°00'	Camber	-0°35'	-0°35'	1°00'	0°00'
.		5°54'	6°54'	Caster			5°54'	6°54'
0°04'	-0°20'	0°03'	0°09'	Toe	0°04'	0°09'	0°03'	0°09'
.		1°00'	15°00'	SAI			1°00'	15°00'
.		13°00'	15°00'	Included Angle			13°00'	15°00'
.				Turning Angle Diff.				

Front			
	Actual	Before	Specified Range
Cross Camber	0°09'	0°11'	
Cross Caster			
Total Toe	0°08'	0°01'	0°06' 0°18'

Left Rear					Right Rear			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-0°44'	-0°45'	1°42'	-0°42'	Camber	-1°09'	-0°47'	1°42'	-0°42'
0°07'	0°07'	0°02'	0°10'	Toe	0°06'	0°11'	0°02'	0°10'

Rear			
	Actual	Before	Specified Range
Total Toe	0°13'	0°19'	0°04' 0°20'
Thrust Angle	0°01'	-0°02'	

Before

PREMEIR AUTOMOTIVE SERVICE PTE LTD

Work Order ID

SHD1155P

Technician

YAO

Date

2021-September-28 08:11p.m.

Hyundai : i30/Elantra Neos

2017- (PDe) Independent Rear Suspension : Rest of World

Left Front					Right Front			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-0°25'	-0°24'	1°00'	0°00'	Camber	-0°35'	-0°35'	1°00'	0°00'
.....		5°54'	6°54'	Caster			5°54'	6°54'
-0°10'4"	-0°10'3"	0°03'	0°09'	Toe	0°04'	0°09'	0°03'	0°09'
.....		14°00'	15°00'	SAI			14°00'	15°00'
.....		13°00'	15°00'	Included Angle			13°00'	15°00'
.....				Turning Angle Diff.				

Front			
	Actual	Before	Specified Range
Cross Camber	0°10'	0°11'	
Cross Caster			
Total Toe	0°00'	0°01'	0°06' 0°18'

Left Rear					Right Rear			
Actual	Before	Specified Range			Actual	Before	Specified Range	
-0°44'	-0°45'	0°42'	-0°42'	Camber	-1°09'	-0°45'	0°42'	-0°42'
0°07'	0°07'	0°02'	0°10'	Toe	0°05'	0°02'	0°02'	0°10'

Rear			
	Actual	Before	Specified Range
Total Toe	0°12'	0°19'	0°04' 0°20'
Thrust Angle	0°01'	-0°02'	