

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 2

Hui Zhen.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0780/2021/ZK

16-Nov-21

CHANG

1 of 1

SGN 1691 S

AUDI Q5 S-LINE TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR LHS FRONT LOWER A-PILLAR.	\$ 400.00	250
2	TO RESPRAY LHS FRONT LOWER A-PILLAR.	\$ 800.00	550
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT A/C VACUUM AND REGAS (R1234yf) S/N	\$ 2,000.00	✓
Parts			
1	SIGN - UNLEADED PETROL nec	\$ 30.00	✓
GRAND TOTAL		\$ 3,230.00	

For Premium Automobiles Pte Ltd

Adrian L.
16/11/21

+ 07 days



Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION WITH SUBFRAME	S/N \$ 2,400.00	?
12	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	S/N \$ 400.00	280.
13	TO REMOVE CENTER CONSOLE, INSTRUMENTS PANELS AND CLUSTERS. RENEW DASHBOARD SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ 3,200.00	✓
14	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. RENEW WHERE NECESSARY.	S/N \$ 1,800.00	✓
15	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER, RHS FRONT DOOR AND HEADLIGHT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD ROOFTOP PANEL. RHS A PILLAR, RHS UPPER A-PILLAR REINFORCEMENT, RHS SILL PANEL AND RHS B PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 16,800.00	4000 (without replacement of roof and A pillar reinforcement)
SUB TOTAL LABOUR CHARGES (FORNTAL)		\$ 24,600.00	+ lock carrier 1500. + B-pillar with sill panel 2000. 1000

Handwritten signature



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
16	TO RESPRAY FRONT BUMPER, BOTH FRONT LOWER SPOILERS, BOTH FRONT FENDER, BONNET, HINGES, BOTH FRONT DOORS, DOOR COVER, DOOR HANDLE, RHS WING MIRROR COVER, RHS A-PILLAR, RHS SILL PANEL, RHS B-PILLAR, ROOFTOP PANEL, BOTH ROOF CHANNELS, DOOR ENTRANCES AND BOTH FRONT WHEEL ARCH TRIMS.	S 12,400.00	Bumper 550 2 Fender = 1100 Bonnet = 550 2 Door = 1100 2 Door Cov = 400 Door handle = 100 Mirror 100 Cover Spoiler 5150 Apillar: 550 Roof = 825 2 wheel Arch = 400 Door Entrance = 275
17	TO CARRY OUT CLEANUP FOR WINDOW GLASSES IN THE INTERIOR.	S.N \$ 280.00	✓
18	TO RENEW LHS FRONT RIM, RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 600.00	✓ B-pillar + 550. sill panel + 550.
19	TO REMOVE AND REINSTALL BOTH ROOFTOP RAIL. RENEW WHERE NECESSARY	S/N \$ 280.00	✓ ?
TOTAL LABOUR CHARGES (FRONTAL)		: \$ 45,520.00	total Spray Paint 7.2K

slip

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0780/2021/ZK

8-Oct-21

CHANG

1 of 1

SGN 1691 S

AUDI Q5 S-LINE TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	LED LIGHT - RH FRONT <i>new</i>	\$ 67.00	✓
2	INNER ACTUATOR - RH <i>new</i>	\$ 255.00	✓
3	TRAY - RH LOWER <i>lit</i>	\$ 548.00	✓
4	DASHBOARD ALUMINIUM TRIM - RH <i>new</i>	\$ 447.00	✓
5	DASHBOARD ALUMINIUM TRIM - LH <i>new</i>	\$ 1,068.00	✓
6	PADDING FOR SEAT DEPTH <i>new</i>	\$ 142.00	✓
7	DISPLAY AND CONTROL PANEL WITH CU (A/C) <i>new</i>	\$ 3,121.00	✓
8	DRIVE SHAFT SCREW <i>new</i>	\$ 46.00	✓
9	BRAKE HOSE - LH FRONT	\$ 72.00	?
10	ENGINE MOUNTING - LH	\$ 370.00	?
11	SUBFRAME CONSOLE - LH	\$ 562.00	?
GRAND TOTAL		\$ 6,698.00	

For Premium Automobiles Pte Ltd

Authorized Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6341 1183
 EMAIL: NORA@HAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del</i>	1 S	1,362.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not m</i>	1	TBC	
3	FRONT BUMPER SECURING STRIP (LH / RH) <i>LT cracked</i>	2 S	76.00	38.
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Not m</i>	2 S	222.00	✓
5	FRONT BUMPER GRILLE - CENTER <i>Not m</i>	1 S	402.00	✓
6	FRONT BUMPER PARKING AID SENSOR SUPPORT <i>Not m</i>	2 S	58.00	✓
7	FRONT BUMPER SPOILER - CENTER <i>Not m</i>	1 S	866.00	✓
8	FRONT BUMPER SPOILER - LH / RH <i>LT Missing</i>	2 S	452.00	226.
9	FRONT BUMPER CLOSING ELEMENT - CENTER <i>Not m</i>	1 S	421.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LT Missing</i>	2 S	534.00	267
11	FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH <i>LT Missing</i>	2 S	68.00	34
12	FRONT BUMPER TRIM (LH / RH) <i>LT Missing</i>	2 S	322.00	161.
13	FRONT RADIATOR GRILLE <i>Not m</i>	1 S	3,470.00	✓
14	QUATTRO EMBLEM <i>Not m</i>	1 S	106.00	✓
15	FRONT BUMPER STRIKER PLATE <i>Not m</i>	1 S	244.00	✓
16	FRONT PARKING AID SENSOR	4	TBC	✓
17	FRONT PARKING AID SENSOR SEAL	4 S	14.00	✓
18	FRONT BUMPER REINFORCMENT FOAM PIECE <i>* cracked</i>	1 S	183.00	✓
19	FRONT BUMPER REINFORCMENT BAR	1 S	981.00	✓
20	FRONT BUMPER BRACKET - LH	1 S	256.00	?
SUB TOTAL SPARE PARTS		:	S	10,037.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



65 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE		REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
21	FRONT BUMPER GUIDE SECTION (LH/RH) <i>Byd</i>	2	\$ 78.00	✓	
22	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 129.00	✓	
23	CAUTION STICKER <i>green</i>	1	\$ 14.00	✓	
24	AIR CONDITIONER STICKER	1	\$ 20.00	✓	
25	HORN - LH <i>green</i>	1	\$ 195.00	✓	
26	HORN - RH	1	\$ 195.00	✓	
27	BONNET <i>Distorted</i>	1	\$ 4,058.00	✓	
28	BONNET HINGE - LH / RH <i>green</i>	2	\$ 327.00	✓	
29	BONNET ATTACHMENT PARTS	1	\$ 141.00	✓	
30	BONNET IMPACT PROTECTOR - CENTER / LH / RH <i>new</i>	3	\$ 84.00	✓	
31	FRONT FENDER - LH / RH <i>Distorted</i>	2	\$ 2,854.00	✓	
32	FRONT FENDER ATTACHMENT PARTS ?	1	\$ 66.00	✓	
33	FRONT FENDER BRACKET (LH/RH) <i>Best</i>	2	\$ 36.00	✓	
34	FRONT FENDER BRACE (LH/RH) <i>Best</i>	2	\$ 450.00	✓	
35	FRONT FENDER CLOSING ELEMENT - RH <i>Byd</i>	1	\$ 105.00	✓	
36	FRONT FENDER MOUNTING BRACKET - RH ?	1	\$ 18.00	✓	
37	FRONT FENDER FILLER COVER - LH / RH <i>PH</i>	2	\$ 62.00	✓	
38	FRONT FENDER FILLER TOP COVER - LH / RH <i>PH</i>	2	\$ 80.00	✓	
39	FRONT FENDER FILLER COVER - OUTER LH / RH <i>PH</i>	2	\$ 156.00	✓	
40	S-LINE EMBLEM <i>new</i>	2	\$ 225.00	✓	

SUB TOTAL SPARE PARTS

: \$ 9,288.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6341 1183
EMAIL: NGBA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5GN 1691 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	HEADLIGHT MOUNTING - LH / RH ?	2 S	236.00	
42	FRONT RADIATOR BRACE - LH / RH <i>new</i>	2 S	114.00	
43	HEADLIGHT - LH / RH <i>2nd cut</i>	2 S	13,075.00 6989	
44	HEADLIGHT CYLINDER - LH / RH <i>new</i>	2 S	280.00	
45	WINDSHIELD WASHER HOSE ?	1 S	125.00	
46	HEADLIGHT WASHER HOSE <i>new</i>	1 S	68.00	
47	HEADLIGHT WASHER PUMP	1 S	155.00	
48	WASHER RESERVOIR <i>Rehd</i>	1 S	235.00	✓
49	WINDSHIELD WASHER PUMP ?	1 S	125.00	
50	FRONT RADIATOR - <i>lock camber. cracked</i>	1 S	1,400.00	✓
51	FRONT RADIATOR SUPPORT - LH <i>new</i>	1 S	53.00	
52	FRONT BUMPER SENSOR BRACKET	1 S	16.00	
53	COOLANT <i>new</i>	6 S	260.00	✓
54	FRONT RADIATOR AIR GUIDE - LH / RH / UPPER / LOWER ? <i>new</i>	4 S	19.00	
55	FRONT RADIATOR AIR GUIDE - CENTER	1 S	42.00	
56	FRONT WHEEL HOUSING LINER - LH / RH <i>Rehd</i>	2 S	528.00	
57	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>	1 S	38.00	
58	FRONT WHEEL SPOILER (LH / RH) <i>new</i>	2 S	320.00	
59	FRONT WHEEL COVER - LH / RH <i>Distorted</i>	2 S	1,264.00	✓
60	SIDE PANEL FRAME - RH <i>Distorted</i>	1 S	6,944.00	✓
SUB TOTAL SPARE PARTS		:	\$ 26,379.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



51 CUBER ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6341 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT WINDSCREEN	1	\$ 1,501.00	
62	FRONT WINDSHIELD RAIN SENSOR	1	\$ 147.00	
63	FRONT WINDSHIELD RAIN SENSOR SPRING	1	\$ 21.00	
64	FRONT WIPER - RH <i>new</i>	1	\$ 1,121.00	
65	PILLAR A REINFORCEMENT - RH OUTER <i>Dented</i>	1	\$ 1,374.00	✓
66	FRONT SIDE WINDOW - RH <i>new</i>	1	\$ 832.00	
67	FUEL FLAP <i>Dented</i>	1	\$ 323.00	
68	FUEL FILLING HOUSING <i>cracked</i>	1	\$ 155.00	✓
69	FRONT DOOR - RH <i>D. started</i>	1	\$ 4,085.00	
70	FRONT DOOR - OUTER SEAL RH <i>new</i>	1	\$ 205.00	✓
71	BONDING AGENT	1	\$ 49.00	
72	CLEANING SOLUTION	1	\$ 68.00	
73	APPLICATOR	1	\$ 8.00	
74	GROMMET	5	\$ 14.00	
75	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 264.00	✓
76	FRONT DOOR CATCH - RH <i>new</i>	1	\$ 146.00	
77	FRONT DOOR HINGE - RH UPPER / LOWER <i>Dented</i>	4	\$ 184.00	
78	FRONT DOOR SEAL - INNER RH <i>new</i>	1	\$ 205.00	✓
79	FRONT DOOR COVER - RH <i>lit</i>	1	\$ 790.00	
80	FRONT SILL TRIM STRIP - RH <i>new</i>	1	\$ 591.00	✓
SUB TOTAL SPARE PARTS		:	\$ 11,079.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55, BR1 ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
E-MAIL: MORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	DATA TAG <i>Nec</i>	1	\$ 462.00	✓	
82	TYER PRESSURE DATA TAG <i>Nec</i>	1	\$ 38.00	✓	
83	FRONT DOOR HANDLE TRIM - RH <i>Distorted</i>	1	\$ 128.00	✓	
84	LOCK CYLINDER WITH HOUSING <i>Dmgd</i>	1	\$ 540.00	✓	
85	FRONT DOOR HANDLE COVER TRANSPARENT - RH <i>Dmgd</i>	1	\$ 6.00	✓	
86	FRONT DOOR HANDLE SENSOR - RH <i>Dmgd</i>	1	\$ 228.00	✓	
87	FRONT DOOR HANDLE EXTERIOR - RH <i>could</i>	1	\$ 44.00	✓	
88	DOOR UNDERLAY - FRONT / REAR <i>Nec</i>	2	\$ 8.00	✓	
89	FRONT DOOR MOUNTING BAR <i>Dmgd</i>	1	\$ 164.00	✓	
90	FRONT DOOR PERIPHERAL LIGHT <i>RH Dmgd</i>	1	\$ 72.00	✓	
91	FRONT WINDOW WITHOUT REGULATOR MOTOR - RH <i>Dmgd</i>	1	\$ 278.00	✓	
92	FRONT WINDOW WITH REGULATOR MOTOR - RH <i>Nec</i>	1	\$ 237.00	✓	
93	FRONT DOOR CONTROL UNIT - RH <i>Nec</i>	1	\$ 794.00	✓	
94	FRONT DOOR LOCK - RH <i>Dmgd</i>	1	\$ 515.00	✓	
95	FRONT DOOR STRIKER <i>Nec</i>	1	\$ 60.00	✓	
96	WING MIRROR - RH <i>Distorted</i>	1	\$ 1,749.00	✓	
97	WING MIRROR CAP - RH <i>Distorted</i>	1	\$ 491.00	✓	
98	WING MIRROR GLASS - RH <i>Distorted</i>	1	\$ 1,908.00	✓	
99	CONTACT HOUSING 16 PIN <i>Nec</i>	1	\$ 6.00	✓	
100	FRONT DOOR CONER TRIM - RH <i>Nec</i>	1	\$ 4.00	✓	
SUB TOTAL SPARE PARTS <i>cluded</i>		:	\$ 7,760.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55TH ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6341 1183
EMAIL: NINEA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICE		REMARKS
			S/NETT		
101	FRONT WINDOW TRIM STRIP - RH <i>Dented</i>	1	\$	340.00	✓
102	FRONT WINDOW GUIDE - RH <i>cut</i>	1	\$	488.00	✓
103	FRONT WINDOW INNER SEAL - RH <i>new cut</i>	1	\$	113.00	✓
104	FRONT DOOR SEAL - RH <i>new</i>	1	\$	15.00	✓
105	FRONT B PILLAR TRIM - RH <i>cut</i>	1	\$	197.00	✓
106	FRONT WINDOW SLOT SEAL - RH <i>Dented</i>	1	\$	616.00	✓
107	FRONT DOOR WINDOW - RH <i>Shattered</i>	1	\$	298.00	✓
108	FRONT DOOR TRIM - RH <i>cut</i>	1	\$	2,310.00	✓
109	FRONT DOOR WINDOW TRIM - RH <i>new cut</i>	1	\$	144.90	✓
110	FRONT DOOR ARMREST - RH <i>new</i>	1	\$	591.00	X
111	FRONT DOOR HANDLE COVER - RH <i>new</i>	1	\$	158.00	X
112	FRONT DOOR TRIM INSERT ALUMINIUM - RH OUTER <i>new cut</i>	1	\$	629.00	✓
113	FRONT DOOR WIRING SET <i>new</i>	1	\$	577.00	X
114	REAR DOOR - RH <i>Dented</i>	1	\$	4,085.00	✓
115	REAR DOOR - OUTER SEAL RH <i>new</i>	1	\$	205.00	✓
116	BONDING AGENT	1	\$	49.00	✓
117	CLEANING SOLUTION	1	\$	68.00	✓
118	APPLICATOR	1	\$	8.00	✓
119	REAR DOOR SEALING STRIP - RH <i>new</i>	1	\$	17.00	✓
120	GROMMET <i>new</i>	3	\$	9.00	✓

SUB TOTAL SPARE PARTS

\$ 10,917.00

ALL CHARGES ARE NETT EXCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55, UPI ROAD 1, SINGAPORE 408699
TEL: 6360 2323 FAX: 6361 1183
EMAIL: NURAJAH@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
121	REAR DOOR ATTACHMENT PART <i>also in</i>	1	\$ 222.00		X
122	REAR DOOR LATCH <i>?</i>	1	\$ 146.00		?
123	REAR DOOR SEAL - INNER <i>also in</i>	1	\$ 205.00		✓
124	SILL PANEL SEAL - RH <i>Also New</i>	1	\$ 253.00		✓
125	REAR DOOR HINGE - RH UPPER / LOWER <i>Damaged</i>	4	\$ 184.00		✓
126	REAR DOOR COVER - RH <i>cut</i>	1	\$ 689.00		✓
127	REAR DOOR HANDLE TRIM PLATE - RH <i>Damaged</i>	1	\$ 275.00		✓
128	REAR DOOR HANDLE HOUSING - RH <i>also damaged</i>	1	\$ 18.00		✓
129	REAR DOOR HANDLE COVER TRANSPARENT - RH <i>also in</i>	1	\$ 6.00		✓
130	REAR DOOR HANDLE SENSOR - RH <i>also in</i>	1	\$ 228.00		✓
131	REAR DOOR HANDLE EXTERIOR - RH <i>also in</i>	1	\$ 44.00		✓
132	REAR DOOR MOUNTING BAR - RH <i>also in</i>	1	\$ 164.00		✓
133	REAR WINDOW WITHOUT REGULATOR MOTOR - RH <i>from</i>	1	\$ 314.00		✓
134	REAR WINDOW WITH REGULATOR MOTOR - RH	1	\$ 351.00		✓
135	REAR DOOR CONTROL UNIT - RH	1	\$ 751.00		✓
136	REAR DOOR LOCK - RH <i>also in</i>	1	\$ 661.00		✓
137	REAR DOOR STRIKER	1	\$ 69.00		✓
138	REAR WINDOW GUIDE - RH <i>also in</i>	1	\$ 488.00		X
139	REAR WINDOW TRIM STRIP - RH <i>cut</i>	1	\$ 187.00		✓
140	REAR WINDOW INNER SEAL - RH <i>also in</i>	1	\$ 205.00		✓

SUB TOTAL SPARE PARTS

: \$ 5,570.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55, UPI ROAD 1, SINGAPORE 408699
TEL: 6360 2323 FAX: 6341 1163
EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCN 1691 S

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICE	
				REMARKS	PRICE
141	REAR WINDOW SLOT SEAL - RH <i>warpped</i>	1	S	✓	616.00
142	REAR DOOR SEAL - RH <i>new</i>	2	S	✓	30.00
143	REAR B PLIAR TRIM - RH <i>cut</i>	1	S	✓	223.00
144	REAR C PLIAR TRIM - RH <i>new</i>	1	S	✓	149.00
145	REAR WINDOW GUIDE RAIL - RH <i>new</i>	1	S	✓	72.00
146	REAR DOOR WINDOW - RH <i>new</i>	1	S	✓	298.00
147	REAR DOOR - LH <i>Dented</i>	1	S	✓	4,085.00
148	REAR DOOR OUTER SEAL - LH <i>new</i>	1	S	✓	205.00
149	BONDING AGENT <i>?</i>	1	S	✓	49.00
150	CLEANING SOLUTION <i>?</i>	1	S	✓	68.00
151	APPLICATOR <i>?</i>	1	S	✓	8.00
152	REAR DOOR SEALING STRIP - LH <i>new</i>	1	S	✓	17.00
153	GROMMET <i>new</i>	3	S	✓	9.00
154	REAR DOOR ATTACHMENT PART <i>new</i>	1	S	✓	222.00
155	REAR DOOR CATCH - LH <i>?</i>	1	S	✓	146.00
156	REAR DOOR COVER - LH <i>Del-d</i>	1	S	✓	689.00
157	REAR BUMPER - UPPER <i>Del-d</i>	1	S	✓	2,397.00
158	REAR BUMPER - LOWER <i>new</i>	1	S	✓	1,182.00
159	TAIL LIGHT - UPPER RH <i>new</i>	1	S	✓	5,746.00
160	TAIL LIGHT - LOWER RH <i>new</i>	1	S	✓	699.00
SUB TOTAL SPARE PARTS		:	S		16,909.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6166 2323 FAX: 6341 1183
EMAIL: HERRA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
161	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2 S	1,166.00	
162	ROOF TOP PANEL <i>new</i>	1 S	4,646.00	
163	INNER ROOF RAIL <i>new</i>	1 S	1,836.00	
164	INNER ROOF RAIL NUT	6 S	213.00	
165	HEAD AIRBAG UNIT - LH / RH <i>Activated</i>	1 S	3,726.00	
166	AIRBAG CONTROL UNIT	1 S	2,114.00	
167	AIRBAG CRASH SENSOR	1	TBC	
168	CENTRAL PROTECTION FUSE <i>new</i>	1 S	533.00	
169	FRONT SEATBELT - LH / RH <i>Activated</i>	2 S	2,234.00	
170	FRONT SEATBELT ADJUSTER <i>new</i>	2 S	342.00	
171	ROOF HEADLINER <i>new</i>	1 S	3,660.00	
172	FRONT ROOF HANDLE <i>new</i>	2 S	283.00	
173	REAR ROOF HANDLE <i>new</i>	2 S	284.00	
174	A - PILLAR TRIM - UPPER <i>new</i>	2 S	474.00	
175	UPPER B-PILLAR TRIM - LH / RH <i>new</i>	2 S	602.00	
176	C - PILLAR TRIM - LH / RH <i>new</i>	2 S	628.00	
177	D - PILLAR TRIM - LH / RH <i>new</i>	2 S	408.00	
178	A - PILLAR TRIM - LOWER RH <i>new</i>	1 S	149.00	
179	B - PILLAR TRIM - LOWER RH <i>new</i>	1 S	234.00	
180	REAR WHEEL HOUSING TRIM - RH <i>new</i>	1 S	252.00	
SUB TOTAL SPARE PARTS		:	\$ 23,782.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (DO) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 JIRI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAZ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
181	REAR FENDER INNER TRIM - RH <i>Me n</i>	1	\$ 75.00	<i>✓</i>
182	DASHBOARD	1	\$ 6,372.00	
183	DASHBOARD CENTER AIR VENT	1	\$ 2,273.00	<i>✓</i>
184	DASHBOARD AIR VENT	1	\$ 591.00	<i>✓</i>
185	STEERING WHEEL <i>Me n</i>	1	\$ 2,374.00	<i>✓</i>
186	FRONT SEAT - RH <i>ut</i>	1	TBC	<i>✓</i>
187	FRONT SEAT PADDING - RH <i>Me n</i>	1	TBC	
188	FRONT SEAT COVER - RH <i>ut</i>	1	TBC	<i>✓</i>
189	FRONT CENTER CONSOLE	1	\$ 815.00	<i>✓</i>
190	FRONT CENTER CONSOLE INSERT <i>Me n</i>	1	\$ 402.00	<i>✓</i>
191	FRONT CENTER CONSOLE TRIM <i>ut</i>	1	\$ 741.00	<i>✓</i>
192	FRONT CENTER CONSOLE INSERT STOWAGE <i>Me n</i>	1	\$ 60.00	
193	FRONT CENTER CONSOLE STOWAGE COMPARTMENT	1	\$ 144.00	<i>✓</i>
194	ASSEMBLY CARRIER	1	\$ 1,891.00	<i>✓</i>
195	FRONT WISHBONE LINK - LH	1	\$ 539.00	<i>✓</i>
196	FRONT SUSPENSION GUIDE - LH	1	\$ 343.00	<i>✓</i>
197	UPPER SUSPENSION GUIDE - FRONT / REAR LH	2	\$ 720.00	<i>✓</i>
198	WHEEL BEARING HOUSING - LH	1	\$ 1,138.00	<i>✓</i>
199	SWIVEL JOINT	1	\$ 193.00	<i>✓</i>
200	WHEEL HUB <i>nec</i>	1	\$ 479.00	<i>✓</i>
SUB TOTAL SPARE PARTS			\$	20,347.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



35 UBI ROAD 1, SINGAPORE 408699
TEL: 6356 2323 FAX: 6341 1183
EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICE		REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
201	FRONT WHEEL BEARING	1	\$ 346.00		
202	SUSPENSION FORKS - LH	1	\$ 366.00		
203	COUPLING ROD	1	\$ 127.00		
204	FRONT ANTI - ROLL BAR	1	\$ 433.00		
205	AXLE ASSEMBLY	1	\$ 2,865.00		
206	SHOCK ABSORBER	1	\$ 1,483.00		
207	LEVEL SENSOR WITH POLES	1	\$ 535.00		
208	STERRING GEAR WITH TRACK ROD JOINT	1	\$ 6,782.00		
209	TRACK ROD	1	\$ 134.00		
210	TIE ROD END - LH	1	\$ 197.00		
211	ROOF HEADER PANEL	1	\$ 262.00		
212	INNER ROOF REINFORCEMENT	1	\$ 247.00		
213	1 PACK ADHESIVE	1	\$ 73.00		
214	ROOF PANEL BONDING ADHESIVE	1	\$ 23.00		
215	PRIMER	1	\$ 20.00		
216	FRONT DOOR COVER - LH	1	\$ 790.00		
217	STATIC MIXER	5	\$ 56.00		
218	BLINDER RIVET STUD	10	\$ 62.00		
219	FRONT NO PLATE	S/N	TBC		
220	FRONT 2 RIMS - LH / RH	3	TBC		
SUB TOTAL SPARE PARTS			\$	14,701.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPECIAL PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 LORRAINE 1, SINGAPORE 408699
TEL: 6465 2323 FAX: 6461 1183
E-MAIL: SALES@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICE	
			S/NETT	REMARKS
221	REAR RIM - LH <i>lit</i>	1	TBC	✓
222	FRONT 2 TYRES - LH / RH <i>2H ton</i>	2	TBC	✓
223	REAR TYRE - LH <i>green</i>	1	TBC	✓
224	ACRYLIC SEALANT	S/N 5	180.00	✓
225	GRAVITY WAX	S/N 5	140.00	✓
226	STONE CHIP TREATMENT	S/N 5	180.00	✓
227	METAL FILLER POWDER	S/N 5	280.00	✓
227	REAR WINDSCREEN SEALANT <i>me a</i>	S/N 5	200.00	✓
228	REAR 1/4 GLASS SEALANT <i>me</i>	S/N 5	100.00	✓
229	SUNDRIES	5	1,500.00	✓
TOTAL SPARE PARTS		:	\$ 159,349.00	
TOTAL LABOUR CHARGES		:	\$ 65,664.00	
GRAND TOTAL		:	\$ 225,013.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.