

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate - 1

Hui Zhen.

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br>Attn: Mr. Adrian Ling - Motor Claims Dept<br>Tel: 6841 0055 / Fax: 6256 4315 |                                                    | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0780/2021/ZK<br>8-Oct-21<br>CHANG<br>1 of 1<br>SGN 1691 S<br>AUDI Q5 S-LINE TFSI |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|
| Quantity                                                                                                                                                                               | Description                                        | Unit Price                                                                                                        | Amount                                                                                 |
| <b>Parts</b>                                                                                                                                                                           |                                                    |                                                                                                                   |                                                                                        |
| 1                                                                                                                                                                                      | LED LIGHT - RH FRONT <i>new</i>                    | \$ 67.00                                                                                                          | ✓                                                                                      |
| 2                                                                                                                                                                                      | INNER ACTUATOR - RH <i>new</i>                     | \$ 255.00                                                                                                         | +                                                                                      |
| 3                                                                                                                                                                                      | TRAY - RH LOWER <i>lit</i>                         | \$ 548.00                                                                                                         | ✓                                                                                      |
| 4                                                                                                                                                                                      | DASHBOARD ALUMINIUM TRIM - RH <i>new</i>           | \$ 447.00                                                                                                         | +                                                                                      |
| 5                                                                                                                                                                                      | DASHBOARD ALUMINIUM TRIM - LH <i>new</i>           | \$ 1,068.00                                                                                                       | X                                                                                      |
| 6                                                                                                                                                                                      | PADDING FOR SEAT DEPTH <i>new</i>                  | \$ 142.00                                                                                                         | +                                                                                      |
| 7                                                                                                                                                                                      | DISPLAY AND CONTROL PANEL WITH CU (A/C) <i>new</i> | \$ 3,121.00                                                                                                       | +                                                                                      |
| 8                                                                                                                                                                                      | DRIVE SHAFT SCREW <i>new</i> 6                     | \$ 46.00                                                                                                          | ✓                                                                                      |
| 9                                                                                                                                                                                      | BRAKE HOSE - LH FRONT                              | \$ 72.00                                                                                                          | ?                                                                                      |
| 10                                                                                                                                                                                     | ENGINE MOUNTING - LH ?                             | \$ 370.00                                                                                                         | ?                                                                                      |
| 11                                                                                                                                                                                     | SUBFRAME CONSOLE - LH ?                            | \$ 562.00                                                                                                         | ?                                                                                      |
| <b>GRAND TOTAL</b>                                                                                                                                                                     |                                                    | <b>\$ 6,698.00</b>                                                                                                |                                                                                        |

For Premium Automobiles Pte Ltd



Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

|                       |                                                                     |     | DAMAGED PARTS & PRICES |         |  |
|-----------------------|---------------------------------------------------------------------|-----|------------------------|---------|--|
| S/N                   | PARTS DESCRIPTION                                                   | QTY | S/NETT                 | REMARKS |  |
| 1                     | FRONT BUMPER <i>dehd</i>                                            | 1   | S 1,362.00             | ✓       |  |
| 2                     | FRONT BUMPER FIXING PARTS <i>Not m</i>                              | 1   | TBC                    | X       |  |
| 3                     | FRONT BUMPER SECURING STRIP <i>LH / RH</i> <i>Not m</i>             | 2   | S 76.00                | +       |  |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Not m</i>                 | 2   | S 222.00               | +       |  |
| 5                     | FRONT BUMPER GRILLE - CENTER <i>Not m</i>                           | 1   | S 402.00               | +       |  |
| 6                     | FRONT BUMPER PARKING AID SENSOR SUPPORT <i>Not m</i>                | 2   | S 58.00                | +       |  |
| 7                     | FRONT BUMPER SPOILER - CENTER <i>Not m</i>                          | 1   | S 866.00               | +       |  |
| 8                     | FRONT BUMPER SPOILER - LH / RH <i>LH Missing</i>                    | 2   | S 452.00               | 226     |  |
| 9                     | FRONT BUMPER CLOSING ELEMENT - CENTER <i>Not m</i>                  | 1   | S 421.00               | +       |  |
| 10                    | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH Missing</i>           | 2   | S 534.00               | 267     |  |
| 11                    | FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH <i>LH Missing</i> | 2   | S 68.00                | 34      |  |
| 12                    | FRONT BUMPER TRIM <i>LH / RH</i> <i>Not m</i>                       | 2   | S 322.00               | +       |  |
| 13                    | FRONT RADIATOR GRILLE <i>Not m</i>                                  | 1   | S 3,470.00             | +       |  |
| 14                    | QUATTRO EMBLEM <i>Not m</i>                                         | 1   | S 106.00               | +       |  |
| 15                    | FRONT BUMPER STRIKER PLATE <i>Not m</i>                             | 1   | S 244.00               | +       |  |
| 16                    | FRONT PARKING AID SENSOR                                            | 4   | TBC                    | +       |  |
| 17                    | FRONT PARKING AID SENSOR SEAL                                       | 4   | S 14.00                | +       |  |
| 18                    | FRONT BUMPER REINFORCMENT FOAM PIECE                                | 1   | S 183.00               | +       |  |
| 19                    | FRONT BUMPER REINFORCMENT BAR                                       | 1   | S 981.00               | +       |  |
| 20                    | FRONT BUMPER BRACKET - LH                                           | 1   | S 256.00               | ?       |  |
| SUB TOTAL SPARE PARTS |                                                                     | :   | \$ 10,037.00           |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S**

|                       |                                                       |     | DAMAGED PARTS & PRICES |          |    |
|-----------------------|-------------------------------------------------------|-----|------------------------|----------|----|
| S/N                   | PARTS DESCRIPTION                                     | QTY | S/NETT                 | REMARKS  |    |
| 21                    | FRONT BUMPER GUIDE SECTION LH / RH ?                  | 2   | S                      | 78.00    | ✓  |
| 22                    | FRONT BUMPER TOP COVER <i>new</i>                     | 1   | S                      | 129.00   | ✓  |
| 23                    | CAUTION STICKER <i>new</i>                            | 1   | S                      | 14.00    | ✓  |
| 24                    | AIR CONDITIONER STICKER <i>new</i>                    | 1   | S                      | 20.00    | ✓  |
| 25                    | HORN - LH <i>new</i>                                  | 1   | S                      | 195.00   | ✓  |
| 26                    | HORN - RH <i>new</i>                                  | 1   | S                      | 195.00   | ✓  |
| 27                    | BONNET <i>Distorted</i>                               | 1   | S                      | 4,058.00 | ✓  |
| 28                    | BONNET HINGE - LH / RH <i>new</i>                     | 2   | S                      | 322.00   | ✓  |
| 29                    | BONNET ATTACHMENT PARTS <i>new</i>                    | 1   | S                      | 141.00   | ✓  |
| 30                    | BONNET IMPACT PROTECTOR - CENTER / LH / RH <i>new</i> | 3   | S                      | 84.00    | ✓  |
| 31                    | FRONT FENDER - LH / RH <i>Distorted</i>               | 2   | S                      | 2,854.00 | ✓  |
| 32                    | FRONT FENDER ATTACHMENT PARTS ?                       | 1   | S                      | 66.00    | ?  |
| 33                    | FRONT FENDER BRACKET LH / RH ?                        | 2   | S                      | 36.00    | ?  |
| 34                    | FRONT FENDER BRACE LH / RH ?                          | 2   | S                      | 450.00   | ?  |
| 35                    | FRONT FENDER CLOSING ELEMENT - RH ?                   | 1   | S                      | 105.00   | ?  |
| 36                    | FRONT FENDER MOUNTING BRACKET - RH ?                  | 1   | S                      | 18.00    | ?  |
| 37                    | FRONT FENDER FILLER COVER - LH / RH <i>new</i>        | 2   | S                      | 62.00    | 31 |
| 38                    | FRONT FENDER FILLER TOP COVER - LH / RH <i>new</i>    | 2   | S                      | 80.00    | 40 |
| 39                    | FRONT FENDER FILLER COVER - OUTER LH / RH <i>new</i>  | 2   | S                      | 156.00   | 78 |
| 40                    | S-LINE EMBLEM <i>new</i>                              | 2   | S                      | 225.00   | ✓  |
| SUB TOTAL SPARE PARTS |                                                       | :   | \$                     | 9,288.00 |    |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL : NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S**

|                       |                                                                   |     | DAMAGED PARTS & PRICES  |         |  |
|-----------------------|-------------------------------------------------------------------|-----|-------------------------|---------|--|
| S/N                   | PARTS DESCRIPTION                                                 | QTY | S/NETT                  | REMARKS |  |
| 41                    | HEADLIGHT MOUNTING - LH / RH ?                                    | 2   | \$ 236.00               | >       |  |
| 42                    | FRONT RADIATOR BRACE - LH / RH <i>new</i>                         | 2   | \$ 114.00               | +       |  |
| 43                    | HEADLIGHT - LH / RH <i>2nd cut</i>                                | 2   | \$ <del>13,978.00</del> | 6989    |  |
| 44                    | HEADLIGHT CYLINDER - LH / RH <i>new</i>                           | 2   | \$ 280.00               | x       |  |
| 45                    | WINDSHIELD WASHER HOSE                                            | 1   | \$ 125.00               | x       |  |
| 46                    | HEADLIGHT WASGER HOSE                                             | 1   | \$ 68.00                | +       |  |
| 47                    | HEADLIGHT WASHER PUMP                                             | 1   | \$ 155.00               | +       |  |
| 48                    | WASHER RESERVOIR                                                  | 1   | \$ 235.00               | ?       |  |
| 49                    | WINDSHIELD WASHER PUMP ?                                          | 1   | \$ 125.00               | ?       |  |
| 50                    | FRONT RADIATOR                                                    | 1   | \$ 1,400.00             | +       |  |
| 51                    | FRONT RADIATOR SUPPORT - LH                                       | 1   | \$ 53.00                | +       |  |
| 52                    | FRONT BUMPER SENSOR BRACKET                                       | 1   | \$ 16.00                | +       |  |
| 53                    | COOLANT                                                           | 6   | \$ 266.00               | x       |  |
| 54                    | FRONT RADIATOR AIR GUIDE - LH / RH / UPPER / LOWER <i>2nd cut</i> | 4   | \$ 192.00               | +       |  |
| 55                    | FRONT RADIATOR AIR GUIDE - CENTER                                 | 1   | \$ 42.00                | +       |  |
| 56                    | FRONT WHEEL HOUSING LINER - LH / RH <i>2nd cut</i>                | 2   | \$ 528.00               | ✓       |  |
| 57                    | FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>              | 1   | \$ 38.00                | +       |  |
| 58                    | FRONT WHEEL SPOILER - LH / RH <i>new</i>                          | 2   | \$ 320.00               | +       |  |
| 59                    | FRONT WHEEL COVER - LH / RH <i>Distorted</i>                      | 2   | \$ 1,264.00             | ✓       |  |
| 60                    | SIDE PANEL FRAME - RH <i>Distorted</i>                            | 1   | \$ 6,944.00             | ✓       |  |
| SUB TOTAL SPARE PARTS |                                                                   | :   | \$ 26,379.00            |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S**

|                       |                                                          |     | DAMAGED PARTS & PRICES |         |
|-----------------------|----------------------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                                        | QTY | S/NETT                 | REMARKS |
| 61                    | FRONT WINDSCREEM                                         | 1   | \$ 1,561.00            | ✓       |
| 62                    | FRONT WINDSHIELD RAIN SENSOR                             | 1   | \$ 137.00              | ✓       |
| 63                    | FRONT WINDSHIELD RAIN SENSOR SPRING                      | 1   | \$ 21.00               | ✓       |
| 64                    | FRONT WIPER - RH <i>New</i>                              | 1   | \$ 67.00               | X       |
| 65                    | PILLAR A REINFORCEMENT - RH OUTER ?                      | 1   | \$ 1,374.00            | ?       |
| 66                    | <del>FRONT</del> SIDE WINDOW - RH <i>Rest</i> <i>New</i> | 1   | \$ 832.00              | ✓       |
| 67                    | FUEL FLAP <i>Bent</i>                                    | 1   | \$ 323.00              | ✓       |
| 68                    | FUEL FILLING HOUSING <i>New</i>                          | 1   | \$ 155.00              | X       |
| 69                    | FRONT DOOR - RH <i>Distorted</i>                         | 1   | \$ 4,085.00            | ✓       |
| 70                    | FRONT DOOR - OUTER SEAL RH <i>New</i>                    | 1   | \$ 205.00              | ✓       |
| 71                    | BONDING AGENT ?                                          | 1   | \$ 49.00               | ?       |
| 72                    | CLEANING SOLUTION ?                                      | 1   | \$ 68.00               | ?       |
| 73                    | APPLICATOR ?                                             | 1   | \$ 8.00                | ?       |
| 74                    | GROMMET ?                                                | 5   | \$ 14.00               | ?       |
| 75                    | FRONT DOOR ATTACHMENT PARTS <i>New</i>                   | 1   | \$ 264.00              | X       |
| 76                    | FRONT DOOR CATCH - RH                                    | 1   | \$ 146.00              | ?       |
| 77                    | FRONT DOOR HINGE - RH UPPER / LOWER <i>Dmg</i>           | 4   | \$ 184.00              | ✓       |
| 78                    | FRONT DOOR SEAL - INNER RH <i>New</i>                    | 1   | \$ 205.00              | ✓       |
| 79                    | FRONT DOOR COVER - RH <i>lt</i>                          | 1   | \$ 790.00              | ✓       |
| 80                    | FRONT SILL TRIM STRIP - RH <i>New</i>                    | 1   | \$ 591.00              | ✓       |
| SUB TOTAL SPARE PARTS |                                                          | :   | \$ 11,079.00           |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S**

|                              |                                                            |     | DAMAGED PARTS & PRICES |         |
|------------------------------|------------------------------------------------------------|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                          | QTY | S/NETT                 | REMARKS |
| 81                           | DATA TAG <i>neu</i>                                        | 1 S | 462.00                 | ✓       |
| 82                           | TYER PRESSURE DATA TAG <i>neu</i>                          | 1 S | 38.00                  | X       |
| 83                           | FRONT DOOR HANDLE TRIM - RH <i>Distorted</i>               | 1 S | 128.00                 | ✓       |
| 84                           | LOCK CYLINDER WITH HOUSING <i>Distorted</i>                | 1 S | 540.00                 | ✓       |
| 85                           | FRONT DOOR HANDLE COVER TRANSPARENT - RH <i>Distorted</i>  | 1 S | 6.00                   | ✓       |
| 86                           | FRONT DOOR HANDLE SENSOR - RH <i>Distorted</i>             | 1 S | 228.00                 | ✓       |
| 87                           | FRONT DOOR HANDLE EXTERIOR - RH <i>Distorted</i>           | 1 S | 44.00                  | ✓       |
| 88                           | DOOR UNDERLAY - FRONT / REAR <i>neu</i>                    | 2 S | 8.00                   | ✓       |
| 89                           | FRONT DOOR MOUNTING BAR <i>?</i>                           | 1 S | 164.00                 | ✓       |
| 90                           | FRONT DOOR PERIPHERAL LIGHT - LH <i>Distorted</i>          | 1 S | 72.00                  | ✓       |
| 91                           | FRONT WINDOW WITHOUT REGULATOR MOTOR - RH <i>Distorted</i> | 1 S | 278.00                 | +       |
| 92                           | FRONT WINDOW WITH REGULATOR MOTOR - RH <i>neu</i>          | 1 S | 237.00                 | +       |
| 93                           | FRONT DOOR CONTROL UNIT - RH <i>neu</i>                    | 1 S | 751.00                 | +       |
| 94                           | FRONT DOOR LOCK - RH <i>neu</i>                            | 1 S | 535.00                 | +       |
| 95                           | FRONT DOOR STRIKER <i>neu</i>                              | 1 S | 69.00                  | +       |
| 96                           | WING MIRROR - RH <i>Distorted</i>                          | 1 S | 1,749.00               | ✓       |
| 97                           | WING MIRROR CAP - RH <i>Distorted</i>                      | 1 S | 491.00                 | ✓       |
| 98                           | WING MIRROR GLASS - RH <i>Distorted</i>                    | 1 S | 1,908.00               | ✓       |
| 99                           | CONTACT HOUSING 16 PIN <i>neu</i>                          | 1 S | 6.00                   | ✓       |
| 100                          | FRONT DOOR CONER TRIM - RH <i>neu</i>                      | 1 S | 46.00                  | X       |
| <b>SUB TOTAL SPARE PARTS</b> |                                                            | :   | <b>\$ 7,760.00</b>     |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NGRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

|                       |                                                        |     |        | DAMAGED PARTS & PRICES |   |
|-----------------------|--------------------------------------------------------|-----|--------|------------------------|---|
| S/N                   | PARTS DESCRIPTION                                      | QTY | S/NETT | REMARKS                |   |
| 101                   | FRONT WINDOW TRIM STRIP - RH <i>Dented</i>             | 1   | S      | 340.00                 | ✓ |
| 102                   | FRONT WINDOW GUIDE - RH <i>cut</i>                     | 1   | S      | 488.00                 | ✓ |
| 103                   | FRONT WINDOW INNER SEAL - RH <i>new</i>                | 1   | S      | 113.00                 | + |
| 104                   | FRONT DOOR SEAL - RH <i>new</i>                        | 1   | S      | 15.00                  | ✓ |
| 105                   | FRONT B PILLAR TRIM - RH <i>cut</i>                    | 1   | S      | 197.00                 | ✓ |
| 106                   | FRONT WINDOW SLOT SEAL - RH <i>Dented</i>              | 1   | S      | 616.00                 | ✓ |
| 107                   | FRONT DOOR WINDOW - RH <i>Shattered</i>                | 1   | S      | 298.00                 | ✓ |
| 108                   | FRONT DOOR TRIM - RH <i>cut</i>                        | 1   | S      | 2,310.00               | ✓ |
| 109                   | FRONT DOOR WINDOW TRIM - RH <i>new cut</i>             | 1   | S      | 144.00                 | ✓ |
| 110                   | FRONT DOOR ARMREST - RH <i>new</i>                     | 1   | S      | 591.00                 | + |
| 111                   | FRONT DOOR HANDLE COVER - RH <i>new</i>                | 1   | S      | 158.00                 | + |
| 112                   | FRONT DOOR TRIM INSERT ALUMINIUM - RH OUTER <i>new</i> | 1   | S      | 629.00                 | + |
| 113                   | FRONT DOOR WIRING SET <i>new</i>                       | 1   | S      | 577.00                 | + |
| 114                   | REAR DOOR - RH <i>Dented</i>                           | 1   | S      | 4,085.00               | ✓ |
| 115                   | REAR DOOR - OUTER SEAL RH <i>new</i>                   | 1   | S      | 205.00                 | ✓ |
| 116                   | BONDING AGENT ?                                        | 1   | S      | 49.00                  | ? |
| 117                   | CLEANING SOLUTION ?                                    | 1   | S      | 68.00                  | ? |
| 118                   | APPLICATOR ?                                           | 1   | S      | 8.00                   | ? |
| 119                   | REAR DOOR SEALING STRIP - RH <i>new</i>                | 1   | S      | 17.00                  | ✓ |
| 120                   | GROMMET <i>new</i>                                     | 3   | S      | 9.00                   | ✓ |
| SUB TOTAL SPARE PARTS |                                                        | :   | S      | 10,917.00              |   |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UPI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S**

|                       |                                                     |     |        | DAMAGED PARTS & PRICES |          |
|-----------------------|-----------------------------------------------------|-----|--------|------------------------|----------|
| S/N                   | PARTS DESCRIPTION                                   | QTY | S/NETT | REMARKS                |          |
| 121                   | RAER DOOR ATTACHMENT PART <i>new</i>                | 1   | S      | 222.00                 | X        |
| 122                   | REAR DOOR CATCH ?                                   | 1   | S      | 146.00                 | ?        |
| 123                   | REAR DOOR SEAL - INNER <i>new</i>                   | 1   | S      | 205.00                 | X        |
| 124                   | SILL PANEL SEAL - RH <i>new</i>                     | 1   | S      | 253.00                 | X        |
| 125                   | REAR DOOR HINGE - RH UPPER / LOWER <i>Dist</i>      | 4   | S      | 184.00                 | ✓        |
| 126                   | REAR DOOR COVER - RH <i>cut</i>                     | 1   | S      | 689.00                 | ✓        |
| 127                   | REAR DOOR HANDLE TRIM PLATE - RH <i>Dist</i>        | 1   | S      | 275.00                 | ✓        |
| 128                   | REAR DOOR HANDLE HOUSING - RH <i>new</i>            | 1   | S      | 18.00                  | +        |
| 129                   | REAR DOOR HANDLE COVER TRANSPARENT - RH <i>new</i>  | 1   | S      | 6.00                   | +        |
| 130                   | REAR DOOR HANDLE SENSOR - RH <i>new</i>             | 1   | S      | 228.00                 | +        |
| 131                   | REAR DOOR HANDLE EXTERIOR - RH <i>new</i>           | 1   | S      | 44.00                  | +        |
| 132                   | REAR DOOR MOUNTING BAR - RH <i>new</i>              | 1   | S      | 164.00                 | +        |
| 133                   | REAR WINDOW WITHOUT REGULATOR MOTOR - RH <i>new</i> | 1   | S      | 314.00                 | +        |
| 134                   | REAR WINDOW WITH REGULATOR MOTOR - RH <i>new</i>    | 1   | S      | 351.00                 | +        |
| 135                   | REAR DOOR CONTROL UNIT - RH                         | 1   | S      | 751.00                 | +        |
| 136                   | REAR DOOR LOCK - RH                                 | 1   | S      | 661.00                 | +        |
| 137                   | REAR DOOR STRIKER                                   | 1   | S      | 69.00                  | +        |
| 138                   | REAR WINDOW GUIDE - RH <i>new</i>                   | 1   | S      | 488.00                 | X        |
| 139                   | REAR WINDOW TRIM STRIP - RH <i>new</i>              | 1   | S      | 297.00                 | ✓        |
| 140                   | REAR WINDOW INNER SEAL - RH <i>new</i>              | 1   | S      | 205.00                 | +        |
| SUB TOTAL SPARE PARTS |                                                     |     | :      | \$                     | 5,570.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

|                       |                                          |     | DAMAGED PARTS & PRICES |         |
|-----------------------|------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                        | QTY | S/NETT                 | REMARKS |
| 141                   | REAR WINDOW SLOT SEAL - RH <i>seen</i>   | 1   | S 616.00               | +       |
| 142                   | REAR DOOR SEAL - RH <i>seen</i>          | 2   | S 30.00                | X       |
| 143                   | REAR B PLIAR TRIM - RH <i>lit</i>        | 1   | S 222.00               | ✓       |
| 144                   | REAR C PLIAR TRIM - RH <i>seen</i>       | 1   | S 149.00               | +       |
| 145                   | REAR WINDOW GUIDE RAIL - RH <i>seen</i>  | 1   | S 72.00                | +       |
| 146                   | REAR DOOR WINDOW - RH <i>seen</i>        | 1   | S 298.00               | +       |
| 147                   | REAR DOOR - LH <i>Sealed</i>             | 1   | S 4,085.00             | ✓       |
| 148                   | REAR DOOR OUTER SEAL - LH <i>MV</i>      | 1   | S 205.00               | ✓       |
| 149                   | BONDING AGENT <i>?</i>                   | 1   | S 49.00                | ?       |
| 150                   | CLEANING SOLUTION <i>?</i>               | 1   | S 68.00                | ?       |
| 151                   | APPLICATOR <i>?</i>                      | 1   | S 8.00                 | ?       |
| 152                   | REAR DOOR SEALING STRIP - LH <i>seen</i> | 1   | S 17.00                | +       |
| 153                   | GROMMET <i>in</i>                        | 3   | S 9.00                 | ✓       |
| 154                   | REAR DOOR ATTACHMENT PART <i>seen</i>    | 1   | S 222.00               | +       |
| 155                   | REAR DOOR CATCH - LH <i>?</i>            | 1   | S 146.00               | ?       |
| 156                   | REAR DOOR COVER - LH <i>glad</i>         | 1   | S 689.00               | ✓       |
| 157                   | REAR BUMPER - UPPER <i>Del</i>           | 1   | S 2,397.00             | ✓       |
| 158                   | REAR BUMPER - LOWER <i>seen</i>          | 1   | S 1,182.00             | +       |
| 159                   | TAIL LIGHT - UPPER RH <i>?</i>           | 1   | S 5,746.00             | +       |
| 160                   | TAIL LIGHT - LOWER RH <i>seen</i>        | 1   | S 699.00               | +       |
| SUB TOTAL SPARE PARTS |                                          | :   | \$ 16,909.00           |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

|                       |                                            |     | DAMAGED PARTS & PRICES |         |  |
|-----------------------|--------------------------------------------|-----|------------------------|---------|--|
| S/N                   | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS |  |
| 161                   | REAR WHEEL ARCH COVER - LH / RH <i>new</i> | 2   | \$ 1,166.00            | ✓       |  |
| 162                   | ROOF TOP PANEL <i>new</i>                  | 1   | \$ 4,646.00            | ✓       |  |
| 163                   | INNER ROOF RAIL <i>new</i>                 | 1   | \$ 1,836.00            | x       |  |
| 164                   | INNER ROOF RAIL NUT <i>new</i>             | 6   | \$ 213.00              | f       |  |
| 165                   | HEAD AIRBAG UNIT - LH / RH                 | 1   | \$ 3,726.00            | ✓       |  |
| 166                   | AIRBAG CONTROL UNIT                        | 1   | \$ 2,112.00            | ✓       |  |
| 167                   | AIRBAG CRASH SENSOR                        | 1   | TBC                    |         |  |
| 168                   | CENTRAL PROTECTION FUSE <i>new</i>         | 1   | \$ 533.00              | ✓       |  |
| 169                   | FRONT SEATBELT - LH / RH <i>Activated</i>  | 2   | \$ 2,234.00            | ✓       |  |
| 170                   | FRONT SEATBELT ADJUSTER - LH / RH ?        | 2   | \$ 342.00              | ?       |  |
| 171                   | ROOF HEADLINER <i>Cracked</i>              | 1   | \$ 3,660.00            | ✓       |  |
| 172                   | FRONT ROOF HANDLE - RH / LH ?              | 2   | \$ 283.00              | ?       |  |
| 173                   | REAR ROOF HANDLE - RH / LH ?               | 2   | \$ 284.00              | ?       |  |
| 174                   | A - PILLAR TRIM - UPPER LH / RH ?          | 2   | \$ 474.00              | ?       |  |
| 175                   | UPPER B-PILLAR TRIM - LH / RH <i>new</i>   | 2   | \$ 602.00              | +       |  |
| 176                   | C - PILLAR TRIM - LH / RH <i>new</i>       | 2   | \$ 628.00              | +       |  |
| 177                   | D - PILLAR TRIM - LH / RH <i>new</i>       | 2   | \$ 408.00              | +       |  |
| 178                   | A - PILLAR TRIM - LOWER RH <i>new</i>      | 1   | \$ 149.00              | +       |  |
| 179                   | B - PILLAR TRIM - LOWER RH <i>new</i>      | 1   | \$ 234.00              | +       |  |
| 180                   | REAR WHEEL HOUSING TRIM - RH <i>new</i>    | 1   | \$ 252.00              | +       |  |
| SUB TOTAL SPARE PARTS |                                            | :   | \$ 23,782.00           |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

|                       |                                                   |     | DAMAGED PARTS & PRICES |          |
|-----------------------|---------------------------------------------------|-----|------------------------|----------|
| S/N                   | PARTS DESCRIPTION                                 | QTY | S/NETT                 | REMARKS  |
| 181                   | REAR FENDER INNER TRIM - RH <i>me n</i>           | 1 S | 75.00                  | <i>+</i> |
| 182                   | DASHBOARD                                         | 1 S | 6,972.00               | <i>+</i> |
| 183                   | DASHBOARD CENTER AIR VENT                         | 1 S | 2,272.00               | <i>+</i> |
| 184                   | DASHBOARD AIR VENT                                | 1 S | 591.00                 | <i>+</i> |
| 185                   | STEERING WHEEL <i>cut</i>                         | 1 S | 2,374.00               | <i>2</i> |
| 186                   | FRONT SEAT - RH <i>ut</i>                         | 1   | TBC                    | <i>✓</i> |
| 187                   | FRONT SEAT PADDING - RH <i>me</i>                 | 1   | TBC                    | <i>+</i> |
| 188                   | FRONT SEAT COVER - RH <i>cut</i>                  | 1   | TBC                    | <i>✓</i> |
| 189                   | FRONT CENTER CONSOLE                              | 1 S | 815.00                 | <i>+</i> |
| 190                   | FRONT CENTER CONSOLE INSERT <i>me n</i>           | 1 S | 402.00                 | <i>+</i> |
| 191                   | FRONT CENTER CONSOLE TRIM <i>cut</i>              | 1 S | 741.00                 | <i>✓</i> |
| 192                   | FRONT CENTER CONSOLE INSERT STOWAGE <i>me</i>     | 1 S | 60.00                  | <i>+</i> |
| 193                   | FRONT CENTER CONSOLE STOWAGE COMPARTMENT          | 1 S | 144.00                 | <i>+</i> |
| 194                   | ASSEMBLY CARRIER                                  | 1 S | 1,891.00               | <i>?</i> |
| 195                   | FRONT WISHBONE LINK - LH                          | 1 S | 539.00                 | <i>?</i> |
| 196                   | FRONT SUSPENSION GUIDE - LH                       | 1 S | 943.00                 | <i>?</i> |
| 197                   | UPPER SUSPENSION GUIDE - FRONT / REAR LH <i>2</i> | 2 S | 720.00                 | <i>?</i> |
| 198                   | WHEEL BEARING HOUSING - LH                        | 1 S | 1,136.00               | <i>?</i> |
| 199                   | SWIVEL JOINT                                      | 1 S | 193.00                 | <i>?</i> |
| 200                   | WHEEL HUB                                         | 1 S | 479.00                 | <i>?</i> |
| SUB TOTAL SPARE PARTS |                                                   | :   | \$ 20,347.00           |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

|                       |                                                          |      | DAMAGED PARTS & PRICES |           |  |
|-----------------------|----------------------------------------------------------|------|------------------------|-----------|--|
| S/N                   | PARTS DESCRIPTION                                        | QTY  | S/NETT                 | REMARKS   |  |
| 201                   | FRONT WHEEL BEARING ?                                    | 1 S  | 246.00                 | ?         |  |
| 202                   | SUSPENSION FORKS - LH ?                                  | 1 S  | 366.00                 | ?         |  |
| 203                   | COUPLING ROD ?                                           | 1 S  | 127.00                 | ?         |  |
| 204                   | FRONT ANTI - ROLL BAR ?                                  | 1 S  | 433.00                 | ?         |  |
| 205                   | AXLE ASSEMBLY ?                                          | 1 S  | 2,865.00               | ?         |  |
| 206                   | SHOCK ABSORBER ?                                         | 1 S  | 1,483.00               | ?         |  |
| 207                   | LEVEL SENSOR WITH POLES ?                                | 1 S  | 535.00                 | ?         |  |
| 208                   | STERRING GEAR WITH TRACK ROD JOINT <del>Not used</del> ? | 1 S  | 6,782.00               | ?         |  |
| 209                   | TRACK ROD ?                                              | 1 S  | 134.00                 | ?         |  |
| 210                   | TIE ROD END - LH ?                                       | 1 S  | 197.00                 | ?         |  |
| 211                   | ROOF HEADER PANEL <del>Not used</del> ?                  | 1 S  | 262.00                 | ?         |  |
| 212                   | INNER ROOF REINFORCEMENT <del>Not used</del> ?           | 1 S  | 247.00                 | ?         |  |
| 213                   | 1 PACK ADHESIVE ?                                        | 1 S  | 73.00                  | ?         |  |
| 214                   | ROOF PANEL BONDING ADHESIVE ?                            | 1 S  | 23.00                  | ?         |  |
| 215                   | PRIMER ?                                                 | 1 S  | 20.00                  | ?         |  |
| 216                   | FRONT DOOR COVER - LH <del>Not used</del>                | 1 S  | 790.00                 | ✓         |  |
| 217                   | STATIC MIXER <del>Not used</del>                         | 5 S  | 56.00                  | ✓         |  |
| 218                   | BLINDER RIVET STUD <del>Not used</del>                   | 10 S | 62.00                  | ✓         |  |
| 219                   | FRONT NO PLATE <del>Not used</del>                       | S/N  | TBC                    | +         |  |
| 220                   | FRONT 2 RIMS - LH / RH <del>Not used</del>               | 3    | TBC                    | ✓         |  |
| SUB TOTAL SPARE PARTS |                                                          | :    | \$                     | 14,701.00 |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S**

|                      |                                      |     | DAMAGED PARTS & PRICES |         |
|----------------------|--------------------------------------|-----|------------------------|---------|
| S/N                  | PARTS DESCRIPTION                    | QTY | S/NETT                 | REMARKS |
| 221                  | REAR RIM - LH <i>lt</i>              | 1   | TBC ✓                  |         |
| 222                  | FRONT 2 TYRES- LH / RH <i>LH tom</i> | 2   | TBC ?                  |         |
| 223                  | REAR TYRE - LH <i>new</i>            | 1   | TBC ✓                  |         |
| 224                  | ACRYLIC SEALANT <i>?</i>             | S/N | \$ 180.00 ✓            |         |
| 225                  | CAVITY WAX <i>new</i>                | S/N | \$ 140.00 ✓            |         |
| 226                  | STONE CHIP TREATMENT                 | S/N | \$ 180.00 ✓            |         |
| 227                  | METAL FILLER POWDER <i>new</i>       | S/N | \$ 280.00 ✓            |         |
| 227                  | REAR WINDSCREEN SEALANT <i>new</i>   | S/N | \$ 200.00 ✓            |         |
| 228                  | REAR 1/4 GLASS SEALANT <i>new</i>    | S/N | \$ 100.00 ✓            |         |
| 229                  | SUNDRIES <i>?</i>                    |     | \$ 1,500.00 ?          |         |
| TOTAL SPARE PARTS    |                                      | :   | \$ 159,349.00          |         |
| TOTAL LABOUR CHARGES |                                      | :   | \$ 65,664.00           |         |
| GRAND TOTAL          |                                      | :   | \$ 225,013.00          |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.