

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0780/2021/ZK
DATE : 22-Sep-21
WIP : 45399

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

We took 80 days, 12 Sundays & 2 PH

Johnny Boo 15 Jun 22

OWNER'S NAME : MR CHOY KAI GHIT BENJAMIN
ADDRESS : 359 CHOA CHU KANG AVE 3
#13-19
SINGAPORE 689883
TELEPHONE : HP +65 82236101
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210035130
VEHICLE NO : **SGN 1691 S**
MODEL CODE : Q5 S Line 2.0 TFSI
MODEL YEAR : 26/4/2021
ENGINE NO : DGK 002793
CHASSIS NO : WAUZZZFY0M2048930
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Sep-21
PLACE OF ACCIDENT : NEAR 6 INTERNATIONAL BUSINESS PARK ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	S/N \$	800.00	\$ 800.00
2	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	S/N \$	2,400.00	\$ 2,400.00
3	TO REMOVE CHECK TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SNSOR, HEADLIGHT WASHER ASSY AND FRONT FRONT PARKING AID	S/N \$	480.00	\$ 480.00
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$ 250.00
5	TO RENEW AND REINSTALL AIRCON CONDENSER ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$	1,700.00	ref supp 2 Lab 3
SUB TOTAL LABOUR CHARGES (FORNTAL)		:	\$ 6,180.00	\$ 3,930.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i> Q		\$ 3,930.00
6	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	S/N \$	280.00	\$ 280.00
7	TO RENEW FRONT WINDSCREEN TO FACILITATE RENEWAL OF RHS A-PILLAR.	S/N	TBC	\$ 480.00
8	TO INSTALL SOLAR FILM FOR FRONTWINDSCREEN AND ALL THE AFFECTED DOOR WINDOW GLASS	S/N \$	400.00	\$ 400.00
9	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	S/N \$	200.00	\$ 150.00
10	TO REMOVE AND REPLACE FRONT WINDSCREEN SENSOR FOIL AND RESER SYSTEM	S/N \$	300.00	\$ 300.00
SUB TOTAL LABOUR CHARGES (FORNTAL)		:	\$ 1,180.00	\$ 5,540.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 5,540.00
11	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION WITH SUBFRAME	S/N \$	2,400.00	\$ 2,400.00
12	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE	S/N \$	400.00	\$ 280.00
13	TO REMOVE CENTER CONSOLE , INSTRUMENTS PANELS AND CLUSTERS.RENEW DASHBOARD SLIP RING.TRANSFER OLD FITTINGS.RENEW SEAT BELTS AND CONTROL UNIT , PILLAR TRIMS , ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$	3,200.00	\$ 3,200.00
14	TO REMOVE AND REINSTALL FRONT SEAT ASSY , BACK REST , CARPETS , ELECTRONIC COMPONENTS AND FUSE TRAYS. RENEW WHERE NECESSARY.	S/N \$	1,800.00	\$ 1,800.00
15	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,BOTH FRONT FENDER , RHS FRONT DOOR AND HEADLIGHT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.TO CUT OUT AND WELD ROOFTOP PANEL . RHS A PILLAR,RHS UPPER A- PILLAR REINFORCEMENT , RHS SILL PANEL AND RHS B PILLAR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED (add 6 days - replace RHS A & B pillar) \$3000.00 (add 3 days for lock carrier) \$1500.00	\$	16,800.00	\$ 8,500.00
SUB TOTAL LABOUR CHARGES (FORNTAL)		:	\$ 24,600.00	\$ 21,720.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 21,720.00
16	TO RESPRAY FRONT BUMPER , BOTH FRONT LOWER SPOILERS,BOTH FRONT FENDER,BONNET , HINGES ,BOTH FRONT DOORS , DOOR COVER , DOOR HANDLE , RHS WING MIRROR COVER , RHS A - PILLAR , RHS SILL PANEL , RHS B-PILLAR , ROOFTOP PANEL , BOTH ROOF CHANNELS , DOOR ENTRANCES AND BOTH FRONT	\$	12,400.00	\$ 7,200.00
17	TO CARRY OUT CLEANUP FOR WINDOW GLASSES IN THE INTERIOR.	S/N \$	280.00	\$ 280.00
18	TO RENEW LHS FRONT RIM,RHS FRONT RIM AND RHS REAR RIM.TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	600.00	\$ 600.00
19	TO REMOVE AND REINSTALL BOTH ROOFTOP RAIL. RENEW WHERE NECESSARY (RHS)	S/N \$	280.00	\$ 140.00
TOTAL LABOUR CHARGES (FRONTAL)		:	\$ 45,520.00	\$ 29,940.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 29,940.00
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	\$ 360.00
2	TO RENEW RHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL	S/N \$	300.00	\$ 300.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT , BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$	1,600.00	\$ 1,600.00
4	TO REMOVE AND REINSTALL REAR SEAT , BACK REST,HAT TRAY AND LUGGAGE COMPARTMENT TRIMS .	S/N \$	1,200.00	\$ 1,200.00
5	TO REMOVE AND TRANSFER RHS REAR DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$ 560.00
SUB LABOUR CHARGES (REAR)		:	\$ 4,260.00	\$ 33,960.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 1691 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 33,960.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND BOTH REAR DOORS. TO CUT OUT AND WELD RHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	7,200.00	\$ 4,000.00
7	TO RESPRAY REAR UPPER BUMPER,REAR LOWER BUMPER,RHS REAR FENDER,DRAIN CHANEL,DOOR ENTRANCE , REAR END PANELLING , RHS REAR DOOR,LHS RER DOOR , DOOR COVERS , DOOR HANDLE ,FUEL FILLER CAP AND BOTH REAR WHEEL ARCH TRIMS	\$	8,300.00	\$ 4,575.00
7a	<i>Added labour - supp 2 (16 Nov 21)</i>	\$	3,200.00	\$ 2,800.00
7b	<i>Added labour - supp 3 (19 Nov 21)</i>	\$	2,800.00	\$ 2,800.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES (FRONTAL+REAR)			\$ 71,664.00	\$ 48,519.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,362.00	\$	1,089.60
2	FRONT BUMPER FIXING PARTS	1	TBC		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 76.00	\$	31.28
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 222.00		
5	FRONT BUMPER GRILLE - CENTER	1	\$ 402.00		
6	FRONT BUMPER PARKING AID SENSOR SUPPORT	2	\$ 58.00		
7	FRONT BUMPER SPOILER - CENTER	1	\$ 866.00		
8	FRONT BUMPER SPOILER - LH / RH	2	\$ 452.00	\$	180.80
9	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 421.00		
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 534.00	\$	213.60
11	FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 68.00	\$	28.32
12	FRONT BUMPER TRIM - LH / RH	2	\$ 322.00	\$	135.20
13	FRONT RADIATOR GRILLE	1	\$ 3,470.00		
14	QUATTRO EMBLEM	1	\$ 106.00		
15	FRONT BUMPER STRIKER PLATE	1	\$ 244.00		
16	FRONT PARKING AID SENSOR	4	TBC		
17	FRONT PARKING AID SENSOR SEAL	4	\$ 14.00		
18	FRONT BUMPER REINFORCMENT FOAM PIECE	1	\$ 183.00	\$	146.00
19	FRONT BUMPER REINFORCMENT BAR	1	\$ 981.00		
20	FRONT BUMPER BRACKET - LH	1	\$ 256.00		
SUB TOTAL SPARE PARTS		:	\$ 10,037.00	\$	1,824.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 1,824.80
21	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	\$ 60.96
22	FRONT BUMPER TOP COVER	1	\$ 129.00	
23	CAUTION STICKER	1	\$ 14.00	
24	AIR CONDITIONER STICKER	1	\$ 20.00	
25	HORN - LH	1	\$ 195.00	
26	HORN - RH	1	\$ 195.00	
27	BONNET	1	\$ 4,058.00	\$ 3,246.40
28	BONNET HINGE - LH / RH	2	\$ 322.00	
29	BONNET ATTACHMENT PARTS	1	\$ 141.00	
30	BONNET IMPACT PROTECTOR - CENTER / LH / RH	3	\$ 84.00	\$ 65.68
31	FRONT FENDER - LH / RH	2	\$ 2,854.00	\$ 2,283.20
32	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
33	FRONT FENDER BRACKET - LH / RH	2	\$ 36.00	\$ 27.52
34	FRONT FENDER BRACE - LH / RH	2	\$ 450.00	\$ 359.20
35	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 105.00	\$ 83.60
36	FRONT FENDER MOUTING BRACKET - RH	1	\$ 18.00	\$ 13.76
37	FRONT FENDER FILLER COVER - LH / RH	2	\$ 62.00	\$ 49.28
38	FRONT FENDER FILLER TOP COVER - LH / RH	2	\$ 80.00	\$ 62.88
39	FRONT FENDER FILLER COVER -OUTER LH / RH	2	\$ 156.00	\$ 124.64
40	S-LINE EMBLEM	2	\$ 225.00	\$ 204.00
SUB TOTAL SPARE PARTS			\$ 9,288.00	\$ 8,405.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 8,405.92</i>
41	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	
42	FRONT RADIATOR BRACE - LH / RH	2	\$ 114.00	
43	HEADLIGHT - LH / RH	2	\$ 13,978.00	<i>\$ 5,608.80</i>
44	HEADLIGHT CYLINDER - LH / RH	2	\$ 280.00	
45	WINDSHIELD WASHER HOSE	1	\$ 125.00	
46	HEADLIGHT WASGER HOSE	1	\$ 68.00	
47	HEADLIGHT WASHER PUMP	1	\$ 155.00	
48	WASHER RESERVOIR	1	\$ 235.00	<i>\$ 188.00</i>
49	WINDSHIELD WASHER PUMP	1	\$ 125.00	
50	FRONT RADIATOR	1	\$ 1,400.00	<i>\$ 1,120.00</i>
51	FRONT RADIATTOR SUPPORT - LH	1	\$ 53.00	
52	FRONT BUMPER SENSOR BRACKET	1	\$ 16.00	
53	COOLANT	6	\$ 266.00	<i>\$ 212.64</i>
54	FRONT RADIATOR AIR GUIDE - LH / RH / UPPER /LOWER	4	\$ 192.00	
55	FRONT RADIATOR AIR GUIDE - CENTER	1	\$ 42.00	
56	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 528.00	<i>\$ 421.60</i>
57	FRONT WHEEL HOUSING LINER ATTACHMENT PART	1	\$ 38.00	
58	FRONT WHEEL SPOILER - LH / RH	2	\$ 320.00	<i>\$ 128.00</i>
59	FRONT WHEEL COVER - LH / RH	2	\$ 1,264.00	<i>\$ 1,011.20</i>
60	SIDE PANEL FRAME - RH	1	\$ 6,944.00	<i>\$ 5,555.20</i>
SUB TOTAL SPARE PARTS		:	\$ 26,379.00	\$ 22,651.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 22,651.36
61	FRONT WINDSCREEN	1 \$	1,561.00	\$ 1,248.80
62	FRONT WINDSHIELD RAIN SENSOR	1 \$	137.00	\$ 109.20
63	FRONT WINDSHIELD RAIN SENSOR SPRING	1 \$	21.00	\$ 16.56
64	FRONT WIPER - RH	1 \$	67.00	
65	PILLAR A REINFORCEMENT - RH OUTER	1 \$	1,374.00	\$ 1,099.20
66	FROTN SIDE WINDOW - RH	1 \$	832.00	\$ 665.20
67	FUEL FLAP	1 \$	323.00	\$ 258.40
68	FUEL FILLING HOUSING	1 \$	155.00	\$ 123.60
69	FRONT DOOR - RH	1 \$	4,085.00	\$ 3,268.00
70	FRONT DOOR - OUTER SEAL RH	1 \$	205.00	\$ 164.00
71	BONDING AGENT	1 \$	49.00	
72	CLEANING SOLUTION	1 \$	68.00	
73	APPLICATOR	1 \$	8.00	
74	GROMMET	5 \$	14.00	
75	FRONT DOOR ATTACHMENT PARTS	1 \$	264.00	
76	FRONT DOOR CATCH - RH	1 \$	146.00	
77	FRONT DOOR HINGE - RH UPPER / LOWER	4 \$	184.00	\$ 145.60
78	FRONT DOOR SEAL - INNER RH	1 \$	205.00	
79	FRONT DOOR COVER - RH	1 \$	790.00	\$ 632.00
80	FRONT SILL TRIM STRIP - RH	1 \$	591.00	\$ 472.80
SUB TOTAL SPARE PARTS			\$ 11,079.00	\$ 30,854.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	30,854.72
81	DATA TAG	1	\$ 462.00	\$	369.60
82	TYER PRESSURE DATA TAG	1	\$ 38.00	\$	29.84
83	FRONT DOOR HANDLE TRIM - RH	1	\$ 128.00	\$	102.40
84	LOCK CYLINDER WITH HOUSING	1	\$ 540.00	\$	432.00
85	FRONT DOOR HANDLE COVER TRANSPARENT - RH	1	\$ 6.00	\$	4.64
86	FRONT DOOR HANDLE SENSOR - RH	1	\$ 228.00	\$	182.40
87	FRONT DOOR HANDLE EXTERIOR - RH	1	\$ 44.00	\$	34.88
88	DOOR UNDERLAY - FRONT / REAR	2	\$ 8.00	\$	5.76
89	FRONT DOOR MOUNTING BAR	1	\$ 164.00	\$	130.80
90	FRONT DOOR PERIPHERAL LIGHT - LH	1	\$ 72.00	\$	57.28
91	FRONT WINDOW WITHOUT REGULATOR MOTOR - RH	1	\$ 278.00	\$	222.40
92	FRONT WINDOW WITH REGULATOR MOTOR - RH	1	\$ 237.00		
93	FRONT DOOR CONTROL UNIT - RH	1	\$ 751.00		
94	FRONT DOOR LOCK - RH	1	\$ 535.00	\$	428.00
95	FRONT DOOR STRIKER	1	\$ 69.00		
96	WING MIRROR - RH	1	\$ 1,749.00	\$	1,399.20
97	WING MIRROR CAP - RH	1	\$ 491.00	\$	392.80
98	WING MIRROR GLASS - RH	1	\$ 1,908.00	\$	1,526.40
99	CONTACT HOUSING 16 PIN	1	\$ 6.00	\$	4.72
100	FRONT DOOR CONER TRIM - RH	1	\$ 46.00	\$	36.24
SUB TOTAL SPARE PARTS			:	\$ 7,760.00	\$ 36,214.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	36,214.08
101	FRONT WINDOW TRIM STRIP - RH	1	\$ 340.00	\$	272.00
102	FRONT WINDOW GUIDE - RH	1	\$ 488.00	\$	390.00
103	FRONT WINDOW INNER SEAL - RH	1	\$ 113.00	\$	90.00
104	FRONT DOOR SEAL - RH	1	\$ 15.00	\$	11.36
105	FRONT B PILLAR TRIM - RH	1	\$ 197.00	\$	157.20
106	FRONT WINDOW SLOT SEAL - RH	1	\$ 616.00	\$	492.40
107	FRONT DOOR WINDOW - RH	1	\$ 298.00	\$	238.00
108	FRONT DOOR TRIM - RH	1	\$ 2,310.00	\$	1,848.00
109	FRONT DOOR WINDOW TRIM - RH	1	\$ 144.00	\$	114.80
110	FRONT DOOR ARMREST - RH	1	\$ 591.00		
111	FRONT DOOR HANDLE COVER - RH	1	\$ 158.00		
112	FRONT DOOR TRIM INSERT ALUMINIUM- RH OUTER	1	\$ 629.00	\$	503.20
113	FRONT DOOR WIRING SET	1	\$ 577.00		
114	REAR DOOR - RH	1	\$ 4,085.00	\$	3,268.00
115	REART DOOR - OUTER SEAL RH	1	\$ 205.00	\$	164.00
116	BONDING AGENT	1	\$ 49.00		
117	CLEANING SOLUTION	1	\$ 68.00		
118	APPLICATOR	1	\$ 8.00		
119	REAR DOOR SEALING STRIP - RH	1	\$ 17.00	\$	12.96
120	GROMMET	3	\$ 9.00	\$	6.72
SUB TOTAL SPARE PARTS		:	\$ 10,917.00	\$	43,782.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>43,782.72</i>
121	RAER DOOR ATTACHMENT PART	1	\$ 222.00		
122	REAR DOOR CATCH	1	\$ 146.00	<i>\$</i>	<i>116.40</i>
123	REAR DOOR SEAL - INNER	1	\$ 205.00		
124	SILL PANEL SEAL - RH	1	\$ 253.00	<i>\$</i>	<i>202.00</i>
125	REAR DOOR HINGE - RH UPPER / LOWER	4	\$ 184.00	<i>\$</i>	<i>145.60</i>
126	REAR DOOR COVER - RH	1	\$ 689.00	<i>\$</i>	<i>551.20</i>
127	REAR DOOR HANDLE TRIM PLATE - RH	1	\$ 275.00	<i>\$</i>	<i>219.60</i>
128	REAR DOOR HANDLE HOUSING - RH	1	\$ 18.00	<i>\$</i>	<i>14.16</i>
129	REAR DOOR HANDLE COVER TRANSPARENT - RH	1	\$ 6.00	<i>\$</i>	<i>4.64</i>
130	REAR DOOR HANDLE SENSOR - RH	1	\$ 228.00		
131	REAR DOOR HANDLE EXTERIOR - RH	1	\$ 44.00	<i>\$</i>	<i>34.88</i>
132	REAR DOOR MOUNTING BAR - RH	1	\$ 164.00		
133	REAR WINDOW WITHOUT REGULATOR MOTOR - RH	1	\$ 314.00		
134	REAR WINDOW WITH REGULATOR MOTOR - RH	1	\$ 351.00		
135	REAR DOOR CONTROL UNIT - RH	1	\$ 751.00		
136	REAR DOOR LOCK - RH	1	\$ 661.00		
137	REAR DOOR STRIKER	1	\$ 69.00		
138	REAR WINDOW GUIDE - RH	1	\$ 488.00		
139	REAR WINDOW TRIM STRIP - RH	1	\$ 297.00	<i>\$</i>	<i>236.00</i>
140	REAR WINDOW INNER SEAL - RH	1	\$ 205.00		
SUB TOTAL SPARE PARTS		:	\$ 5,570.00	<i>\$</i>	<i>45,307.20</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 45,307.20
141	REAR WINDOW SLOT SEAL - RH	1	\$ 616.00	\$ 516.00
142	REAR DOOR SEAL - RH	2	\$ 30.00	\$ 22.72
143	REAR B PLIAR TRIM - RH	1	\$ 222.00	\$ 177.60
144	REAR C PLIAR TRIM - RH	1	\$ 149.00	
145	REAR WINDOW GUIDE RAIL - RH	1	\$ 72.00	
146	REAR DOOR WINDOW - RH	1	\$ 298.00	
147	REAR DOOR - LH	1	\$ 4,085.00	\$ 3,268.00
148	REAR DOOR OUTER SEAL - LH	1	\$ 205.00	\$ 164.00
149	BONDING AGENT	1	\$ 49.00	
150	CLEANING SOLUTION	1	\$ 68.00	
151	APPLICATOR	1	\$ 8.00	
152	REAR DOOR SEALING STRIP - LH	1	\$ 17.00	\$ 12.96
153	GROMMET	3	\$ 9.00	\$ 6.72
154	RAER DOOR ATTACHMENT PART	1	\$ 222.00	
155	REAR DOOR CATCH - LH	1	\$ 146.00	\$ 116.40
156	REAR DOOR COVER - LH	1	\$ 689.00	\$ 551.20
157	REAR BUMPER - UPPER	1	\$ 2,397.00	\$ 1,917.60
158	REAR BUMPER - LOWER	1	\$ 1,182.00	
159	TAIL LIGHT - UPPER RH	1	\$ 5,746.00	
160	TAIL LIGHT - LOWER RH	1	\$ 699.00	
SUB TOTAL SPARE PARTS			\$ 16,909.00	\$ 52,060.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 52,060.40
161	REAR WHEEL ARCH COVER - LH / RH	2	\$ 1,166.00	\$ 932.80
162	ROOF TOP PANEL	1	\$ 4,646.00	
163	INNER ROOF RAIL	1	\$ 1,836.00	
164	INNER ROOF RAIL NUT	6	\$ 213.00	
165	HEAD AIRBAG UNIT - LH / RH	1	\$ 3,726.00	\$ 2,980.80
166	AIRBAG CONTROL UNIT	1	\$ 2,112.00	\$ 1,689.60
167	AIRBAG CRASH SENSOR	1	TBC	
168	CENTRAL PROTECTION FUSE	1	\$ 533.00	\$ 426.80
169	FRONT SEATBELT - LH / RH	2	\$ 2,234.00	\$ 1,787.20
170	FRONT SEATBELT ADJUSTER - LH / RH	2	\$ 342.00	\$ 273.60
171	ROOF HEADLINER	1	\$ 3,660.00	\$ 3,083.20
172	FRONT ROOF HANDLE - RH / LH	2	\$ 283.00	\$ 226.40
173	REAR ROOF HANDLE - RH / LH	2	\$ 284.00	\$ 226.40
174	A - PLIAR TRIM - UPPER LH / RH	2	\$ 474.00	\$ 379.20
175	UPPER B-PILLAR TRIM - LH / RH	2	\$ 602.00	
176	C - PILLAR TRIM - LH / RH	2	\$ 628.00	
177	D - PILLAR TRIM - LH / RH	2	\$ 408.00	
178	A - PLLAR TRIM - LOWER RH	1	\$ 149.00	
179	B - PILLAR TRIM - LOWER RH	1	\$ 234.00	
180	REAR WHEEL HOUSING TRIM - RH	1	\$ 252.00	
SUB TOTAL SPARE PARTS			\$ 23,782.00	\$ 64,066.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 64,066.40</i>
181	REAR FENDER INNER TRIM - RH	1	\$ 75.00	
182	DASHBOARD	1	\$ 6,972.00	
183	DASHBOARD CENTER AIR VENT	1	\$ 2,272.00	
184	DASHBOARD AIR VENT	1	\$ 591.00	
185	STEERING WHEEL	1	\$ 2,374.00	<i>\$ 1,899.20</i>
186	FRONT SEAT - RH	1	<i>\$ 2,636.00</i>	<i>\$ 2,108.80</i>
187	FRONT SEAT PADDING - RH	1	TBC	
188	FRONT SEAT COVER - RH	1	<i>\$ 2,096.00</i>	<i>\$ 1,676.80</i>
189	FRONT CENTER CONSOLE	1	\$ 815.00	
190	FRONT CENTER CONSOLE INSERT	1	\$ 402.00	
191	FRONT CENTER CONSOLE TRIM	1	\$ 741.00	<i>\$ 592.80</i>
192	FRONT CENTER CONSOLE INSERT STOWAGE	1	\$ 60.00	
193	FRONT CENTER CONSOLE STOWAGE COMPARTMENT	1	\$ 144.00	
194	ASSEMBLY CARRIER	1	\$ 1,891.00	<i>\$ 1,512.80</i>
195	FRONT WISHBONE LINK - LH	1	\$ 539.00	<i>\$ 430.80</i>
196	FRONT SUSPENSION GUIDE - LH	1	\$ 943.00	<i>\$ 754.40</i>
197	UPPER SUSPENSION GUIDE - FRONT / REAR LH	2	\$ 720.00	<i>\$ 576.00</i>
198	WHEEL BEARING HOUSING - LH	1	\$ 1,136.00	<i>\$ 908.80</i>
199	SWIVEL JOINT	1	\$ 193.00	<i>\$ 154.40</i>
200	WHEEL HUB	1	\$ 479.00	<i>\$ 383.20</i>
SUB TOTAL SPARE PARTS		:	\$ 25,079.00	<i>\$ 75,064.40</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	75,064.40
201	FRONT WHEEL BEARING	1	\$ 246.00	\$	196.80
202	SUSPENSION FORKS - LH	1	\$ 366.00	\$	292.40
203	COUPLING ROD	1	\$ 127.00	\$	101.20
204	FRONT ANTI - ROLL BAR	1	\$ 433.00		
205	AXLE ASSEMBLY	1	\$ 2,865.00	\$	2,292.00
206	SHOCK ABSORBER	1	\$ 1,483.00	\$	1,186.40
207	LEVEL SENSOR WITH POLES	1	\$ 535.00	\$	428.00
208	STERRING GEAR WITH TRACK ROD JOINT	1	\$ 6,782.00		
209	TRACK ROD	1	\$ 134.00	\$	106.00
210	TIE ROD END - LH	1	\$ 197.00	\$	157.20
211	ROOF HEADER PANEL	1	\$ 262.00		
212	INNER ROOF REINFORCEMENT	1	\$ 247.00		
213	1 PACK ADHESIVE	1	\$ 73.00		
214	ROOF PANEL BONDING ADHESIVE	1	\$ 23.00		
215	PRIMER	1	\$ 20.00		
216	FRONT DOOR COVER - LH	1	\$ 790.00	\$	632.00
217	STATIC MIXER	5	\$ 56.00	\$	44.40
218	BLINDER RIVET STUD	10	\$ 62.00	\$	49.60
219	FRONT NO PLATE	S/N	TBC		
220	FRONT 2 RIMS - LH / RH (Owner)	3	\$ 981.31	\$	981.31
SUB TOTAL SPARE PARTS		:	\$ 15,682.31	\$	81,531.71

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 1691 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	81,537.71
221	REAR RIM - LH	1	TBC		
222	FRONT 2 TYRES- LH / RH	2	TBC		
223	REAR TYRE - LH	1	TBC	\$	510.00
224	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
225	CRAVITY WAX	S/N	\$ 140.00	\$	140.00
226	STONE CHIP TREATMENT	S/N	\$ 180.00	\$	180.00
227	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
227	REAR WINDSCREEN SEALANT	S/N	\$ 200.00		
228	REAR 1/4 GLASS SEALANT	S/N	\$ 100.00	\$	100.00
230	SUPPLEMENTARY 1	\$	6,698.00	\$	587.52
231	SUPPLEMENTARY 2	\$	30.00	\$	24.00
229	SUPPLEMENTARY 3	\$	33,826.00	\$	27,157.44
234	SUNDRIES	\$	1,500.00	\$	395.28
TOTAL SPARE PARTS			:	\$ 205,616.31	\$ 111,091.95
TOTAL LABOUR CHARGES			:	\$ 71,664.00	\$ 48,519.00
GRAND TOTAL			:	\$ 277,280.31	\$ 159,610.95

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-20/05/22



Supplementary Estimate - 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0780/2021/ZK 8-Oct-21 CHANG 1 of 1 SGN 1691 S AUDI Q5 S-LINE TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LED LIGHT - RH FRONT	\$ 67.00	\$ 55.52
2	INNER ACTUATOR - RH	\$ 255.00	
3	TRAY - RH LOWER	\$ 548.00	\$ 438.00
4	DASHBOARD ALUMINIUM TRIM - RH	\$ 447.00	
5	DASHBOARD ALUMINIUM TRIM - LH	\$ 1,068.00	
6	PADDING FOR SEAT DEPTH	\$ 142.00	
7	DISPLAY AND CONTROL PANEL WITH CU (A/C)	\$ 3,121.00	
8	DRIVE SHAFT SCREW 6	\$ 46.00	\$ 37.04
9	BRAKE HOSE - LH FRONT	\$ 72.00	\$ 56.96
10	ENGINE MOUNTING - LH	\$ 370.00	
11	SUBFRAME CONSOLE - LH	\$ 562.00	
GRAND TOTAL		\$ 6,698.00	\$ 587.52

For Premium Automobiles Pte Ltd

Authorized Signature



Supplementary Estimate - 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0780/2021/ZK 16-Nov-21 CHANG 1 of 1 SGN 1691 S AUDI Q5 S-LINE TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REPAIR LHS FRONT LOWER A-PILLAR.	\$ 400.00	\$ 250.00
2	TO RESPRAY LHS FRONT LOWER A-PILLAR.	\$ 800.00	\$ 550.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT A/C VACUUM AND REGAS (R1234yf) S/N	\$ 2,000.00	\$ 2,000.00
			\$ 2,800.00
<u>Parts</u>			
1	SIGN - UNLEADED PETROL	\$ 30.00	\$ 24.00
GRAND TOTAL		\$ 3,230.00	\$ 2,824.00

For Premium Automobiles Pte Ltd

 Authorised Signature

Supplementary Estimate - 3

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0780/2021/ZK 19-Nov-21 CHANG 1 of 1 SGN 1691 S AUDI Q5 S-LINE 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO SUSPEND ENGINE ASSY, REMOVE AND REINSTALL CARDAN SHAFT. TO DISMANTLE AND RENEW GEARBOX ASSY. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	\$ 2,800.00
<u>Parts</u>			
1	7-SPEED DUAL CLUTCH GEARBOX	\$ 32,056.00	\$ 26,644.80
2	DUAL CLUTCH TRANSMISSION FLUID	\$ 630.00	
3	MTF TRANSMISSION FLUID	\$ 546.00	
4	GEARBOX BOLT SET	\$ 110.00	\$ 86.40
5	ENGINE MOUNTING - RH	\$ 370.00	\$ 335.60
6	ENGINE MOUNTING BOLT	\$ 114.00	\$ 90.64
GRAND TOTAL		\$ 36,626.00	\$ 29,957.44

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT