



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0772/2021/JT
DATE : 20-Sep-21
WIP : 45197

Veron
\$4776.80

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 22/9/21
YOUR INSURED VEH NO : SHA 5976 B

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TEY KHANG WEEI (ZHENG KANGWEI)
ADDRESS : BLK 323 JURONG EAST ST 31
#04-216
SINGAPORE 600323
TELEPHONE : HP +65 96986068
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210081490
VEHICLE NO : SKH 6068 T
MODEL CODE : AUDI Q3 SB 1.4 TFSI S
MODEL YEAR : 29/7/2021
ENGINE NO : CZD C40473
CHASSIS NO : WAUZZZF33M120276
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Sep-21
PLACE OF ACCIDENT : CTE TOWARDS SLE AT 1.8KM
MASK BEFORE ENTERIN TUNNEL

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6068 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LTD	S/N \$ 480.00 ✓ ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 X	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REISNTALL ALL PARTS REMOVED.	\$ 1,200.00 500 ✓	
4	TO REPSRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH WHEEL ARCH TRIMS.	\$ 3,000.00 950 ✓	Bumper 550 Wheel Arch 270x22400 950
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓ ✓	
TOTAL LABOUR CHARGES		: \$ 5,672.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6068 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1 S	2,815.00 X	
2	FRONT BUMPER FIXING PARTS	1 S	414.00 X	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 S	118.00 X	
4	FRONT BUMPER LOWER TRIM (GREY)	1 S	356.00 X	
5	FRONT BUMPER LOWER GRILLE	1 S	217.00 X	
6	FRONT BUMPER GRILLE SENSOR SUPPORT - LH / RH	2 S	50.00 X	
7	FRONT BUMPER LOWER GRILLE CENTER COVER	1 S	51.00 X	
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1 S	190.00 X	
9	FRONT BUMPER SPOILER	1 S	763.00 X	
10	FRONT BUMPER AIR GRILLE - LH / RH	2 S	306.00 X	
11	FRONT BUMPER AIR GRILLE TRIM (GREY) - LH / RH	2 S	328.00 X	
12	FRONT BUMPER SENSOR SUPPORT - LH / RH	2 S	50.00 X	
13	RADIATOR GRILLE <i>ht</i>	1 S	1,928.00	1542.40
14	RADIATOR GRILLE STRIKER PLATE <i>Not Nec</i>	1 S	244.00	X
15	FRONT CAMERA CAP	1 S	56.00 X	
16	FRONT CAMERA BRACKET <i>Not Nec</i>	1 S	41.00 X	
17	RADIATOR GRILLE INNER COVER <i>ht</i>	1 S	244.00 X	194.80
18	FRONT CAMERA	1 S	1,141.00 X	
19	FRONT BUMPER CARRIER FORM <i>Not Nec</i>	1 S	102.00 X	
20	FRONT BUMPER CARRIER	1 S	916.00 X	
SUB TOTAL SPARE PARTS (FRONT)			\$ 10,330.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6068 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER TOP COVER	1	\$ 123.00	X
22	CAUTION STICKER	1	\$ 14.00	X
23	A/C STICKER	1	\$ 8.00	X
24	FRONT PARKING AID SENSOR - LH / RH	2	TBC	X
25	FRONT PARKING AID SENSOR SEAL RING	4	\$ 14.00	X
26	HORN - RH	1	\$ 130.00	X
27	HORN BRACKET - RH	1	\$ 22.00	X
28	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	X
29	HEADLIGHT - RH	1	\$ 5,589.00	X
30	HEADLIGHT LIFT CYLINDER - RH	1	\$ 210.00	X
31	HEADLIGHT LIFT CYLINDER HOSE	1	\$ 80.00	X
32	RADIATOR AIR GRILLE - LH / RH / UPPER	3	\$ 118.00	X
33	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,072.00	857.60
34	FRONT NO. PLATE	S/N	\$ 60.00	60
35	SUNDRIES		\$ 300.00	X
TOTAL SPARE PARTS (FRONT + REAR)		:	\$ 18,306.00	
TOTAL LABOUR CHARGES		:	\$ 5,672.00	
GRAND TOTAL		:	\$ 23,978.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

Adrian Ling

SURVEYED DATE :

22/09/12

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

not authorised, 03 Days.
H.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT