

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

*Xiao Chan*

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMC 5466 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CEHCK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
4	TO REPSRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER. <i>SSD 300</i>	\$ 1,600.00	850
5	TO CARRY OUT CALIBRATION SETTING FOR FRONT RADAR SENSOR AND DISTANCE REGULA'ION	S/N \$ 480.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,752.00	

*Add 1 day  
for labour 5.*

*Adrian King,  
11/11/21.*

*SL/S*