

PREMIUM AUTOMOBILES

55 UB. ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0702/2021/JT
DATE : 28-Aug-21
WIP :

Veron

\$6001.44

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KOO CHONG EN, JOEL (QIU CHONG'EN)
ADDRESS : 30 JALAN SELAMAT
SINGAPORE 418558
TELEPHONE : HP +65 93863323
TYPE OF CLAIM : THIRD PARTY CLAIM *OD claim*
POLICY NO : 1900114974-02
VEHICLE NO : SMN 8800 C
MODEL CODE : Q5 SPORT 2.0 TFSI
MODEL YEAR : 28/6/2019
ENGINE NO : DAX 056215
CHASSIS NO : WAUZZZFY1K2091752
MILEAGE : -
DATE I/I : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Aug-21
PLACE OF ACCIDENT : JUNCTION OF SIMS AVE AND
JALAN EUNOS TOWARDS
SIMS AVE EAST

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 8800 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO FACILITATE THE RENEWAL OF RHS WING MIRROR ASSY.	S/N \$ 280.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER BONNET AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00	1000 ✓
5	TO REPSRAY FRONT BUMPER, FRONT LOWER SPOILER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS WING COVER, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 6,200.00	2050 ✓ 3x550 = 1650 Wheel Arc x2 = 200x2 = 400 2050
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		\$ 11,152.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 8800 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 1,362.00	✓
2	FRONT BUMPER FIXING PARTS	1	\$ 293.00	✓
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 113.00	✓
4	FRONT BUMPER SECURING STRIP - RH	1	\$ 38.00	✓
5	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 581.00	✓
6	FRONT BUMPER AIR GUIDE GRILLE END CAP - RH	1	\$ 92.00	✓
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 39.00	✓
8	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,427.00	✓ 1141.60
9	FRONT FENDER BRACE - RH <i>Not Nec</i>	1	\$ 225.00	✓ X
10	FRONT FENDER BRACKET - RH <i>Not Nec</i>	1	\$ 18.00	✓ X
11	FRONT FENDER FLEDGE COVER SHORT - RH <i>Damaged</i>	1	\$ 31.00	✓ 24.64
12	FRONT FENDER FLEDGE COVER LONG - RH <i>Not Nec</i>	1	\$ 40.00	✓ X
13	"S-LINE" EMBLEM <i>Not Nec</i>	1	\$ 128.00	✓ 102
14	HEADLIGHT MOUNTING - RH <i>Not Nec</i>	1	\$ 118.00	✓
15	LED HEADLIGHT - RH <i>Not Nec</i>	1	\$ 8,191.00	✓
16	FRONT WHEEL HOUSING LINER - RH <i>Not Nec</i>	1	\$ 278.00	✓
17	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH <i>Not Nec</i>	1	\$ 38.00	✓
18	FRONT WHEEL SPOILER - RH <i>Not Nec</i>	1	\$ 155.00	✓
19	FRONT WHEEL ARCH COVER - LH / RH <i>LH Not, RH Dented</i>	2	\$ 1,264.00	✓ 1011.20
20	FRONT WING MIRROR MOUNTING - RH <i>Not Nec</i>	1	\$ 1,749.00	✓
SUB TOTAL SPARE PARTS			\$ 16,180.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEI:END: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 8800 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR COVER - RH <i>new</i>	1	\$ 790.00	x
22	BONNET <i>Regis</i>	1	\$ 4,058.00	x
23	BONNET ATTACHMENT PARTS	1	\$ 141.00	+
24	BONNET IMPACT PROTECTION - LH / RH	2	\$ 56.00	+
25	BONNET IMPACT PROTECTION - CENTER	1	\$ 28.00	+
26	SUNDRIES <i>Noe Nec.</i>	1	\$ 350.00	? X
TOTAL SPARE PARTS		:	\$ 21,603.00	
TOTAL LABOUR CHARGES		:	\$ 11,152.00	
GRAND TOTAL		:	\$ 32,755.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 63 6 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Ling
SURVEYED DATE : 22/09/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 Days.
H. Z.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT