

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No:
Make and model:

SMS2958U
Toyota Sienta

Estimate

Qty Spare parts

1	Front bumper	S	✓ 581.90	BRV
1	Front bumper top rubber seal	S	55.00	NSX
1	Front bumper LH side retainer	S	✓ 67.20	
1	Front bumper RH side retainer	S	✓ 67.20	NECV
1	Front bumper RH side garnish	S	90.40	156.70
1	RH headlamp assy	S	727.20	987.00
1	Front RH fender	S	✓ 551.00	DDV
1	Front RH fender "Hybrid" emblem	S	42.10	59.00
1	Front RH fender splash shield	S	153.20	176.00
1	Front RH door	S	✓ 1,112.00	DDV
1	Front RH door frame black tape	S	✓ 51.00	NECV
1	Front RH door inner trim board	S	1,077.00	NDX
1	Front RH side mirror assy	S	866.10	1,157.80
1	Front RH side mirror cover	S	73.40	105.70
1	Front RH door lock	S	657.00	NDX
1	Front RH rim cap	S	174.80	NSX
1	Front RH steel rim	S	280.00	NDX
1	Front RH wheel bearing	S	409.00	
1	Front RH lower arm	S	497.00	
1	Front RH knuckle arm	S	593.80	
1	Front RH shock absorber	S	457.00	NDX
1	Front RH tie rod end	S	409.00	
1	Front RH drive shaft	S	1,099.80	
1	Steering rack and pinion	S	1,331.10	

S 4382.70 11,513.00
-25% S 1095.68 2,878.25
S 3287.03 8,634.75

Qty Spare parts

1set	Front bumper clips	S	30.00	70.00
1set	Front RH fender splash shield clips	S		50.00
1	Front RH tyre	S		280.00
1set	Front RH door inner trim board clips	S		60.00
1	Brake fluid	S		55.00

30.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

S 600.00 1,000.00 ✓

Spray painting on affected panels

S 600.00 1,000.00 ✓

Check wiring and lighting system

S 80.00 NXX

Apply rust coating chemical on affected panels

S 70.00 NXX

Remove and replace front undercarriage parts to assist repair

S 280.00 NXX

Conduct and adjust wheel alignment system

S 100.00 NXX

Remove and reinstall front RH door inner mechanism to new door

S 80.00 400.00 ✓

1280.00

Total: S 11,779.75

Survey Resurvey

24/9/2021 24/9/2021

1800 hrs 1800 hrs

Team Lin Team Lin

Lump sum repair
Repair days 5

Parts 3287.03

SN 30.00

Labour 1280.00

4597.03

@ 20% 919.41

3677.62

LS 3650/-

Team Lin

6/2/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: