



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 37L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER,REAR (SN)	DENTED	1,102.10	1,102.10
1	REAR BUMPER SPOILER (SN)	TO REPAIR SEE LABOUR	319.90	-
1	REAR BUMPER LOWER TRIM (SN)	NOT NECESSARY	213.30	-
8	EXPANDER NUT (SN)	NECESSARY	12.80	12.80
1	P95B-807-254-C-/SUPPORT BRACKET RH (SN)	NOT NECESSARY	80.20	-
1	REAR BUMPER RETAINER RH (SN)	NOT NECESSARY	93.60	-
2	EXPANDER NUT (SN)	NECESSARY	4.40	4.40
4	SENSOR GASKET (SN)	NECESSARY	12.40	12.40
1	WHEEL COVER RH (SN)	CUT	48.60	48.60
1	REAR DOOR LOWER TRIM RH (SN)	NECESSARY	559.40	559.40
1	REPAIR KIT ADHESIVE (SN)	NECESSARY	107.80	107.80
1	STONE GUARD FILM RH (SN)	NECESSARY	85.90	85.90
1	ALLOY WHEEL (SN)	CUT	3,351.00	3,351.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			6,041.40	5,304.40
	<u>LABOUR</u>			
	TO REMOVE/REPLACE REAR BUMPER & ALL DAMAGED BODY PARTS.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR BUMPER SPOILER.		3,120.00	1,560.00
	TO RESPRAY REAR BUMPER,REAR BUMPER LOWER SPOILER,REAR DOOR RH,REAR FENDER RH.		4,800.00	3,500.00
	TO REPLACE 1PC TYRE 295/40R20.	NOT NECESSARY	980.00	-
	TO MOUNT 1PC SPORT RIM AND CONDUCT WHEEL BALANCING.		120.00	120.00
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		680.00	680.00
	TO INSTALL THE REAR DOOR RH STICKER.		225.00	225.00
	TO TRANSFER THE REVERSE SENSORS.		300.00	150.00
	TO APPLY SPECIAL CERAMIC COATING (NPA).	NOT NECESSARY	-	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00

Report Ref No. CS/SMR21009919/Euf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			11,075.00	6,985.00
GRAND TOTAL			17,116.40	12,289.40
RECOMMENDED COST OF REPAIRS				12,289.40

Report Ref No. CS/SMR21009919/Euf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.