



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009919/Euf3n2	
			Date: 11/11/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6070S	Veh. Inspected	SGS 37L
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/09/21/2033	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	23/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	PORSCHE MACAN	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WP1ZZZ95ZJLB02663	Colour	WHITE
	Odometer	80054 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/40 R20	PIRELLI	4 mm
	L/H Front Tyre	295/40 R20	PIRELLI	4 mm
	R/H Rear Tyre	295/40 R20	PIRELLI	4 mm
	L/H Rear Tyre	295/40 R20	PIRELLI	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/09/2021	Inspection Date	27/09/2021
	Survey held at	27A TANJUNG PENJURU		
	Repairer	EUROKARS HABITAT PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	