



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

ELROKARS GROUP

SMRT AUTOMOTIVE SERVICES PTE LTD 60 Woodlands Industrial Park E4 Singapore 757705		NAME : ADDRESS : TEL :		WIP : 22070 EXCESS : DATE: 21-Sep-21	
ATTN : MOTOR CLAIMS FAX :					
VEH NO :	SGS37L	DATE IN :		CONTACT PERSON :	
CHASSIS NO :	WP1ZZZ95ZJLB02663	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	Macan	DATE REG.:	17-Nov-17	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	1ST	SUPP	REVISED	PRICES
1	BUMPER, REAR / DD	1				\$ 1,102.10
2	REAR BUMPER SPOILER X R	1				\$ 319.90
3	REAR BUMPER LOWER TRIM X nn	1				\$ 213.30
4	EXPANDER NUT / MC	8				\$ 12.80
5	P95B-807-254-C -/SUPPORT BRACKET RH ? X nn	1				\$ 80.20
6	REAR BUMPER RETAINER RH ? X nn	1				\$ 93.60
7	EXPANDER NUT / MC	2				\$ 4.40
8	SENSOR GASKET / MC	4				\$ 12.40
9	WHEEL COVER RH / Cui	1				\$ 48.60
10	REAR DOOR LOWER TRIM RH (Black) / MC	1 (photo)				\$ 559.40
11	REPAIR KIT ADHESIVE / MC	1				\$ 107.80
12	STONE GUARD FILM RH / MC	1				\$ 85.90
13	ALLOY WHEEL (Rear RH) / Cui	1				\$ 3,351.00
14		0				\$ -
TOTAL PARTS						\$ 5,991.40
TOTAL PARTS COST						\$ 5,991.40

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
Labour Description							
1	TO REMOVE /REPLACE REAR BUMPER & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 1560						\$ 3,120.00
2	TO RESPRAY REAR BUMPER, REAR BUMPER LOWER SPOILER, REAR DOOR RH, REAR FENDER RH.						\$ 4,800.00
3	TO REPLACE 1 PC TYRE. 295/40 R20					NETT	\$ 980.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.					NETT	\$ 120.00

5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		NETT	\$ 680.00	✓
6	TO INSTALL THE REAR DOOR RH STICKER.		NETT	\$ 225.00	✓
7	TO TRANSFER THE REVERSE SENSORS.			\$ 300.00	150 -
8	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE)		NETT		7 x
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00	150 -
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$ 600.00	✓
11	SUNDRIES.		NETT	\$ 50.00	20 -
TOTAL LABOUR			\$ -	\$ 11,125.00	
TOTAL PARTS			\$ -	\$ 5,991.40	
TOTAL			\$ -	\$ 17,116.40	
LESS EXCESS			\$ -	\$ -	
TOTAL AFTER EXCESS			\$ -	\$ 17,116.40	
GST 7%			\$ -	\$ 1,198.15	
GRAND TOTAL			\$ -	\$ 18,314.55	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Stee (LKK)

27/9/21, 2:30p

Wk A/L

P/P

Ry Bul Sy

6 djs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: