

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 05 Oct 2021

Preliminary Advice

Insured Vehicle No	: SLM8774L	Accident Date	: 21/09/2021
TP Vehicle No	: SMK747S	Assignment Date	: 23/09/2021
Make	: MERCEDES-BENZ A200	Est. Duration of Repair	: 2
Date of Inspection	: 23/09/2021		
Inspection At	: 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53		
	REPAIRER: ZOOM AUTOWERKS PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,834.40
Revised Amount	:S\$	1,629.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,629.60
 Lump Sum Repair	 :S\$	 1,300.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	118,000.00
COE / PARF Rebate	:S\$	59,457.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,543.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.