

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

Contact : 98394400

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVWZZZ16ZEM035344/CAXE38528

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENDER / DEF	1	1200.99	1,200.99
AIRCON CONDENDER ALUMINIUM PIPE / DEF	1	1007.60	1,007.60
AIRCON CONDENDER DISCHARGE PIPE / DEF	1	1033.77	1,033.77
ENGINE OIL DIPSTICK / DEF	1	99.79	99.79
ENGINE OIL FILTER / NEC	1	90.97	90.97
ENGINE OIL FILTER LOWER BRACKET / NEC	1	388.90	388.90
FRONT AIR CLEANER BOX ASSY / DEF	1	688.90	688.90
FRONT AIR CLEANER BOX LOWER BRACKET (BATTERY TRAY) / DEF	1	369.10	369.10
FRONT BONNET / BT	1	2333.90	2,333.90
FRONT BONNET HINGES L/R / BT	2	190.77	381.54
FRONT BONNET INSULATOR / DEF	1	500.78	500.78
FRONT BONNET LOCK CABLE / DEF	1	133.71	133.71
FRONT BONNET LOCK CATCH / DEF	1	199.71	199.71
FRONT BONNET MECHANISM LOCK / DEF	1	280.71	280.71
FRONT BRACE PANEL / BT	1	140.71	140.71
FRONT BUMPER / CRK	1	1700.71	1,700.71
FRONT BUMPER CENTER BRACKET / CRK	1	199.70	199.70
FRONT BUMPER FOGLAMP GARNISH L/R / DEF	2	199.70	399.40

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

Contact : 98394400

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVVZZZ16ZEM035344/CAXE38528

FRONT BUMPER LOWER GRILLE XSVL	1	488.96	488.96
FRONT BUMPER NUMBER PLATE GARNISH DEF	1	199.77	199.77
FRONT BUMPER REINFORCEMENT DD	1	688.90	688.90
FRONT BUMPER SIDE RETAINER L/R	2	120.77	241.54
FRONT BUMPER SPONGE DEF	1	199.70	199.70
FRONT BUMPER TOW HOOK COVER DEF	1	100.77	100.77
FRONT ENGINE MOUNTING LH DEF	1	488.96	488.96
FRONT ENGINE MOUNTING REAR XSVL	1	200.33	200.33
FRONT ENGINE MOUNTING RH DEF	1	500.33	500.33
FRONT ENGINE UNDER COVER DEF	1	488.96	488.96
FRONT ENGINE WIRE HARNESS DEF	1	4900.77	4,900.77
FRONT FENDER 'SPECIAL EDITION' EMBLEM L/R NEL	2	188.96	377.92
FRONT FENDER INNER BRACKET L/R DEF	2	90.91	181.82
FRONT FENDER INNER PANEL L/R BT	2	999.70	1,999.40
FRONT FENDER INNER SHIELD CLIPS L/R - SET	2	50.00	100.00
FRONT FENDER INNER SHIELD L/R TN	2	199.79	399.58
FRONT FENDER L/R DD	2	999.70	1,999.40
FRONT GRILLE ASSY XSVL	1	800.77	800.77

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

Contact : 98394400

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVWZZZ16ZEM035344/CAXE38528

FRONT HEADLAMP L/R <i>R/CRK</i>	2	999.79	1,999.58
FRONT HEADLAMP TOP PANEL L/R <i>/DEF</i>	2	133.70	267.40
FRONT HORN <i>/DEF</i>	1	233.96	233.96
FRONT INTERCOOLER <i>/DEF</i>	1	833.75	833.75
FRONT INTERCOOLER HOSE LOWER <i>/DEF</i>	1	190.77	190.77
FRONT INTERCOOLER HOSE TOP <i>/DEF</i>	1	189.79	189.79
FRONT LH BODY WIRE HARNESS <i>/DEF</i>	1	2999.70	2,999.70
FRONT SUPPORT PANEL <i>/DEF</i>	1	1200.97	1,200.97
FRONT WASHER TANK <i>/CRK</i>	1	233.96	233.96
FRONT WASHER TANK MOTOR <i>/DEF</i>	1	190.77	190.77
FRONT WASHER TANK NECK <i>/DEF</i>	1	190.99	190.99
RADIATOR <i>/DEF</i>	1	999.70	999.70
RADIATOR FAN COWLING ASSY <i>/DEF</i>	1	180.97	180.97
RADIATOR LOWER HOSE <i>/DEF</i>	1	2119.60	2,119.60
RADIATOR SIDE BRACKET L/R <i>/DEF</i>	2	199.79	399.58
RADIATOR TOP HOSE <i>/DEF</i>	1	233.91	233.91
REAR BOOTLID <i>XSL</i>	1	1997.60	1,997.60
REAR BOOTLID 'JETTA' EMBLEM <i>/NEC</i>	1	160.77	160.77

*** This is a computer-generated document which requires no signature. ***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

Contact : 98394400

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVWZZZ16ZEM035344/CAXE38528

REAR BOOTLID 'LOGO' EMBLEM X NN	1	180.77	180.77
REAR BOOTLID 'TSI' EMBLEM X NN	1	160.77	160.77
REAR BOOTLID HINGES L/R X SVC	2	180.73	361.46
REAR BOOTLID INNER RUBBER STOPPER L/R X SVC	2	30.17	60.34
REAR BOOTLID INNER TRIM BOARD X SVC	1	489.60	489.60
REAR BOOTLID MECHANISM LOCK X SVC	1	269.70	269.70
REAR BOOTLID REFLECTOR L/R X SVC	2	390.99	781.98
REAR BOOTLID WEATHER STRIP X SVC	1	680.77	680.77
REAR BUMPER / CRK	1	1499.70	1,499.70
REAR BUMPER CENTER BRACKET / CRK	1	299.70	299.70
REAR BUMPER LOWER LID / CRK	1	699.70	699.70
REAR BUMPER REFLECTOR L/R L / CRK, R / MIS	2	189.79	379.58
REAR BUMPER REINFORCEMENT / DD	1	600.71	600.71
REAR BUMPER SIDE RETAINER L/R L / CRK	2	189.79	379.58
REAR BUMPER UNDER COVER RH - DEF	1	500.99	500.99
REAR END PANEL / DD	1	1500.77	1,500.77
REAR END PANEL INNER TOP GARNISH / CRK	1	388.91	388.91
REAR EXHAUST CHROME TAIL PIPE L/R / DEF	2	500.77	1,001.54

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVWZZZ16ZEM035344/CAXE38528

REAR EXHAUST GASKET / DEC	1	30.37	30.37
REAR EXHAUST HEAT COVER / DEF	1	388.71	388.71
REAR EXHAUST RUBBER MOUNTING X SVC	2	180.77	361.54
REAR EXHAUST SILENCER BOX / PD	1	1999.70	1,999.70
REAR FENDER INNER TRIM BOARD L/R X SVC	2	233.75	467.50
REAR FLOOR PANEL / DD	1	1900.99	1,900.99
REAR FLOOR PANEL TOP BOARD COVER X SVC	1	3889.00	3,889.00
REAR LH FENDER INNER SHIELD / TN	1	233.71	233.71
REAR TAILLAMP L/R / CLK	2	500.77	1,001.54
REAR TAILLAMP LOWER BRACKET L/R / CLK	2	179.10	358.20
TIMING COVER / DEF	1	700.77	700.77
TURBOCHARGER ASSY / DEF	1	5000.77	5,000.77
TURBOCHARGER BYPASS VALVE SENSOR / DEF	1	199.70	199.70
TURBOCHARGER CHROME HEAT COVER / DEF	1	233.96	233.96
TURBOCHARGER OUTER HOSE BRACKET / DEF	1	169.79	169.79

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVVZZZ16ZEM035344/CAXE38528

Contact : 98394400

Subtotal before discount		67,305.36
Percentage discount	0%	0.00
Sub-total 1		67,305.36
FRONT BONNET INSULATOR CLIPS - SET / NEC	1	60.00 30 60.00
FRONT BUMPER CLIPS - SET / NEC	1	60.00 50 60.00
FRONT BUMPER LOWER SPOILER X SVC	1	800.00 800.00
FRONT BUMPER NUMBER PLATE / MISSING	1	25.00 25.00
FRONT BUMPER NUMBER PLATE HOLDER / CRK	1	50.00 30 50.00
RADIATOR COOLANT / NEC	1	80.00 60 80.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET X NN	1	50.00 50.00
REAR BUMPER CENTER LOWER SPOILER X SVC	1	350.00 350.00
REAR BUMPER CLIPS - SET / NEC	1	50.00 50.00
REAR BUMPER REVERSE SENSOR - SET / DEF	1	280.00 280.00
REAR BUMPER SIDE SPOILER L/R / DEF	2	350.00 700.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET / NEC	1	30.00 30.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET X NN	2	50.00 100.00
REAR FLOOR PANEL INSULATOR MAT X SVC	1	300.00 300.00
REAR LH FENDER INNER SHIELD CLIPS - SET / NEC	1	50.00 30 50.00
REAR TAILLAMP CLIPS L/R - SET / NEC	2	25.00 30 50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

Contact : 98394400

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVWZZZ16ZEM035344/CAXE38528

Subtotal before discount	3,035.00
Percentage discount 0%	0.00
Sub-total 2	3,035.00
Parts-total	70,340.36

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector XNN	80.00
To remove, change air con parts, vacuums, refill air con gas. NFE	200 120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR) NFE	80.00
To reset system after repair works y show report.	400.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	50 80.00
To remove, install engine with transmission. (to FR) NFE	250 450.00
To remove, reinstall front suspension undercarriage parts. (to FR) XNN	240.00
To remove, reinstall rear suspension and undercarriage part. (to FR) XNN	240.00
To road test driving, check and resetting wheel alignments system. y show report.	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) XNN	140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	600 1,200.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	900 1,400.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident. NFE	50 100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,600 2,000.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

S D KAM PTE LTD
6 WARINGIN PARK
SINGAPORE 416320

Contact : 98394400

ESTIMATE

Repair Code : CLM15317

Date in : 22/09/2021

Vehicle Num. : SKP3737Z

Model : VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis/Eng# : WVVZZZ16ZEM035344/CAXE38528

To apply anti-rust chemical on repaired and replaced panel. *NFL*

Labour Total

100 128.00
7,350.00

Parts & Labour Total

77,690.36

*** This is a computer-generated document which requires no signature.***

page 8

NA2 LKK
23/9/2021

L/S
15 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: