



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0773/2021/ZK  
**DATE** : 20-Sep-21  
**WIP** : 45352

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/9/2021**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

*Hi Steve*

*5 days - ok - Johnny Boo*

*27-Oct-21*

**OWNER'S NAME** : MR NG HOCK CHUAN  
**ADDRESS** : 73 HUME AVENUE  
#03-01  
SINGAPORE 598747  
**TELEPHONE** : HP +65 93821646  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2070151462  
**VEHICLE NO** : **SJW 5117 A**  
**MODEL CODE** : A4 2.0 TFSI S TRONIC  
**MODEL YEAR** : 26/10/2020  
**ENGINE NO** : DEM 025292  
**CHASSIS NO** : WAUZZZF4XMN000749  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 20-Sep-21  
**PLACE OF ACCIDENT** : SUNTEC CITY CARPARK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 5117 A**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$ 560.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS B-PILLAR AND LHS SILL PANEL.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$ 1,000.00
3	TO RESPRAY LHS FRONT DOOR,LHS REAR DOOR , HINGES,LHS SILL PANEL,LHS B-PILLAR,DOOR HANDLE AND DOOR ENTRANCES	\$	4,500.00	\$ 1,650.00
4	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	S/N \$	800.00	
5	TO PUT CAR ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	S/N \$	2,400.00	
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 11,392.00</b>	<b>\$ 3,402.00</b>

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 5117 A**

					<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>S/NETT</b>	<b>REMARKS</b>	
1	FRONT DOOR - LH	1	\$	3,192.00	<b>\$ 2,553.60</b>	
2	RIVETTED CAP NUT	8	\$	24.00		
3	FRONT DOOR OUTER SEAL - LH	1	\$	205.00	<b>\$ 164.00</b>	
4	BONDING AGENT	S/N	\$	49.00		
5	CLEANING SOLUTION	S/N	\$	68.00		
6	APPLICATOR	S/N	\$	8.00		
7	FRONT DOOR ATTACHMENT PARTS - LH	1	\$	1,050.00		
8	FRONT DOOR CATCH	1	\$	105.00		
9	FRONT DOOR HANDLE TRIM - LH	1	\$	88.00	<b>\$ 69.92</b>	
10	FRONT DOOR HOUSING - LH	1	\$	8.00	<b>\$ 5.92</b>	
11	FRONT HANDLE DOOR COVER - LH	1	\$	6.00	<b>\$ 4.64</b>	
12	FRONT DOOR HANDLE SENSOR - LH	1	\$	228.00	<b>\$ 182.40</b>	
13	FRONT DOOR EXTERIOR HANDLE - LH	1	\$	44.00	<b>\$ 34.88</b>	
14	FRONT DOOR HANDLE UNDERLAY RUBBER - LH FRONT/ REAR	2	\$	8.00	<b>\$ 5.76</b>	
15	FRONT DOOR MOUNTING BAR - LH	1	\$	164.00		
16	REAR DOOR - LH	1	\$	3,192.00	<b>\$ 2,553.60</b>	
17	RIVETTED CAP NUT	13	\$	39.00		
18	REAR DOOR OUTER SEAL - LH	1	\$	205.00	<b>\$ 164.00</b>	
19	BONDING AGENT	S/N	\$	49.00		
20	CLEANING SOLUTION	S/N	\$	68.00		
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>8,800.00</b>	<b>\$ 5,738.72</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 5117 A**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<b>C/F</b>		<b>\$</b>	<b>5,738.72</b>
21	APPLICATOR	S/N	\$	8.00	
22	REAR DOOR SEALING STRIP - LH	1	\$	17.00	
23	REAR DOOR ATTACHEMENT PARTS - LH	1	\$	860.00	
24	REAR DOOR CATCH	1	\$	120.00	
25	REAR DOOR UPPER HINGE - LH	1	\$	44.00	
26	REAR DOOR LOWER HINGE - LH	1	\$	46.00	
27	FRONT DOOR UPPER HINGE - LH	1	\$	45.00	
28	FRONT DOOR LOWER HINGE - LH	1	\$	46.00	
29	REAR INNER DOOR SEAL - LH	1	\$	222.00	
30	FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	1	\$	282.00	
31	REAR DOOR SILL TRIM - LH	1	\$	120.00	
32	AIRBAG / CHILD'S SEAT STICKER	1	\$	24.00	
33	STONE CHIP	S/N	\$	180.00	<b>\$ 180.00</b>
34	SUNDRIES		\$	400.00	<b>\$ 8.32</b>
<b>TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 11,214.00</b>	<b>\$ 5,927.04</b>
<b>TOTAL LABOUR CHARGES</b>			<b>:</b>	<b>\$ 11,392.00</b>	<b>\$ 3,402.00</b>
<b>GRAND TOTAL</b>			<b>:</b>	<b>\$ 22,606.00</b>	<b>\$ 9,329.04</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-27/10/21



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT