

BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4 #01-49
 SINGAPORE 415875
 TEL: 64524457 FAX: 64524584
 ATT: IKHWAN HP 93290237

Estimate for SKX7498U(Toyota Altis)

2015

1 *REAR BOOTLID	755.00	\$881.10	DDV ✓
1 *REAR BOOTLID ALTIS EMBLEM	✓	\$54.10	} NECV ✓
1 *REAR BOOTLID COROLLA EMBLEM	✓	\$50.20	
1 *REAR BOOTLID LOGO EMBLEM	✓	\$58.50	
2 *REAR BOOTLID HINGES L/R		\$159.20	NDX ✓
2 *REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R		\$34.00	NDX ✓
1 *REAR BOOTLID INNER TRIM BOARD		\$281.85	NDX ✓
1 *REAR BOOTLID LOCK STRIKER		\$85.00	NDX ✓
1 *REAR BOOTLID MECHANISM LOCK	379.20	\$379.20	JMV ✓
1 *REAR BOOTLID OUTER CHROME HANDLE		\$203.00	NDX ✓
1 *REAR BOOTLID REFLECTOR INNER BLACK RUBBER GASKET R		\$86.20	} NDX ✓
1 *REAR BOOTLID REFLECTOR INNER BLACK RUBBER GASKET L		\$86.20	
1 *REAR BOOTLID REFLECTOR L		\$374.10	
1 *REAR BOOTLID REFLECTOR R		\$374.10	} NDX ✓
1 *REAR BOOTLID WEATHER STRIP		\$271.45	
1 *REAR BUMPER	492.20	\$581.90	DDV ✓
1 *REAR BUMPER REFLECTOR L/R		\$282.00	NDX ✓
1 *REAR BUMPER REINFORCEMENT		\$398.70	NDX ✓
1 *REAR BUMPER REINFORCEMENT BRACKET R		\$165.00	} NDX ✓
1 *REAR BUMPER REINFORCEMENT BRACKET L		\$165.00	
1 *REAR BUMPER REVERSE SENSOR L	100.00	\$265.30	} SCV ✓
1 *REAR BUMPER REVERSE SENSOR R	100.00	\$265.30	
2 *REAR BUMPER REVERSE SENSOR HOLDER	90.00	\$242.20	NECV ✓
1 *REAR BUMPER REVERSE SENSOR WIRE HARNESS		\$715.20	NDX ✓
1 *REAR BUMPER SIDE RETAINER L	✓	\$65.00	} NECV ✓
1 *REAR BUMPER SIDE RETAINER	✓	\$65.00	
1 *REAR END PANEL	581.20	\$781.90	DD ✓
1 *REAR END PANEL ANTENNA SENSOR		\$175.00	NDX ✓
1 *REAR END PANEL INNER TOP GARNISH	✓	\$185.99	BRV ✓
1 *REAR TAILLAMP INNER BACK RUBBER GASKET L/R	✓	\$51.00	NECV ✓
1 *REAR TAILLAMP R	✓	\$391.90	} BRV ✓
1 *REAR TAILLAMP L	✓	\$391.90	
1 *REAR TAILLAMP LOWER BRACKET L/R	110.00	\$177.40	BRV ✓
1 *REAR FENDER INNER TRIM R	338.00	\$388.00	} TNV ✓
1 *REAR FENDER INNER TRIM L	338.00	\$388.00	
	4,597.19	\$9,519.89	
Less 25%	1,149.30	\$2,379.97	
	3,447.89	\$7,139.92	
S/Nett			
*REAR BOOTLID INNER TRIM BOARD CLIPS - SET	30.00	\$50.00	NECV ✓
*REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	20.00	\$40.00	NECV ✓

*REAR BUMPER CLIPS - SET	30.00	\$80.00	NEC ✓
*REAR END PANEL INNER TOP GARNISH CLIPS - SET		\$30.00	NEC ✓
*REAR FENDER INNER TRIM CLIPS L/R - SET	60.00	\$100.00	NEC ✓
*REAR TAILLAMP CLIPS L/R - SET		\$40.00	NSX
*REAR BUMPER LOWER SPOILER	400.00	\$850.00	BR ✓
		<u>\$1,190.00</u>	

TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR		\$80.00	✓
--	--	---------	---

TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR		\$100.00	NNX
--	--	----------	-----

TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		\$140.00	NNX
---	--	----------	-----

TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		\$1,300.00	600.00
--	--	------------	--------

TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		\$1,200.00	600.00
---	--	------------	--------

TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$120.00	NNX
--	--	----------	-----

\$2,940.00

Total

\$11,269.92

Survey	Resurvey	Lump sum repair
24/9/2021	24/9/2021	Repair days 7
Tellin	Tellin	
Mr	Mr	
1730 hrs	1730 hrs	

Parts	3447.89
SN	570.00
Labour	1280.00
	<u>5297.89</u>
@ 20%	1059.58
	<u>4238.31</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

L/S 4,250/2

Tellin Mr
26/10/2021