

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ZAINALABIDIN BIN MOHD ADNAN
 BLK 149 TAMPINES ST 12 #02-90
 SINGAPORE 521149

Contact : 96444093, 82233354

ESTIMATE

Repair Code : CLM15318
 Date in : 23/09/2021
 Vehicle Num. : SJQ1356J
 Model : HONDA CITY 1.5L I-VTEC AUTO
 Chassis/Eng# : MRHGM26509P020147/L15A71800732

Parts and Labour Assesment

| Description of part | Qty | Unit Price | Amount |
|---|-----|------------|--------|
| REAR BOOTLID / DD | 1 | 503.90 | 503.90 |
| REAR BOOTLID 'CITY' EMBLEM / NEC | 1 | 16.20 | 16.20 |
| REAR BOOTLID 'I-VTEC' EMBLEM / NEC | 1 | 22.20 | 22.20 |
| REAR BOOTLID 'LOGO' EMBLEM / NEC | 1 | 17.80 | 17.80 |
| REAR BOOTLID HINGES L R X SVC | 2 | 64.30 | 128.60 |
| REAR BOOTLID INNER LOWER GUIDE STOPPER L R X SVC | 2 | 11.50 | 23.00 |
| REAR BOOTLID INNER RUBBER GUIDE STOPPER L R X SVC | 2 | 9.50 | 19.00 |
| REAR BOOTLID INNER TRIM BOARD X SVC | 1 | 79.80 | 79.80 |
| REAR BOOTLID LOCK STRIKER / DEF | 1 | 27.50 | 27.50 |
| REAR BOOTLID MECHANISM LOCK / DEF | 1 | 56.80 | 56.80 |
| REAR BOOTLID NUMBER PLATE LAMP L R / Not working | 2 | 18.20 | 36.40 |
| REAR BOOTLID OUTER HANDLE X SVC | 1 | 74.40 | 74.40 |
| REAR BOOTLID WEATHER STRIP / TN | 1 | 74.40 | 74.40 |
| REAR BUMPER / DEF | 1 | 463.70 | 463.70 |
| REAR BUMPER SIDE BRACKET L R / DEF | 2 | 14.80 | 29.60 |
| REAR BUMPER SIDE RETAINER L R / DEF | 2 | 14.80 | 29.60 |
| REAR END PANEL / DD | 1 | 399.30 | 399.30 |
| REAR END PANEL INNER TOP GARNISH / DEF | 1 | 66.60 | 66.60 |

\$1,744.00

*** This is a computer-generated document which requires no signature. ***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ZAINALABIDIN BIN MOHD ADNAN
 BLK 149 TAMPINES ST 12 #02-90
 SINGAPORE 521149

Contact : 96444093, 82233354

ESTIMATE

Repair Code : CLM15318
 Date in : 23/09/2021
 Vehicle Num. : SJQ1356J
 Model : HONDA CITY 1.5L I-VTEC AUTO
 Chassis/Eng# : MRHGM26509P020147/L15A71800732

| | | | |
|---|---|--------|-----------------|
| REAR FENDER INNER TRIM BOARD L R <i>X SVC</i> | 2 | 87.30 | 174.60 |
| REAR FLOOR PANEL TOP BOARD COVER <i>/ DEF</i> | 1 | 70.80 | 70.80 |
| REAR LH FENDER <i>XR</i> | 1 | 761.90 | 761.90 |
| REAR TAILLAMP INNER BLACK GASKET L R <i>/ NEC</i> | 2 | 12.50 | 25.00 |
| REAR TAILLAMP INNER PANEL L R <i>X SVC</i> | 2 | 114.00 | 228.00 |
| REAR TAILLAMP L R <i>/ CRK</i> | 2 | 205.70 | 411.40 |
| REAR WINDSCREEN MOULDING <i>/ NEC</i> | 1 | 65.60 | 65.60 |
| Subtotal before discount | | | 3,806.10 |
| Percentage discount 20% | | | 761.22 |
| Sub-total 1 | | | 3,044.88 |
| REAR BOOTLID INNER TRIM BOARD CLIPS - SET <i>X NN</i> | 1 | 50.00 | 50.00 |
| REAR BOOTLID NUMBER PLATE <i>X SVC</i> | 1 | 25.00 | 25.00 |
| REAR BOOTLID NUMBER PLATE HOLDER <i>X SVC</i> | 1 | 50.00 | 50.00 |
| REAR BOOTLID OUTER HANDLE CLIPS - SET <i>X NN</i> | 1 | 50.00 | 50.00 |
| REAR BUMPER CLIPS - SET <i>/ NEC</i> | 1 | 80.00 | 80.00 |
| REAR BUMPER REVERSE SENSOR - SET <i>/ DEF</i> | 1 | 280.00 | 280.00 |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>/ NEC</i> | 1 | 20.00 | 20.00 |
| REAR FENDER INNER TRIM BOARD CLIPS L R - SET <i>X NN</i> | 2 | 50.00 | 100.00 |

572.00

*** This is a computer-generated document which requires no signature. ***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ZAINALABIDIN BIN MOHD ADNAN
 BLK 149 TAMPINES ST 12 #02-90
 SINGAPORE 521149

Contact : 96444093. 82233354

ESTIMATE

Repair Code : CLM15318
 Date in : 23/09/2021
 Vehicle Num. : SJQ1356J
 Model : HONDA CITY 1.5L I-VTEC AUTO
 Chassis/Eng# : MRHGM26509P020147/L15A71800732

| | | | | |
|-------------------------------|-------|---|-------|---------------------|
| REAR TAILLAMP CLIPS L R - SET | ✓ NEC | 2 | 25.00 | 50.00 |
| REAR WINDSCREEN SEALANT | ✓ NEC | 1 | 80.00 | 80.00 50 |
| Subtotal before discount | | | | 480 785.00 |
| Percentage discount 0% | | | | 0.00 |
| Sub-total 2 | | | | 785.00 |
| Parts-total | | | | <u>3,829.88</u> |

LABOUR

| | | | | |
|---|-----|--|--|---------------------------|
| To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector | ✓ | | | 50 80.00 |
| To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor. | ✓ | | | 30 80.00 |
| To remove, reinstall windscreen (REAR) | ✓ | | | 120 150.00 |
| To remove, reinstall petrol tank. (to FR) | XNN | | | X 80.00 |
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) | XNN | | | X 120.00 |
| To re-spray painting on the rear bootlid, rear end panel, rear fender (L R), spare tyre panel and rear bumper. | | | | 1,000 1,300.00 |
| To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | | | | 1,000 1,500.00 |
| To apply anti-rust chemical on repaired and replaced panel. | | | | 50 120.00 |
| Labour Total | | | | 2,250 3,430.00 |
| Parts & Labour Total | | | | <u>7,259.88</u> |

*** This is a computer-generated document which requires no signature.***

PARTS \$2,316.80
 LESS 20% \$1,853.44
 NETT \$ 580.00
 LABOUR \$2,250.00
\$4,683.44

LESS 20% \$3,746.75
\$3,750.00

14 DAYS