



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA			Ref: CC4/ASM21009944/Bpa3q2 Date: 16/03/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4569U	Veh. Inspected	SMP 9755H	
Policy No.	P2419140	Coverage (\$)	0.00	
Claim No.	S1M03ILR	Excess (\$)	0.00	
Assign From		Assign Date	23/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72005509	Colour	BLUE	
Odometer	122818 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WEST LAKE	6 mm	
L/H Front Tyre	185/60 R15	WEST LAKE	6 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2021	Inspection Date	23/09/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			11 Working Days	