

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/769/2021/JT  
**DATE** : 20-Sep-21  
**WIP** : 45118

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/9/21**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR TAN INN POH BERNARD ( CHEN YINBAO BERNARD)  
**ADDRESS** : 962 DUNEARN ROAD  
#07-30  
SINGAPORE 589487  
**TELEPHONE** : HP +65 97401570  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900112346-02  
**VEHICLE NO** : **SJX 249 E**  
**MODEL CODE** : Q2 1.0 TFSI S  
**MODEL YEAR** : 24/6/2019  
**ENGINE NO** : CHZ A91072  
**CHASSIS NO** : WAUZZZGA5KA000599  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 17-Sep-21  
**PLACE OF ACCIDENT** : ALONG CLEMENCEAU AVE

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJX 249 E**

| S/N                         | NATURE OF JOBS                                                                                                                                 |        | ESTIMATED CHARGES  | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                          | S/N \$ | 360.00 ✓           | ✓                          |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                          | S/N \$ | 400.00 ✓           | 250                        |
| 3                           | TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.        | S/N \$ | 280.00 ?           | ×                          |
| 4                           | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 2,400.00 1100 ✓    | ✓                          |
| 5                           | TO REPSRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. ?                                                                                | \$     | 3,000.00 1000 ✓    | ✓                          |
| 6                           | TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                          | S/N \$ | 280.00 ✓           | ✓                          |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                 | S/N \$ | 192.00 ✓           | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                | :      | <b>\$ 6,912.00</b> |                            |

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 249 E**

|                              |                                      |     | DAMAGED PARTS & PRICES |                     |
|------------------------------|--------------------------------------|-----|------------------------|---------------------|
| S/N                          | PARTS DESCRIPTION                    | QTY | S/NETT                 | REMARKS             |
| 1                            | FRONT BUMPER - LH                    | 1   | \$ 894.00              | de 714.80           |
| 2                            | FRONT BUMPER FIXING PARTS            | 1   | \$ 347.00              | ? nn                |
| 3                            | FRONT BUMPER AIR GUIDE GRILLE - LH   | 1   | \$ 169.00              | cut 135.20          |
| 4                            | FRONT BUMPER END CAP - LH            | 1   | \$ 59.00               | ? nn                |
| 5                            | FRONT BUMPER SPOILER                 | 1   | \$ 299.00              | cut 238.80          |
| 6                            | FRONT BUMPER CLOSING ELEMENT         | 1   | \$ 156.00              | ? nn                |
| 7                            | FRONT WHEEL SPOILER - LH             | 1   | \$ 34.00               | ? nn                |
| 8                            | FRONT BUMPER ADAPTER - LH            | 1   | \$ 36.00               | ? nn                |
| 9                            | FRONT HEADLIGHT MOUNTING - LH        | 1   | \$ 118.00              | ? nn                |
| 10                           | FRONT HEADLIGHT - LH                 | 1   | \$ 4,915.00            | cut 3932            |
| 11                           | FRONT HEADLIGHT CYLINDER WASHER - LH | 1   | \$ 142.00              | ? nn                |
| 12                           | FRONT HEADLIGHT WASHER HOSE          | 1   | \$ 182.00              | ? nn                |
| 13                           | FRONT BUMPER GUIDE SECTION - LH      | 1   | \$ 36.00               | ? nn                |
| 14                           | FRONT WHEEL ARCH COVER - LH / RH     | 2   | \$ 644.00              | cut LH - RH? 514.40 |
| 15                           | FRONT FENDER - LH                    | 1   | \$ 1,147.00            | bf 917.60           |
| 16                           | FRONT FENDER ATTACHEMENT PART        | 1   | \$ 40.00               | ? nn                |
| 17                           | FRONT FENDER TOP BRACKET - LH        | 1   | \$ 48.00               | ? nn                |
| 18                           | FRONT FENDER CENTER BRACKET - LH     | 1   | \$ 16.00               | ? nn                |
| 19                           | FRONT FENDER REAR BRACKET - LH       | 1   | \$ 23.00               | ? nn                |
| 20                           | FRONT FENDER BRACE bent              | 1   | \$ 44.00               | ? 34.88             |
| <b>SUB TOTAL SPARE PARTS</b> |                                      | :   | <b>\$ 9,349.00</b>     |                     |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

photo.  
 Deformed

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 249 E**

|                             |                                            |     | DAMAGED PARTS & PRICES  |             |
|-----------------------------|--------------------------------------------|-----|-------------------------|-------------|
| S/N                         | PARTS DESCRIPTION                          | QTY | S/NETT                  | REMARKS     |
| 21                          | FRONT WHEEL HOUSING LINER - LH deformed    | 1   | \$ 196.00               | ? 156.40    |
| 22                          | FRONT WHEEL HOUSING LINER ATTACHEMENT PART | 1   | \$ 57.00                | ? nn        |
| 23                          | FRONT ALUMINIUM RIM - LH                   | 1   | \$ 949.00               | cut 758.80  |
| 24                          | SUNDRIES                                   |     | \$ 300.00               | ? nec 21.04 |
| <b>TOTAL SPARE PARTS</b>    |                                            | :   | \$ 10,851.00            |             |
| <b>TOTAL LABOUR CHARGES</b> |                                            | :   | \$ 6,912.00             |             |
| <b>GRAND TOTAL</b>          |                                            | :   | \$ <del>12,353.00</del> | 17,763.00   |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Tanjiu 97495747  
# 23/9/21 @ 1415  
Not Authorise, Repair  
Ex: to be advise  
Resurvey before paint. 05 days  
tanjiu @ khando-wan

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT