

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Estimate No: EST2100244
Date: 23 Sep 2021

Veh Reg No: SLG9097H
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053ZEE106158978
Reg. Date: 04/11/2009
Your Ref No: SGS3702E

Claim Type: Third Party
Accident Date: 17/09/2021
TP Veh Reg No: SGS3702E

Xiao Chen

Estimate Repair Cost to Vehicle No :SLG9097H

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC FRT BUMPER <i>Delhd</i>	453.80 ✓	
2	1 PC FRT BUMPER REINFORCEMENT <i>Dented</i>	367.20 ✓	
3	1 PC FRT BUMPER LOGO <i>Delhd</i>	60.10 ✓	
4	1 PC FRT BUMPER GRILLE <i>Delhd</i>	121.90 ✓	
5	2 PCS FRT BUMPER SIDE RETAINERS <i>in</i>	120.20 ✓	
6	1 PC HEADLAMP RH <i>crashd</i>	691.50 ✓	
		1,814.70	
	Less 25%	453.68	1,361.04
Special Net			
7	1 PC FRT LOWER SPOILER <i>Delhd</i>	500.00 ✓	
8	1 PC FRT GRILLE <i>Delhd</i>	280.00 ✓	
9	1 PC FRT GRILLE TRD EMBLEM <i>in</i>	50.00 ✓	
10	1 SET FRT BUMPER CLIPS <i>in</i>	60.00 ✓	
11	1 SET FRT BUMPER SIDE PROTECTOR <i>in</i>	150.00 ✓	
12	1 PC FRT NUMBER PLATE <i>Delhd</i>	50.00 ✓	
		1,090.00	1,090.00
Labour			
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	500.00 ✓	
14	1 TO SPRAY PAINTING	500.00 ✓	
15	1 TO CHECK WIRING	50.00 ✓	
		1,050.00	1,050.00

1814.70

1361.02

780

830

400

200

450

400

30

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 17/09/2021
TP Veh Reg No: SGS3702E

Estimate No: EST2100244
Date: 23 Sep 2021

Veh Reg No: SLG9097H
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEE106158978
Reg. Date: 04/11/2009
Your Ref No: SGS3702E

Estimate Repair Cost to Vehicle No :SLG9097H

Quantity	Description	List Price	Amount
		SS	SS
	Total		S\$ 3,501.04
	Add GST @ 7%		245.07
	Total Amount Payable		S\$ 3,746.11

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED FORTY SIX AND CENTS ELEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

Alvin
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

blud: 297102 Adrian L
A/S: 2350 A/S 28/09/21
03 Sep

2350 Resurveyed. 06/12/21
Sl.S.