

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 22 Apr 2022

Preliminary Advice

Insured : SLP1446P
Vehicle No
TP Vehicle No : SMD87A
Accident Date : 23/09/2021
Make : PORSCHE PANAMERA 4S
Assignment Date : 24/09/2021
Date of Inspection : 24/09/2021
Est. Duration of Repair : 7
Inspection At : JWG INTERNATIONAL PTE LTD (HQ)
BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK
AUTOPOINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,423.15
Revised Amount	:S\$	18,882.17
Check Items (Estimated)	:S\$	0.00
Total	:S\$	18,882.17

Lump Sum Repair	:S\$	15,000.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00

COE / PARF Rebate	:S\$ 32,099.00
Salvage Value	:S\$
Margin for Repair	:S\$ 107,901.00

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.