

REF: MSG/ 210098511ku

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/P 91082728

Fax : 64816131

Yang Jia Qiang
Blk 108A Rivervale Crescent
#16-341
Singapore 541180

Not WhatsApp
Call @ 4200h
Resurvey After Paint
5days

Vehicle No : SJM 851 Z
Make : Honda Stream
Year : 2008

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	903.20
1 pc	Rear tail-gate outer handle	181.90
2 pcs	Rear no plate lamp	
1 pc	Rear tail-gate emblem "Stream "	
1 pc	Rear tail-gate inner trim board	
1 pc	Rear tail-gate inner lock	195.20
1 pc	Rear tail-gate glass moulding	Q388.50
2 pcs	Rear tail-lamp assy	
1 pc	Rear wiper motor	481.90
1 pc	Rear end panel	353.10
1 pc	Rear end panel inner garnish	
1 pc	Rear boot rubber	
2 pcs	Rear fender inner trim board	
1 pc	Rear boot floor panel top cover board	
1 pc	Rear bumper	683.60
2 pcs	Rear bumper side retainer	
2 pcs	Rear bumper bracket	
1 pc	Rear exhaust silencer	

MSD	\$45.10	\$985.70	✓
MSD		\$265.70	✓
MSD		\$90.20	✓
MSD		\$45.60	✓
MSD		\$285.70	✓
MSD		\$255.30	✓
MSD		\$55.20	✓
MSD	\$485.10	\$970.20	✓
MSD		\$485.90	✓
MSD		\$482.30	✓
MSD		\$185.70	✓
82.90SW		\$165.80	30h
	\$455.20	\$910.40	X
		\$385.70	X
		\$950.70	✓
	\$65.20	\$130.40	X
	\$48.60	\$97.20	X
		\$846.70	X
		\$7,594.40	
Less 20 %		\$1,518.88	
		\$6,075.52	

S. Nett Item

1 pc	Rear reverse camera
1 pc	Rear windscreen sealant
1 pc	Rear no plate
0 pcs	Rear bumper clip

MSD	\$450.00	250h
MSD	\$55.00	40h
MSD	\$45.00	X
\$2.50	\$25.00	✓
	\$575.00	

balance c/f \$6,650.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SJM 851 Z

balance b/f \$6,650.52

Labour Charges

Remove/renew the above parts including knockng, welding & cutting.	\$1,000.00	600
To putty and spray paint	\$1,000.00	660
Check and reconnect wiring.	\$40.00	201
To spray anti rust on accident affected portion.	\$120.00	601
Remove/renew rear windscreen glass	\$120.00	✓
Remove/refit rear boot upholstery to facilitate repair	\$120.00	601
Remove/renew rear exhaust silencer	ⁿⁿ \$120.00	X
Total	<u>\$9,170.52</u>	