



Claim	S1M03I96
Reference	CS3/ASM21009957/R1uce2 
Loss Date	17 September 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	20 Sep 2021 11:14:38 AM
Request Date	24 September 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	GBF7871B
Vehicle	
Registration #	
Make	TPVD Toyota
Model	HIACE DX

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107296.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	22 October 2021

FAQ English (SG) ▾ Elaine Kuan ▾			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	...	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 October 2021
	 GBF7871B RESURVEY PHOTOS.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	15 October 2021	
	 GBF7871B INSPECTION PHOTOS.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	15 October 2021	
	 EMAIL FROM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	24 September 2021	
	 GIA INSD SHC1135C.pdf.pdf	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	22 September 2021	