

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 59474 Page No. : 1 of 5
Date Estimated : 10/09/2021
Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR -

Wong Yik Pern Reuben
8 College Avenue East
#05-61

Singapore 138615

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9888P	WBA6V120305R45474	25/08/2020	216i Gran Tourer	23514

DESCRIPTION

VALUE

To replace rear bumper, boot lid including to knock out dented area caused by the accident

~~1700~~ 2,550.00

To respray rear bumper and boot lid

~~1826~~ 1,923.00

To carry out body cavity preservation.
(Per panel).

~~112~~ 118.00

To remove and install rear windscreen glass to facilitate repair.

~~574~~ 574.00

To conduct water leak tests.

~~75~~ 75.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

~~504~~ 521.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

~~168~~ 177.00

To check electrical wiring system and lighting at the rear section for proper function.

~~168~~ 177.00

Sundries.

~~80~~ 150.00

Total Labour 1: **6,275.00**

DESCRIPTION

QTY

PRIC

VALUE

BOOTLID 1			
RR BUMPER LH SIDE GUIDE ^{? xsu}	1	1,216.40	1,216.40
# REAR BUMPER CARRIER ^{? xsu}	1	161.15	161.15
# RR BUMPER LH INNER SIDE GUID ^{? xsu}	1	483.40	483.40
# REAR BUMPER TRIM STRIP (BLAC ^{x su}	1	161.15	161.15
# REAR BUMPER PANEL PRIMED (LI ^{de}	1	72.20	72.20
	1	1,050.65	1,050.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59474
Date Estimated : 10/09/2021
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9888P	WBA6V120305R45474	25/08/2020	216i Gran Tourer	23514

DESCRIPTION	QTY	PRIC	VALUE
# LETTERING 216i <i>Xan</i>	1	64.75	64.75
GROMMET <i>Xan</i>	2	0.80	1.60
PLAQUE 74MM <i>Xan</i>	1	71.95	71.95
REAR WINDOW (ESG) ? <i>photo Xan</i>	1	657.60	657.60
HOOK AND LOOP FASTENER ? <i>Xan</i>	6	2.20	13.20
REAR LH REFLECTOR ? <i>Xan</i>	1	39.05	39.05
REAR LH LIGHT IN THE SIDE PANEL <i>Xan</i>	1	376.30	376.30
(DG) CLEANER R1 (100ML) <i>Xan</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>Xan</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>Xan</i>	1	27.85	27.85

Total Parts : 4,686.50

Claims OD / 3rd Party Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 27/09/21 @ 1026 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90010668 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-insurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,275.00
Parts	:	4,686.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	767.31
Grand Total	:	11,728.81

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 59474**
Date Estimated : **10/09/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -

Wong Yik Pern Reuben
8 College Avenue East
#05-61

Singapore 138615

- ACCOUNT - **219**

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9888P	WBA6V120305R45474	25/08/2020	216i Gran Tourer	27279

DESCRIPTION	ORIGINAL PRICE	NETT
-------------	----------------	------

DESCRIPTION	UNIT PRICE	QTY	NETT
# EXPANDING NUT nec ✓	1.00	2.00	2.00
# BUMP STOP nec ✓	3.20	10.00	32.00

SUPPLEMENTARY ITEMS

Total Labour :	0.00
Total Parts :	34.00
Total Labour & Parts :	34.00