

DING AUTO PTE LTD

Blk 176 #04-06
 Sin Ming Drive (Sin Ming Autocare)
 Singapore 575721
 Tel: 83636141
 Fax: 6452 0614

Vehicle:	SMK6940K
Model:	AUDI A5 COUPE 2.0L TFSI QUATTRO
Chassis:	WAUZZZ8T5AA032550

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	FRT BUMPER <i>Bu/Al</i>	1	\$ 2,000.33	5%	\$ 1,900.31	✓
2	BUMPER DAMPER <i>Sm</i>	1	\$ 200.85	5%	\$ 190.81	X
3	BUMPER REINF SUPPORT <i>R</i>	1	\$ 999.55	5%	\$ 949.57	X
4	BUMPER SIDE AIR GUIDE RH	1	\$ 133.75	5%	\$ 127.06	?
5	BUMPER LOWER TRIM COVER	1	\$ <i>R</i> 400.77	5%	\$ 380.73	X
6	BUMPER JET WASH ASSY & COVER RH <i>Sm</i>	1	\$ 500.55	5%	\$ 475.52	X
7	BUMPER RETAINER RH <i>Or</i>	1	\$ 80.17	5%	\$ 76.16	✓
8	BUMPER PARKING SENSOR ASSY RH (1PC) <i>Sm</i>	1	\$ <i>Sm</i> 251.75	5%	\$ 239.16	X
9	CENTRE GRILLE BASE + CH TRIM + BADGE	1	\$ 1,400.75	5%	\$ 1,330.71	?
10	FRT TOP SUPPORT PANEL + GARNISH <i>Prt</i>	1	\$ 1,600.22	5%	\$ 1,520.21	<i>CPT</i> ✓
11	FRT FENDER RH <i>Bu</i>	1	\$ 1,111.22	5%	\$ 1,055.66	✓
12	FENDER INNER SHIELD COVER RH <i>Sm</i>	1	\$ 388.75	5%	\$ 369.31	X
13	HEADLAMP ASSY RH <i>CPT</i>	1	\$ 2,500.33	5%	\$ 2,375.31	✓
14	HEADLAMP MODULE CPL RH <i>Sm</i>	1	\$ 1,009.75	5%	\$ 959.26	X
15	FRT ALLOY RIM RH <i>Sm</i>	1	\$ 2,333.10	5%	\$ 2,216.44	X
TOTAL:					\$ 14,166.22	

*Not Notified
 U/Pap & ?
 The survey After Paint
 3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SPECIAL NETT		QTY	PRICE	SURVEYOR MARKING
1	STICKER WRAPPING - FRT BUMPER, BONNET AND FENDER RH	(8/1) 1	\$ 1,500.00	?
2	PARKING SENSOR ASSY RH (1/PC)	SL 1	\$ 280.00	X
3	FRT BUMPER AND FENDER CLIPS	1/2 1	\$ 120.00	✓
4	HEADLAMP - ECU REPROGRAMMING	1	\$ 450.00	?
SPECIAL NETT:			\$ 2,350.00	

LABOUR		PRICE	SURVEYOR MARKING
1	SPRAY PAINT - FRT BUMPER, FENDER RH AND BONNET(INNER/OUTER)	\$ 1,500.00	500l
2	PANEL BEATING AND STRAIGHTEN ACCIDENT AREA	\$ 800.00	400l
3	REMOVE AND INSTALL FRT BUMPER COMPONENTS	\$ 250.00	50l
4	ALIGN HEADLAMP AND TEST WIRING	\$ 120.00	20l
5	ALIGN REVERSE SENSOR AND TEST WIRING	\$ 120.00	?
TOTAL:		\$ 2,790.00	

PARTS	\$ 14,166.22	
LABOUR	\$ 2,790.00	
SPECIAL NETT	\$ 2,350.00	
TOTAL	\$ 19,306.22	
GST 7%	\$ 1,351.44	
FINAL TOTAL	\$ 20,657.66	