

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No :200704370C

Not Authorised
Date
24/9/21

Repair sum 7000
7 days.

24/9/2021

India International Insurance Pte Ltd

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GBD 84145

NO	QTY	DESCRIPTION	Nett items
1	1 PC	FLOOR PANEL REPAIR	\$ 0.00
2	1 PC	LH WIPER ARM	\$ 107.30
3	1 PC	NUMBER PLATE LAMP GARNISH	\$ 352.00
4	1 PC	REAR BUMPER	\$ 485.90
5	1 PC	REAR BUMPER SPONGE	\$ 94.00
6	2 PCS	REAR DOOR HINGE	\$ 162.60
7	1 PC	REAR END PANEL INNER	\$ 697.00
8	1 PC	REAR END PANEL TOP GARNISH	\$ 83.30
9	1 PC	REAR LH DOOR	\$ 1,469.50
10	1 PC	REAR LH DOOR CATCH	\$ 34.80
11	1 PC	REAR LH DOOR LOCK	\$ 115.50
12	1 PC	REAR LH DOOR RUBBER	\$ 88.40
13	1 PC	REAR NISSAN " NV200"	\$ 141.70
14	1 PC	REAR NISSAN LOGO	\$ 157.20
15	1 PC	REAR RH DOOR	\$ 1,102.20
16	1 PC	REAR RH DOOR CATCH	\$ 34.80
17	1 PC	REAR DOOR "DCI" STICKER	\$ 136.00
18	1 PC	REAR RH DOOR LOCK	\$ 115.80
19	1 PC	REAR RH DOOR RUBBER	\$ 72.60
20	2 PCS	REAR RH LAMP	\$ 619.60
21	2 PCS	REAR BUMPER REFLECTOR	\$ 123.80
			\$ 6,194.00
			less 10%
			\$ (619.40)
			\$ 5,574.60
			S.NETT
22	1 PC	REAR END PANEL OUTER	\$ 135.00
23	1 PC	REAR WIPER MOTOR	\$ 212.20

24	1 PC	LH WIPER ARM CAP	nn	\$	13.10	X	
25	1 PC	REAR "70 km/h"	nee	10	\$	15.00	10
26	1 PC	REAR DOOR "5 pax"	nee	10	\$	15.00	10
27	4-PC/50f	REAR BUMPER CLIPS	nee	30	\$	50.00	30
					\$	440.30	
28	1-PC Set	REAR BUMPER REVERSE SENSOR	shot/b nee		\$	6,014.90	
29	2 SET	REAR WINDSCREEN SEALANT			\$	250.00	200 s/n
30		TRANSFER DOOR FITTING			\$	60.00	✓
31		REMOVE AND REFIX REVERSE SENSOR			\$	320.00	120
32		REMOVE & REFIT REAR WINDSCREEN (2PCS)			\$	80.00	50
33		SPRAY PAINTING			\$	240.00	200
34		LABOUR CHARGE			\$	1,750.00	950
35		WIRING CHECK			\$	1,650.00	1200
36		TUFFCOAT			\$	50.00	20
37					\$	120.00	90
				Total	\$	<u>10,534.90</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5257.50

102

P-4726.35

S.N-445

L-2630

7801.35

102
704.