



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

lock 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

24-Sept-2021

India International Insurance Pte Ltd

64 Cecil Street #05-00

IOB Building

SINGAPORE (049711)

Dear Sirs,

RE: Cost of repair to Yamaha FZ16ST- FBH7612Y

1pc of Front Fork	S\$	480.00
1pc of Steering Cone Stand		160.00
1pc of Head Lamp		320.00
1pc of Front Fairing		180.00
1pc of Centre Fairing		140.00
1pc of Brake Pump		110.00
1pc of Handle Bar		45.00
1pc of Windscreen		35.00
1pc of Exhaust Pipe Cover		65.00
1pc of Front Footrest		28.00
1pc of Brake Pedal		45.00
1pc of Front Signal Light		28.00
1pc of Handle Balancer		20.00
1pc of Handle Grip		25.00
		<hr/>
		1,681.00
	Less 10%	168.10
		<hr/>
	Nett	1,512.90
	Transport	40.00
	LTA Fees	7.50
	Alignment Front Sprc	65.00
	Labour	250.00
		<hr/>
		<u>\$1,875.40</u>

Yours Faithfully,

Southern Motor



Date: 24 Sept 2021

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
SINGAPORE (049711)

Dear Sirs,

RE: ACCIDENT INVOLING FBH7612Y AND SLG4107X ALONG
Along Holland Dr ,Singapore ON 24-07-2021 AT 14:00 PM

Please be informed that the above-said motorcycle bearing registration no: FBH7612Y was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.