



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
lock 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

24-Sept-2021
India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
SINGAPORE (049711)

Dear Sirs,

RE: Cost of repair to Yamaha FZ16ST- FBH7612Y

	LOCAL REPAIR (BT)		
1pc of Front Fork	Repair	Rasul	S\$ 480.00 220.00(SN)
1pc of Steering Cone Stand	XNN		160.00
1pc of Head Lamp	Scr /	Ap 90010068	320.00
1pc of Front Fairing	scr /	4 days	180.00
1pc of Centre Fairing	scr /	4 days	140.00
1pc of Brake Pump	XNN	1/3	110.00
1pc of Handle Bar	XNN	27/09/21 @ 130	45.00
1pc of Windscreen	scr /	Reng after repair	35.00
1pc of Exhaust Pipe Cover	scr /		65.00
1pc of Front Footrest	scr /		28.00
1pc of Brake Pedal	scr /		45.00
1pc of Front Signal Light	scr /		28.00
1pc of Handle Balancer	scr /		20.00
1pc of Handle Grip	cut /		25.00
			1,681.00
			Less 10%
			168.10
			Nett
			1,512.90
			Transport XNN
			40.00
			LTA Fees
			7.50
			Alignment Front Sprc
			65.00
			Labour
			250.00
			<u>\$1,875.40</u>

Yours Faithfully,
Southern Motor



LKK Auto Cons. Agents hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: