

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLH5688Z
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

WS Ref: TP INDIA
 Claim Type: Third Party
 Accident Date: 21/09/2021
 TP Veh Reg No: SHD2315M

Estimate No: ES2190902/WS
Date: 23 Sep 2021
Policy No:
Veh Reg No: SLH5688Z
Make/Model: TOYOTA TOYOTA
 LEXUS ES250
Chassis No: JTHBJ1GG502091624
Engine No:
Reg. Date: 07/10/2016

Not Notified
 U/Sing &
 Recovery After Pain

Estimate Repair Cost to Vehicle No :SLH5688Z

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	926.20	1 PC	R1 926.20	✓
2 REAR BUMPER REINFORCEMENT	656.40	1 PC	R1 656.40	✓
3 REAR BUMPER SPONGE	146.70	1 PC	CM 146.70	✓
4 REAR BUMPER LH SIDE RETAINER	122.80	1 PC	Di 122.80	✓
5 REAR BUMPER SCREW COVERS	12.50	2 PCS	25.00	?
6 REAR BUMPER LH REFLECTOR	59.90	1 PC	Rv 59.90	✓
7 REVERSE SENSORS	490.80	3 PCS	1,963.20	LHR
8 REAR BUMPER CLIPS	3.90	8 PCS	31.20	✓
9 REAR BOOT	888.10	1 PC	R1 888.10	✓
10 REAR BOOT LOGO	66.70	1 PC	Rv 66.70	✓
11 REAR BOOT EMBLEM (ES 250)	65.80	1 PC	Rv 65.80	✓
12 REAR BOOT REFLECTORS	590.60	2 PCS	CM 1,181.20	✓
13 REAR BOOT LH HINGE	168.20	1 PC	168.20	?
14 REAR BOOT OUTER GARNISH	360.85	1 PC	360.85	?
15 REAR BOOT INNER LOCK	478.50	1 PC	Rv 478.50	✓
16 REAR BOOT INNER RUBBER	237.90	1 PC	Di 237.90	5088Z
17 REAR BOOT INNER GARNISH	462.70	1 PC	Return 462.70	✓
18 REAR END CENTRE PANEL	795.30	1 PC	R1 795.30	✓
19 REAR END CENTRE PANEL INNER TOP GARNISH	380.70	1 PC	Rv 380.70	✓
20 TAILLAMPS	727.20	2 PCS	1,454.40	✓
21 TAILLAMP PANEL LH	198.10	1 PC	198.10	?
22 REAR LH FENDER INNER GARNISH	719.50	1 PC	719.50	?
23 REAR SPARE TYRE COMPARTMENT	842.00	1 PC	RTB 842.00	✓
24 SMART KEY SENSOR	235.00	1 PC	235.00	?
25 REAR SPARE TYRE HOLDER SCREW	39.90	1 PC	CM 39.90	✓
26 REAR SPARE TYRE TOP BOARD	580.80	1 PC	Return 580.80	✓
27 REAR EXHUAST	595.13	1 PC	595.13	?
28 CENTRE EXHAUST	810.60	1 PC	810.60	?
			14,492.78	
			Less 25%	10,869.59

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

WS Ref: TP INDIA
 Claim Type: Third Party
 Accident Date: 21/09/2021
 TP Veh Reg No: SHD2315M

Estimate No: ES2190902/WS
Date: 23 Sep 2021
Policy No:
Veh Reg No: SLH5688Z
Make/Model: TOYOTA TOYOTA
 LEXUS ES250
Chassis No: JTHBJ1GG502091624
Engine No:
Reg. Date: 07/10/2016

Estimate Repair Cost to Vehicle No :SLH5688Z

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
29 REMOVE & REFIX REAR BUMPER, TAILLAMPS, REAR BOOT, CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE COMPARTMENT, KNOCK & REPAIR REAR BOTH FENDERS & REALIGN THE SAME	1,300.00	1 LA	1,300.00	1200/
30 REMOVE & REFIX REAR SEAT, CARPET, GARNISH, ETC	80.00	1 LA	80.00	✓
31 REMOVE & REFIX REAR UNDER CARRIAGE, REAR EXHAUST & CHECK SYSTEM	180.00	1 LA	180.00	?
32 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR PANEL, BOOT, BUMPER, REINFORCEMENT	1,200.00	1 LA	1,200.00	1100/
33 RUSTPROOFING	90.00	1 LA	90.00	✓
34 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	?
			2,910.00	2,910.00
			Total	S\$ 13,779.59
			Add GST @ 7%	964.57
			Total Amount Payable	<u>S\$ 14,744.16</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/09/2021 19:20 (SGT)
Date of Accident 21/09/2021 13:10 (SGT)
Exact Location of Accident Singapore
Additional Location Information SEMBAWANG RD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH5688Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LAW GEK MENG
NRIC No SXXXX876G
Email Address law_jo1961@hotmail.com
Mobile Phone No (Phone) +65-90033544
Alternative Phone No +65-90033544

VEHICLE PARTICULARS

Manufacturer Toyota
Model LEXUS ES250 A/T S/R
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2494

INSURANCE COMPANY

Name of Insurance Company EQ Insurance Company Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPPHQ20-006862
Cover Note Number 7/10/20-6/10/21

DRIVER

Name of Driver LAW GEK MENG
NRIC No SXXXX876G

