

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLH5688Z
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100
 ATTN: Motor Claim Department

FAX: 62247743

Estimate No: ES2190902/WS
Date: 23 Sep 2021

Policy No:
Veh Reg No: SLH5688Z
Make/Model: TOYOTA TOYOTA
 LEXUS ES250
Chassis No: JTHBJ1GG502091624

WS Ref: TP INDIA
Claim Type: Third Party
Accident Date: 21/09/2021
TP Veh Reg No: SHD2315M

Not Notified
 C/Sing @ 10,850/-
 Recovery After Pains
 7 days

Engine No:
Reg. Date: 07/10/2016

Estimate Repair Cost to Vehicle No :SLH5688Z

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER 926.20	926.20	1 PC	R ₁ 926.20	✓
2 REAR BUMPER REINFORCEMENT	656.40	1 PC	R ₁ 656.40	✓
3 REAR BUMPER SPONGE	146.70	1 PC	CM 146.70	✓
4 REAR BUMPER LH SIDE RETAINER	122.80	1 PC	Diy 122.80	✓
5 REAR BUMPER SCREW COVERS	12.50	2 PCS	Sun 25.00	X
6 REAR BUMPER LH REFLECTOR	59.90	1 PC	Ru 59.90	✓
7 REVERSE SENSORS @ 490.80	490.80	3 4 PCS	1,963.20	CH 1492.40
8 REAR BUMPER CLIPS	3.90	8 PCS	rec 31.20	✓
9 REAR BOOT 888.10	888.10	1 PC	R ₁ 888.10	✓
10 REAR BOOT LOGO	66.70	1 PC	rec 66.70	✓
11 REAR BOOT EMBLEM (ES 250)	65.80	1 PC	rec 65.80	✓
12 REAR BOOT REFLECTORS	590.60	2 PCS	CM 1,181.20	✓
13 REAR BOOT LH HINGE	168.20	1 PC	R 168.20	X
14 REAR BOOT OUTER GARNISH	360.85	1 PC	CM 360.85	✓
15 REAR BOOT INNER LOCK 478.50	478.50	1 PC	Ru 478.50	✓
16 REAR BOOT INNER RUBBER	237.90	1 PC	Diy Ru 237.90	508.50
17 REAR BOOT INNER GARNISH	462.70	1 PC	Return 462.70	✓
18 REAR END CENTRE PANEL	795.30	1 PC	R ₁ 795.30	✓
19 REAR END CENTRE PANEL INNER TOP GARNISH	380.70	1 PC	Ru 380.70	✓
20 TAILLAMPS @ 703.30	727.20	2 PCS	1,454.40	✓
21 TAILLAMP PANEL LH	198.10	1 PC	R 198.10	X
22 REAR LH FENDER INNER GARNISH	719.50	1 PC	Sun 719.50	X
23 REAR SPARE TYRE COMPARTMENT	842.00	1 PC	RT/Bu 842.00	✓
24 SMART KEY SENSOR	235.00	1 PC	Ru 235.00	✓
25 REAR SPARE TYRE HOLDER SCREW	39.90	1 PC	CM 39.90	✓
26 REAR SPARE TYRE TOP BOARD	580.80	1 PC	Return 580.80	✓
27 REAR EXHUAST	595.13	1 PC	R ₁ 595.13	✓
28 CENTRE EXHAUST	810.60	1 PC	R ₁ 810.60	✓
			14,492.78	
		Less 25%	3,623.20	10,869.59

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711
 TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

Estimate No: **ES2190902/WS**
 Date: 23 Sep 2021
 Policy No:
 Veh Reg No: **SLH5688Z**
 Make/Model: TOYOTA TOYOTA
 LEXUS ES250
 Chassis No: JTHBJ1GG502091624
 Engine No:
 Reg. Date: 07/10/2016

WS Ref: TP INDIA
 Claim Type: Third Party
 Accident Date: 21/09/2021
 TP Veh Reg No: SHD2315M

Estimate Repair Cost to Vehicle No :SLH5688Z

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
29 REMOVE & REFIX REAR BUMPER,TAILLAMPS,REAR BOOT,CUT,WELD & RENEW REAR END PANEL,REAR SPARE TYRE COMPARTMENT,KNOCK & REPAIR REAR BOTH FENDERS & REALIGN THE SAME	1,300.00	1 LA	1,300.00	1200/
30 REMOVE & REFIX REAR SEAT,CARPET,GARNISH,ETC	80.00	1 LA	80.00	✓
31 REMOVE & REFIX REAR UNDER CARRIAGE,REAR EXHAUST & CHECK SYSTEM	180.00	1 LA	180.00	750/
32 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR FENDERS,REAR PANEL,BOOT,BUMPER,REINFORCEMENT	1,200.00	1 LA	1,200.00	1100/
33 RUSTPROOFING	90.00	1 LA	90.00	✓
34 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
			2,910.00	2,910.00
			Total	S\$ 13,779.59
			Add GST @ 7%	964.57
			Total Amount Payable	S\$ 14,744.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLH 5688Z
 SUPP 1

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711
 TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

Estimate No: ES2190902/WS
 Date: 24 Sep 2021
 Policy No: DMPPHQ20-006862
 Veh Reg No: SLH5688Z
 Make/Model: TOYOTA TOYOTA
 LEXUS ES250
 Chassis No: JTHBJ1GG502091624
 Engine No:
 Reg. Date: 07/10/2016

WS Ref: TP INDIA
 Claim Type: Third Party
 Accident Date: 21/09/2021
 TP Veh Reg No: SHD2315M

Estimate Repair Cost to Vehicle No :SLH5688Z

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
Supplementary 1				
1 REVERSE SENSOR WIRE HARNESS	380.50	1 PCS	380.50	✓
2 REAR SPARE TYRE PANEL UNDER COVER	352.80	1 PC	352.80	✓
3 REAR EXHAUST PIPE LH EXTENSION	210.50	1 PC	210.50	✓
4 REAR EXHAUST PIPE LH HOLDER BUSH	40.70	1 PC	40.70	✓
5 CENTRE EXHAUST PIPE REAR HOLDER BUSH	40.70	1 PC	40.70	✓
6 REAR LH CHASSIS BRACKET	458.25	1 PC	458.25	✓
7 FRONT EXHAUST	2,908.20	1 PC	2,908.20	✗
8 REAR LH CONTROL BAR	280.10	1 PC	280.10	✓
		1 PC		
		Less 25%		
		Total		S\$ 4,387.55
		GST Amount		S\$ 287.04
		Total Amount Payable		S\$ 4,387.55

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Part \$12,653.28
 1,763.55

 \$14,416.83
 3,604.21

 \$10,812.62
 1,185.50
 2680

 \$13,611.12
 4/3 \$10,850 ✓