

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJX 8181M

Vehicle Model : MITSUBISHI LANCER

Chassis Number : JMYSRCY1AGU006844

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____
Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID X nn	1	\$ 693.00
2	BOOT LID WEATHERSTRIP X nn	1	\$ 166.00
3	BOOT LID LOCK X nn	1	\$ 67.00
4	BOOT LID LOGO X nn	1	\$ 47.00
5	BOOT LID LAMP (LH & RH) X nn	2	\$ 1050.00
6	"LANCER" EMBLEM X nn	1	\$ 39.00
7	"MIVEC" EMBLEM X nn	1	\$ 44.00
8	C & C STICKER X nn	1	\$ 41.00
9	TAIL LAMP (LH & RH) X nn	2	\$ 1050.00
10	REAR BUMPER / 00	1	\$ 815.00
11	REAR BUMPER CLIPS / npc	10	\$ 50.00
12	REAR BUMPER RETAINER (LH & RH) / BR	2	\$ 40.00
13	REAR BUMPER REINFORCEMENT ? / BT	1	\$ 210.00
14	REAR BUMPER REFLECTOR (LH & RH) ? / BR	2	\$ (LH) 44.00
15	TOWING CAP X nn	1	\$ 20.00
16	END PANEL ? x R	1	\$ 506.00
17	END PANEL UPPER GARNISH X nn	1	\$ 150.00
18	SPARE TYRE TANK BOARD X nn	1	\$ 165.00
			\$ 5197.00
			10%
			\$ 519.70
List Prices Total			\$ 4,677.30

1117
-10%
1005.30

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR / Shorted	1SET	\$ 350.00 200
2	REAR NUMBER PLATE WITH HOLDER / BT	1SET	\$ 60.00 45
Special Nett Total			\$ 410.00
Spare Part's Total Price			\$ 5087.30

245

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJX 8181M

Vehicle Model : MITSUBISHI LANCER

Chassis Number : JMYSRCY1AGU006844

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1500.00
2	TO SPRAY PAINTING ON: BOOT LID (INNER & OUTER), REAR BUMPER, REAR END PANEL.	\$ 1200.00
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 120.00
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00
5	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$ 150.00
5	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 150.00

Need to adjust Labour Boot lid got dented.

860

= 2110.30

Labour Total \$ 3400.00

L/S - 1688.24

Parts & Labour Total \$ 8487.30

= 1700

Steve (LKK)

27/9/21, 11.30am

ML AL

L/S

My AL sy

3 dys