

June Repairing

4/10/21



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

		SLM 6761 L	
		Finalised	
Parts	(a) Cost / List Price Items	\$ 8459.70	18,474.00
	Plus/Less 20%	\$ 1691.94	3,694.80
	Total of Cost / List	\$ 6767.76	14,779.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	450.00
Total Parts Cost		\$	15,229.20
Labour		\$ 1240.00	3,190.00
Total		\$ 8007.76	18,419.20

Not Authorized
C/Rm 86400/h
Heavy After Pain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

201
= \$6400.00

Name of Surveyor : Memorh
Company : LKK
Survey conducted on : 27/9/21 at 10:35

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 27/9/21

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SLM 6761 L**
Make & Model : **MAZDA 6**
Chassis No. : **JM6GL1031H0120220**

Submit By : **Carmen Lim**
Year Manufacture : **2017 Apr**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Bonnet	1	\$1,285.00		X
2	Bonnet lock	1	\$269.00		X
3	Bonnet hinge LH	1	\$67.00		X
4	Bonnet hinge RH	1	\$67.00		X
5	Headlamp RH <i>Gmm1-51-031F CM</i>	1	\$4,975.00		✓
6	Front grille <i>mgcm</i>	1	\$161.00		7
7	Front grille logo <i>mc</i>	1	\$86.00		7
8	Front grille chrome <i>cm</i>	1	\$195.00		7
9	Front support panel (complete) <i>pu</i>	1	\$594.00		X
10	Front bumper <i>1211-90 Bt/Tn</i>	1	\$1,342.00	1211-90	✓
11	Front bumper clip <i>mc</i>	10	\$50.00		✓
12	Front bumper reinforcement	1	\$680.00		X
13	Front bumper side retainer LH	1	\$35.00		X
14	Front bumper side retainer RH <i>cm</i>	1	\$35.00		✓
15	Front bumper bracket LH	1	\$48.00		X
16	Front bumper bracket RH	1	\$48.00		X
17	Front bumper sponge	1	\$97.00		X
18	Front bumper chrome moulding RH <i>pu</i>	1	\$112.00		✓
19	Fog lamp RH <i>mg cm</i>	1	\$694.00		7
20	Fog lamp garnish RH <i>cm</i>	1	\$53.00		7
21	Front bumper sensor <i>pu</i>	1	\$254.00		7
22	Front bumper lower rubber	1	\$176.00		X
23	RH front fender	1	\$394.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

8134-90

It will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLM 6761 L**
 Make & Model : **MAZDA 6**
 Chassis No. : **JM6GL1031H0120220**

Submit By : **Carmen Lim**
 Year Manufacture : **2017 Apr**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front fender undershield	1	\$165.00		✓
25	RH front fender undershield clip	10	\$50.00		✓
26	RH front lower arm	1	\$554.00		X
27	RH front shock absorber	1	\$393.00		X
28	RH front shock absorber top mouting	1	\$107.00		X
29	RH front shock absorber stopper	1	\$65.00		X
30	RH front knuckle arm	1	\$448.00		X
31	RH front knuckle bearing	1	\$597.00		X
32	RH front wheel hub	1			.
33	RH front wheel hub lock nut	1	\$35.00		X
34	RH front tie rod	1	\$165.00		X
35	RH front tie rod end	1	\$185.00		X
36	RH front drive shaft	1	\$2,525.00		X
37	RH front rim	1	\$1,498.00		X
38	RH front tyre	1	\$450.00	S.N	X
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

215



ESTEEM

Supplementary

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SLM 6761 L
Make & Model : MAZDA 6
Chassis No : JM6GL1031H0120220

Submit By : JENNY
Year Manufacture : 2017 Apr
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Washer tank	1	\$109.80		✓
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

109.80

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 0484 1221 (F) 6484 7829

Labour

Vehicle No. : SLM 6761 L
Make & Model : MAZDA 6

Submit By : Carmen Lim
Year of Manufacture : 2017 Apr

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,SUPPORT PANEL, RHF FENDER,RHF DOOR)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,SUPPORT PANEL, RHF FENDER,RHF DOOR)	\$1,000.00	600
3	To check wiring	\$50.00	20
4	To remove & refit front bumper sensor	\$120.00	50
5	To tuff coat	\$150.00	30
6	To remove & refit aircon condensor to assist work load,to top up A/C gas. <i>nn</i>	\$150.00	X
7	To remove & refit radiator to assist work load. <i>nn</i>	\$150.00	X
8	To remove & refit undercarriage to assist work load. <i>nn</i>	\$250.00	X
9	To do wheel alignment. <i>nn</i>	\$120.00	60

1240