

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 8388E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	TORN	880.00	880.00
1	FRONT BUMPER SIDE HOLDER LH (CONSISTENT)	NECESSARY	32.00	32.00
1	HEADLAMP LH (CONSISTENT)	CRACKED	1,860.00	1,860.00
1	HEADLAMP LOWER BRACKET LH (CONSISTENT)	NOT NECESSARY	78.00	-
1	FRONT LH FENDER (CONSISTENT)	DISTORTED	591.00	591.00
1	FRONT LH FENDER ARC GARNISH (CONSISTENT)	CUT	185.00	185.00
1	FRONT LH FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	179.00	-
1	BONNET (CONSISTENT)	DENTED	992.00	992.00
1	BONNET HINGE LH (CONSISTENT)	NOT NECESSARY	79.00	-
1	FRONT LH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	988.00	-
1	FRONT LH DOOR WING MIRROR (CONSISTENT)	DAMAGED	952.00	952.00
	LESS 20% DISCOUNT		-	-1,098.40
			6,816.00	4,393.60
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT LH FENDER ARC GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	FRONT LH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT LH WHEEL RIM (SN) (CONSISTENT)	NOT NECESSARY	800.00	-
			880.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR.		1,000.00	800.00
	SPRAY PAINTING.		1,000.00	900.00
	WIRING.		50.00	30.00
	TO SPRAY TUFF COAT.		150.00	80.00
	TO TRANSFER DOOR FITTINGS.	NOT NECESSARY	150.00	-

Report Ref No. CS/ASM21010007/Avce2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			2,500.00	1,810.00
	GRAND TOTAL		10,196.00	6,253.60

RECOMMENDED COST OF LUMP SUM REPAIRS		5,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM21010007/Avce2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.