



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Ref: CS/TP21010008/Uqf3e2 Date: 05/10/2021 Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected	SME 3547P	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	27/09/2021	
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E 250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2120472A575214	Colour	BLACK
Odometer	205278 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40ZR18	PIRELLI	6 mm
L/H Front Tyre	245/40ZR18	PIRELLI	6 mm
R/H Rear Tyre	245/40ZR18	PIRELLI	6 mm
L/H Rear Tyre	245/40ZR18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/09/2021	Inspection Date	27/09/2021
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	