

ASS. REC. BY: *MC6145*

REF:

CS/ TP210.10008/U9f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

MMUC Ajax account 129-3-2022
3d brake rep/6k worth 5061

Veh No:

Type: *M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /*

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *in order* / Jammed / Leaked / Burnt orBrake: *in order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD AIRim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / *PIR* / SUMI

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 04/10 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS __ \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: TP

Lump Sum ~~4800~~ (\$ 4800

TOTAL

3/10/21 2/5 @ 4800 confirmed with MR Yip (Red \$5189.87, 52%)

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

Not Attached
H/M
27/5/21
1/5 \$4800
H/dmg

VEHICLE No: SME 3547P

1PC	BOOTLID	R	\$2,165.00	X
1PC	BOOTLID REAR LOGO	nee	\$69.40	/
1PC	BOOTLID 7 G-TRONIC EMBLEM	nee	\$75.00	/
1PC	BOOTLID E 250 EMBLEM	nee	\$82.00	/
1PC	BOOTLID C&C LOGO	nee	\$50.00	/
1PC	BOOTLID WEATHERSTRIP	11	\$232.20	X
1PC	REAR BUMPER	25 / ne	\$1,537.12	X
1PC	REAR BUMPER LOWER GARNISH	215	\$288.20	/
1PC	REAR BUMPER CENTRE CHROME MOULDING	scr/nee	\$232.35	/
2PCS	REAR BUMPER SIDE CHROME MOULDINGS @ \$161.00	scr/nee	\$322.00	/
1PC	REAR BUMPER PDC SENSOR	shotel	\$195.00	/
1PC	REAR BUMPER REINFORCEMENT	berf	\$545.22	/
1SET	REAR BUMPER CLIPS & RIVERT	nee	\$60.00	/
2PCS	REAR BUMPER SIDE HOLDERS @ \$165.00	o/s cr	\$330.00	1pc
1PC	REAR BUMPER EXHAUST CHOME O/S	berf	\$182.00	/
1PC	REAR BUMPER TOP RETAINER	cr	\$158.20	/
1PC	REAR END PANEL	R	\$813.70	X
1PC	REAR END PANEL TOP GARNISH	11	\$223.50	X
1PC	TAILLAMP O/S	cr	\$672.30	/
			\$8,233.19	
			LESS 10%	\$7,409.87

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO SPRAY RUST PROOFING	11 \$50.00	X
TO RESET & REPROGRAMME SYSTEM	\$100.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	600
TO PUTTY & SPRAY PAINTING	\$1,280.00	1000
TOTAL	\$9,989.87	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

463379
102
417041