

LKK Mechanical Inspection Request

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Wed 22/9/2021 6:54 AM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Raziz TAHAR (SPF) <Raziz_TAHAR@spf.gov.sg>; Beifeng NG (SPF) <NG_Beifeng@spf.gov.sg>; Mohamed Sufian MOHAMED JUNID (SPF) <Mohamed_Sufian_Mohamed_Junid@spf.gov.sg>; MUHAMMAD FIRDAUS SULEIMAN (SPF) <Muhammad_Firdaus_SULEIMAN@spf.gov.sg>; Mohamed Yazid MOHAMMED YUSOFF (SPF) <Mohamed_Yazid_Mohammed_Yusoff@spf.gov.sg>; Kia Huat YEO (SPF) <YEO_Kia_Huat@spf.gov.sg>; Jocelyn LOH (SPF) <Jocelyn_Loh@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the following **24 cases**. The ones marked in **red** are deemed to be **urgent**:

SN	Case IAFP-IB-20210920 IP No.	Brief Facts	Vehicles to be inspected:	IO In-Charge:
1-2	TP/IP/28539/2021	On 11 June 2021 (Friday) at 5.08 p.m., the Involved Party (who was driving minibus, PC4587S) was travelling along Geylang Road towards Kallang Road on lane 2 of 4-lane road when he collided onto the deceased (riding motorcycle FBE1045P) who was stationary in between lane 2 and 3 of the 4-lane road due to red light. The Deceased sustained multiple injuries and was pronounced dead at the hospital.	PC4587S - Driver (Potential Defendant) FBE1045P - Rider (Deceased)	SIO Raziz
3-4	TP/IP/31841/2021	On 5 July 2021 (Monday) at 7.51 a.m., the Involved Party (who was driving motor trailer XE3668T) was travelling along KJE(BKE) on lane 3 of 4-lane road when it ran over the Deceased who was riding the motorcycle FBC2692A. The deceased had self-skidded and encroached into the path of the Involved Party's trailer. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene.	XE3668T - Driver (Involved Party) FBC2692A - Rider (Deceased)	SIO Raziz
5-6	TP/IP/32687/2021	On 8 July (Thursday) 2021 at about 8.48 a.m., the deceased was riding his	SFW87H - Driver (Potential Defendant)	SIO Raziz

		<p>motorcycle FBK2349A along Upper Changi Road East towards Upper Changi Road North when the Involved Party who was driving the motorcar SFW87H made an unauthorised U-turn from the opposite direction and encroached into the travel path of the deceased. The deceased's motorcycle subsequently collided into the left rear portion of the Involved Party's motorcar. The deceased sustained multiple injuries and was pronounced dead at the hospital.</p>	<p>FBK2349A - Rider (Deceased)</p>	
7	TP/IP/40473/2021	<p>On 25 August 2021 at about 6.47 a.m., the Involved Party (driving bus SG5051H) was travelling along Ang Mo Kio Avenue 4 towards Ang Mo Kio Avenue 3 and had made a right turn into Ang Mo Kio Avenue 3 towards Ang Mo Kio Avenue 1 on green traffic light signal. While making the right turn, the front left portion of the Involved Party's bus had collided onto the deceased (a pedestrian) who was walking across the signalised pedestrian crossing. As a result of the collision, the deceased was pinned underneath the left rear tyre of the Involved Party's bus. The deceased sustained multiple injuries and was pronounced dead at scene.</p>	<p>SG5051H - Driver (Potential Defendant)</p>	SIO Raziz
8	TP/IP/43293/2021_	<p>On 10 September 2021 at about 4.43 a.m., the driver of motorcar, SJM7807G was travelling along SLE towards BKE on lane 1 of a 3 lane road, suddenly motorcar skidded and hit onto the right wall kerb. The impact caused the motorcar to flung upwards into the air before it overturned. While the motorcar was overturning, one passenger flung out from the motorcar and was landed in-between lane 1 and lane 2. Due to the</p>	<p>SJM7807G - Driver (Potential Defendant)</p>	SIO Beifeng

		accident, 2 victims were unconscious and conveyed to Khoo Teck Puat by ambulance.		
9	TP/IP/44019/2021	On 15 September 2021 at about 5.15 a.m., the driver of motorcar, SMN5166U was driving down the ramp from Deck 2B to Deck 2A of the Multi-Storey Carpark when she claimed that her brake was not responding as such resulted in her losing control of her motorcar and collided onto a parked car and a pillar (government property).	SMN5166U - Driver (Potential Defendant)	SIO Sufian Junid
10	TP/IP/31475/2021	On 4 July 2021 at about 10.03 a.m., the rider was riding his motorcycle along Airport Boulevard when he lost control and skidded. No other vehicles were involved in the collision. The rider subsequently succumbed to his injuries and was pronounced dead at CGH at 10.53 a.m.	AY6262C - Rider (Deceased)	SIO Firdaus
11	TP/IP/25247/2021	On 23 May 2021 at about 4.16 a.m., the rider was riding his motorcycle along SLE (BKE) when it is believed that he had lost control of his motorcycle and skidded. The rider subsequently succumbed to his injuries and was pronounced dead at KTPH at 5.56 a.m.	FBG9095G - Rider (Deceased)	SIO Firdaus
12 - 13	TP/IP/26221/2021	On 28 May 2021 at about 11.57 a.m., the rider was riding his motorcycle (FBN8422R) on lane 1 of the 2-lane road along Penjuru Lane towards Tg Penjuru when the collision occurred with a prime mover (XE2159C) at the uncontrolled cross-junction of Penjuru Road by Penjuru Lane. The prime mover was travelling along Penjuru Road towards Penjuru End on lane 1 of the 2-lane road. No other	XE2159C - Driver (Involved Party) FBN8422R - Rider (Deceased)	SIO Firdaus

		vehicles were involved in the collision. The rider subsequently succumbed to his injuries and was pronounced dead at NTFGH at 1.11 p.m.		
14 - 15	TP/IP/37441/2021	On 6 August 2021 at about 5.45 p.m., the motorcar (SGW32D) was driving on lane 2 of the 3-lane road along Macpherson Road towards Airport Road. The lorry (GX2399C) was travelling ahead of the motorcar on the same lane. The motorcar subsequently switched to the left lane when he saw the pedestrian appeared ahead of the lorry from his right to left. The motorcar subsequently swerve his car to the right and collided onto the left portion of the lorry. The car was unable to avoid the pedestrian and the front left portion of the car collided onto the pedestrian. No other vehicles were involved in the collision. The pedestrian subsequently succumbed to her injuries and was pronounced dead at TTSH at 6.43 p.m.	SGW32D - Driver (Involved Party) GX2399C - Driver (Involved Party)	SIO Firdaus
16	TP/IP/43987/2021	On 14 September 2021 at about 1025 hrs, the rider of motorcycle FBA7474R was travelling along AYE towards MCE and at the 18.4 km collided onto a stationary trailer on lane 4 which had broken down. The rider of the motorcycle was pronounced dead at the scene.	FBA7474R - Rider (Deceased)	DOC Yazid
17-21	TP/IP/35321/2021	On 23 July 2021 at about the driver of motorcar SGH 1678 M was travelling along CTE 4km towards SLE when the driver lost control of her car and collided onto 2 motorcycles, a lorry and a taxi that was ahead of the driver. As a result one of the motorcyclist was sent to TTSH in an	SGH1678M - Driver (Potential Defendant) SHB8077Z - Driver (Involved Party) GBD5455T - Driver (Involved Party)	DOC Yazid

		unconscious state and was pronounced dead in TTSH on the same day.	FBJ3860M - Rider (Involved Party) FBR5386K - Rider (Deceased)	
22	TP/IP/38483/2021	On 13 August 2021 at about 0656 hrs, the cyclist was cycling along Hougang Ave 3 and at the junction of Lorong Ah Soo collided with a pedestrian who was crossing at the street. The pedestrian was sent to CGH unconscious and on the same day succumbed to his injuries.	Bicycle - Pedal Cyclist (Deceased)	DOC Yazid
23	TP/IP/43543/2021	On 12/09/2021 at about 0836hrs, the driver of motorcar, SJR3657Y was travelling on lane 1 of 3-lane road along Ayer Rajah Expressway towards Marina Coastal Expressway when he lose control of his vehicle and skidded to the right before he counter-steered to the left and collide into 2 portions of the left side fuard railing. Driver of SJR3657Y claimed that the steering wheel had suddenly locked to the right which caused the motorcar to veer to the right.	SJR3657Y - Driver (Potential Defendant)	SIO Kia Huat
24	TP/IP/43407/2021	On 11 September 2021 at about 0759hrs, the Deceased was running across the road at the pedestrian crossing when the pedestrian man colour was red. At this juncture, the driver of lorry, GBE4524D, was driving along Old Airport Road towards Dunman Road and collided onto the Deceased's right side. As a result of the collision, Deceased sustained head injuries, unconscious and was conveyed by the ambulance to TTSH. The Deceased was	GBE4524D - Driver (Potential Defendant)	SIO Kamaliah

		pronounced dead at TTSH at 0859hrs by Dr Jefferson Chua.		
--	--	---	--	--

- 2. These request has been approved by my management.
- 3. Thank you, Sirs.

cc: Mr Bryan & OC FAIT, fyip
SIO Raziz, SO Beifeng, SIO Sufian, SIO Firdaus & SIO Yazid, as requested by you

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



Singapore Police Force **W** police.gov.sg **FB** fb.com/singaporepoliceforce **IG** instagram.com/singaporepoliceforce

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error.