

Stere(LKK)
1/10/21

Without Prejudice

2 days

P/P

Resurvey Before Spray

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 01 Oct 2021

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR MERCEDES BENZ SPRINTER 516 - YP4059A ACCIDENT INVOLVING YP4059A & SMU4731H ON 03/08/2021

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear Step Panel board — BT	1pc	\$ 629.29 —
2	Rear Step Panel board rivet @\$3.8ea — nec	7pcs	\$ 26.60 20 nett —
3	Rear bumper — BR	1pc	\$ 590.39 —
			\$ 1,246.28
	Less 10%		\$ (124.62)
			\$ 1,121.66
4	Rear sensor — BR	1set	\$ 220.00 200 nett —
<u>Labour Charge & Misc</u>			
	To remove, repair, replace & install damaged parts.	}	\$ 500.00 300
	To R & R sensor wiring		\$ 100.00 50
Total			\$ 1,941.66

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

P - 1219.68

- 10%

1097.71

n - 220

L - 350

P/P = 1667.71

