

**Section A - Accident Details**



Registration Number	SHB5318X
Case Reference Number	TAX/09/21/2038
Registration Date	30/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIANG FOO SEW
Type of Accident	Side Swipe
Accident Date and Time	17/9/2021 11:15 AM
Accident Reported Date and Time	17/9/2021 1:23 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112357
Special Instruction to ARC, if any	TP/ LEFT PORTION / AIG - LKK
Prepared Date and Time	21/9/2021 2:20 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$936.00	\$480.00
Total Spare Part Cost	\$2,827.86	\$106.38
Total Other Cost	\$680.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,119.86</b>	<b>\$786.38</b>
<b>Lump Sum Total</b>	<b>\$5,100.00</b>	<b>\$800.00 (L/S)</b>
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	22/09/2021 3:00 PM	22/09/2021 2:06 PM
Signature		
Remarks		RESURVEY AFTER REPAIR

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-2110-0038	Invoice Number	
Quotation Date	05.10.2021	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$676.00	\$200.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$936.00</b>	<b>\$480.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$680.00</b>	<b>\$0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87940474 40	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given
		87945470 60A1	COVER, OUTER MIRROR, LH	1.00	\$89.50	100.00	\$0.00	Replace	Repair
		67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		69210470 51A1	DOOR OUTER HANDLE FRONT, LH	0.00	\$378.90	0.00	\$0.00	Replace	Not Given
		69217470 20	DOOR FRONT, COVER OUTER HANDLE, LH	1.00	\$17.30	25.00	\$12.98	Replace	Replace
		67004472 10	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair
		67896470 10	WEATHERSTRIP, REAR DOOR, NO.2, LH	0.00	\$33.20	0.00	\$0.00	Replace	Check
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace
<b>Total</b>					<b>\$4,416.30</b>		<b>\$132.98</b>		

X NN  
R  
R  
√ NEC  
X NN  
√ NEC  
R  
X NN  
√ NEC

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	132.98	
	-20%	
	106.38	L/S \$800/-
+	200.00	
+	480.00	
	786.38	