

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21010034/TGA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800080331
Claimant Vehicle No :	SHB7602L	Insured Vehicle No :	SMC5528S
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	2129997736SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7602L		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C33850
Reg. Date:	27/06/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU503081963
Colour:	Red	Odometer:	214593 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,376.17	1,455.25	4,920.92	77.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	600.00	2,990.00	83.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,966.17	2,055.25	7,910.92	79.38
+ GST 7.00/7.00% (S\$)	697.63	143.87	553.76	79.38
Nett Amount (S\$)	10,663.80	2,199.12	8,464.68	79.38
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$112.35/day) (S\$)		449.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,855.97		

INSPECTION

Date of Assignment:	17/09/2021		
Date Inspected:	17/09/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Deformed	442.60 FL	*442.60 FL
2	1		*GUARD ,REAR BUMPER ,CENTER	Deformed	576.30 FL	*576.30 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Deformed	15.40 FL	*15.40 FL
4	1		*FILLER ,REAR BUMPER EXTENSION RH	Not Necessary	123.70 FL	*- FL
5	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
6	1		*RETAINER ,REAR BUMPER SIDE,RH	Not Necessary	116.50 FL	*- FL
7	1		*COVER ,FLOOR UNDER NO.1 (RH)	Not Necessary	175.10 FL	*- FL
8	1		*COVER ,REAR FLOOR (CTR)	Not Necessary	229.90 FL	*- FL
9	1		*LENS AND BODY ,REAR LAMP ,RH	Not Necessary	502.00 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Not Necessary	443.30 FL	*- FL
11	1		*COVER ,DECK TRIM ,REAR	Not Necessary	126.70 FL	*- FL
12	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Not Necessary	650.30 FL	*- FL
13	1		*PANEL SUB-ASSY ,BACK DOOR	Not Necessary	1,147.80 FL	*- FL
14	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	925.60 FL	*- FL
15	1		*STAY ASSY ,BACK DOOR ,LH	Not Necessary	242.50 FL	*- FL
16	1		*STAY ASSY ,BACK DOOR ,RH	Not Necessary	242.50 FL	*- FL
17	1		*HINGE ASSY ,BACK DOOR ,LH	Not Necessary	61.00 FL	*- FL
18	1		*HINGE ASSY ,BACK DOOR ,RH	Not Necessary	61.00 FL	*- FL
19	1		*PARKING AID	Not Working	700.00 FS	*200.00 FS
20	1		*REAR FLOOR COVER CLIP	Not Necessary	60.00 FS	*- FS
21	1		*REAR LOWER BUMPER CLIP	Not Necessary	65.00 FS	*- FS
22	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
23	1		*BOOT STICKER TRANSCAB	Necessary	100.00 FS	*100.00 FS
24	1		*BOOT STICKER TEL NO	Necessary	100.00 FS	*100.00 FS
25	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
27	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,979.90	1,797.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,603.73	341.75
Total Parts (\$\$)	6,376.17	1,455.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	400.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$\$)			3,590.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >