

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010041/RPA3Q2**Date:** 01/02/2023REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D21MCV0003293 |
| Claimant Vehicle No : | SJT8811A | Insured Vehicle No : | GBH480G |
| Date of Loss: | 17/09/2021 | Nature of Claim: | TP |
| | | Claim No: | MCV2021D0004133 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SJT8811A | Engine No: | CHZ567842 |
| Make & Model: | VOLKSWAGEN GOLF, 1.2 TSI (A) | Chassis No: | WVWZZZAUZJW080548 |
| Reg. Date: | 29/12/2017 (Man. Year: 2017) | Odometer: | 76024 km |
| Colour: | White | | |
| Engine Capacity: | 999 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 856.80 | 856.80 | 0.00 | 0.00 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 680.00 | 400.00 | 280.00 | 41.18 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 1,547.80 | 1,267.80 | 280.00 | 18.09 |
| + GST 7.00/7.00% (S\$) | 108.35 | 88.75 | 19.60 | 18.09 |
| Nett Amount (S\$) | 1,656.15 | 1,356.55 | 299.60 | 18.09 |
| + Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$) | | 321.00 | | |
| + Doc/Search Fee (S\$) | | 7.49 | | |
| Nett Liability (S\$) | | 1,685.04 | | |

INSPECTION

| | | | |
|-----------------------------|------------|-------------------|--|
| Date of Assignment: | 27/09/2021 | Present Location: | Mova Automotive Pte Ltd (Bukit Merah) |
| Date Inspected: | 28/09/2021 | Inspected At: | Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 27 Jul 2022) |
| Parts: | 144 | VOLKSWAGEN GOLF 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJT8811A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--|-----|----------|------------------------------------|-----------|------------|------------|
| 1 | 1 | | *SIDE MIRROR COVER LH | Missing | 174.00 FL | *174.00 FL |
| 2 | 1 | | *SIDE MIRROR INDICATOR LIGHT LH | Cracked | 91.00 FL | *91.00 FL |
| 3 | 1 | | *SIDE MIRROR HOUSING WITH MOTOR LH | Cracked | 575.00 FL | *575.00 FL |
| 4 | 1 | | *SIDE MIRROR UNDER LAMP LH | Cracked | 112.00 FL | *112.00 FL |
| 5 | 1 | | *FRONT DOOR LH - REPAIR (NPA) | Repair | - | *- FL |
| 6 | 1 | | *A-PILLAR LH - REPAIR (NPA) | Repair | - | *- FL |
| F=Franchise part. L=ListItemDisc. | | | | | | |
| Sub Total (S\$) | | | | | 952.00 | 952.00 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | | | | | 95.20 | 95.20 |
| Total Parts (S\$) | | | | | 856.80 | 856.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|------------|--------|
| <u>Miscellaneous Items</u> | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 | 11.00 |
| Sub Total (\$\$) | | | 11.00 | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION | New | 280.00 | 100.00 |
| 2 | TO SPRAY PAINT ON REPAIRED AREAS | New | 400.00 | 300.00 |
| Gross Labour Cost (\$\$) | | | 680.00 | 400.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >