



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21010042/Uqf3e2	
			Date: 26/10/2021	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKJ 920L	Veh. Inspected	SMS 6277A	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D16752110	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	28/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GP72003045	Colour	RED	
Odometer	150407 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	NEXEN	6 mm	
L/H Front Tyre	185/60 R15	NEXEN	6 mm	
R/H Rear Tyre	185/60 R15	NEXEN	6 mm	
L/H Rear Tyre	185/60 R15	NEXEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/09/2021	Inspection Date	28/09/2021	
Survey held at	Blk 15 Kaki Bukit Road 4, Bartley , #01-53,			
Repairer	ZOOM AUTOWERKS PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	