



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : Auto & General Insurance (S) P L
(MOTOR CLAIM DEPARTMENT)

Email claims@gudgetdirect.com.sg

Xiao Chen

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SLU9466C Date: 25.09.2021
Vehicle Model: HYUNDAI TUCSON TURBO Reg. Date: 19.12.2017
Chassis No: KMHJ3812VJU628029 D.O.A: 24.09.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Tailgate <i>Repair</i>	1	\$ 1,758.90	\$ 1,758.90	<i>+</i>
2	Tailgate Lamps <i>new</i>	2	\$ 955.80	\$ 1,911.60	<i>+</i>
3	Tailgate Outer Garnish <i>deduct</i>	1	\$ 242.00	\$ 242.00	<i>✓</i>
4	Tailgate Outer Garnish Bracket <i>new</i>	1	\$ 268.50	\$ 268.50	<i>+</i>
5	Tailgate Glass Moulding 1set <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
6	Tailgate Inner Trim <i>new</i>	1	\$ 758.90	\$ 758.90	<i>+</i>
7	Tailgate Lock <i>new</i>	1	\$ 192.40	\$ 192.40	<i>+</i>
8	Tailgate Weatherstrip <i>new</i>	1	\$ 186.90	\$ 186.90	<i>+</i>
9	Tailgate Stoppers <i>new</i>	2	\$ 38.00	\$ 76.00	<i>+</i>
10	Taillamps <i>new</i>	2	\$ 893.30	\$ 1,786.60	<i>+</i>
11	Rear Fender Inner Trim - Lower <i>new</i>	2	\$ 378.40	\$ 756.80	<i>+</i>
12	Rear Bumper - Upper <i>deduct</i>	1	\$ 466.50	\$ 466.50	<i>✓</i>
13	Rear Bumper - Lower <i>deduct</i>	1	\$ 381.40	\$ 381.40	<i>✓</i>
14	Rear Bumper Side Lamps <i>new</i>	2	\$ 132.90	\$ 265.80	<i>+</i>
15	Rear Bumper Side Retainer <i>new</i>	2	\$ 48.30	\$ 97.60	<i>✓</i>
16	Rear Bumper Reinforcement <i>could</i>	1	\$ 270.30	\$ 270.80	<i>✓</i>
17	Rear Bumper Reinforcement Bracket - upper <i>new</i>	2	\$ 48.00	\$ 96.00	<i>+</i>
18	Rear Bumper Reinforcement Bracket - lower <i>deduct</i>	3	\$ 48.00	\$ 144.00	<i>✓</i>
19	Rear Bumper Reinforcement Bracket - metal <i>new</i>	2	\$ 128.80	\$ 257.60	<i>+</i>
20	End Panel <i>deduct</i>	1	\$ 785.60	\$ 785.60	<i>✓</i>

\$ 10,763.90

C/F \$ 10,763.90



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 10,763.90

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
21	End Panel Top Garnish <i>new</i>	1	\$ 225.90	\$ 225.90	<i>+</i>
22	Smartkey Antenna <i>new</i>	1	\$ 265.70	\$ 265.70	<i>+</i>
23	Smartkey Wireharness <i>new</i>	1	\$ 172.80	\$ 172.80	<i>+</i>
24	Rear Corner Radar Unit Assy LH <i>3rd</i>	1	\$ 1,596.40	\$ 1,596.40	<i>+</i>
25	Rear Corner Radar Unit Assy Bracket LH <i>an</i>	1	\$ 85.50	\$ 85.50	<i>+</i>

Total For List Items: \$ 13,110.20

Less Spare Parts Discount (20%): \$ 2,622.04

Total: \$ 10,488.16

C/F \$ 10,488.16

2387.9

1910.32



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 10,488.16

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Rear Number Plate W Casing <i>Dented</i>	1	\$ 70.00	\$ 70.00	✓
2	Tailgate Logo <i>new</i>	1	\$ 85.00	\$ 85.00	✓
3	Tailgate Emblem - Tucson <i>new</i>	1	\$ 51.00	\$ 51.00	✓
4	Tailgate Emblem - Turbo <i>new</i>	1	\$ 51.00	\$ 51.00	✓
5	Tailgate Emblem - S <i>new</i>	1	\$ 28.00	\$ 28.00	✓
6	Tailgate Inner Trim Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	+
7	Tailgate Glass Sealant <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	Rear Bumper Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	✓
9	Rear Bumper Reverse Sensor 1set <i>Damaged</i>	1	\$ 280.00	\$ 280.00	✓
10	Rear Fender Inner Cowling Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	+
11	Rear Fender Inner Trim Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	+
12	End Panel Top Garnish Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	+
13	End Panel Sealant <i>new</i>	1	\$ 80.00	\$ 80.00	60

Total For S/N Items: \$ 875.00

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,500.00	\$ 1,500.00	700
2	To spray paints affected areas	1	\$ 1,500.00	\$ 1,500.00	600
3	To tuff coat affected areas	1	\$ 150.00	\$ 150.00	60
4	To remove/refix rear interior upholstery	1	\$ 120.00	\$ 120.00	60
5	To check wiring/wire connector and rewire/repair	1	\$ 60.00	\$ 60.00	30
6	To dismantle/transfer/repair tailgate components	1	\$ 150.00	\$ 150.00	x
7	To remove/refix tailgate glass	1	\$ 150.00	\$ 150.00	x
8	To conduct water leakage testing	1	\$ 60.00	\$ 60.00	x
9	To remove/refix reverse sensors and distance setting	1	\$ 80.00	\$ 80.00	50
10	To remove/refix/replace rear reverse camera	1	\$ 80.00	\$ 80.00	x
11	To program rear corner radar system	1	\$ 350.00	\$ 350.00	x

Total For Labour: \$ 4,200.00

Grand Total: \$ 15,563.16

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Adrian L
2/s 28/09/21 - OSB

total: 4063.3
HS: 3.21c