

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Count: 09-08-2027 LYA \$ 29888
 nruu Ajax

7/10/24 4/5 \$5500 confirmed work was done 5 repair days
 (RED \$3586.80; 39%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

) \$ + RS \$ SI

) Photos

) Others

Report Format: TP

Lump Sum \$5500

TOTAL

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Adhount
all
29/9/21
1/5 @ \$5500/
5 days

VEHICLE No; SJX 1751P

1PC	BONNET	DD	\$873.20	✓
1PC	BONNET INNER RUBBER	11	\$45.00	X
2PCS	BONNET HINGES @ \$85.00	R	\$170.00	X
1PC	BONNET LOCK	twi	\$161.00	✓
1PC	FRONT BUMPER	D.S	\$1,101.40	✓
2PCS	FRONT BUMPER SIDE RETAINERS @ \$25.00	neu	\$50.00	✓
1PC	FRONT BUMPER BEAM	But	\$455.00	✓
1PC	FRONT GRILLE CHROME MOULDING	one	\$267.00	✓
1PC	FRONT GRILLE	one	\$350.40	✓
1PC	FRONT GRILLE 'H' LOGO	neu	\$45.00	✓
1PC	FRONT SUPPORT PANEL	R	\$455.80	X
1PC	FRONT SUPPORT PANEL TOP GARNISH	twi	\$162.30	✓
2PCS	HEADLAMPS @ \$1100.20	one	\$2,200.40	✓
1PC	HEADLAMP LOWER BRACKET O/S	But	\$34.20	✓
1PC	FRONT FENDER O/S	R	\$566.30	X
1PC	AIR CON CONDENSER	pin	\$899.00	X
			\$7,836.00	
			LESS 20%	\$6,268.80

S.NETT

1SET	FRONT BUMPER CLIPS	neu	\$48.00	45
1PC	FRONT LICENCE PLATE	one	\$50.00	40
1SET	FRONT BUMPER LOWER CENTRE GARNISH W/WIRE MESH	D.S	\$480.00	✓
1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	neu	\$30.00	✓

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	30
TO REFILL AIR CON GAS	\$120.00	X
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$100.00	✓
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00	600
TO PUTTY & SPRAY PAINTING	\$1,180.00	1000
TOTAL	\$9,086.80	

KKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5699.9
202
4559.92