

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TEO CHEW KUNG
BLK 646 JURONG WEST ST 61 #05-148
SINGAPORE 640646

Contact : 98193758

TPAXA.
Jaslin.

ESTIMATE

Repair Code : CLM15322

Date in : 27/09/2021

Vehicle Num. : SLU4938R

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106114691/3ZZ4784862

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER RESONATOR <i>chld</i>	1	187.60	✓ 187.60
AIR CLEANER RESONATOR AIR DUCT <i>new</i>	1	130.70	X 130.70
FRONT BUMPER <i>chld</i>	1	551.40	✓ 551.40
FRONT BUMPER 'LOGO' EMBLEM <i>new</i>	1	74.10	✓ 74.10
FRONT BUMPER LH FOGLAMP <i>chld</i>	1	298.60	✓ 298.60
FRONT BUMPER LH FOGLAMP COVER <i>chld</i>	1	82.30	✓ 82.30
FRONT BUMPER SIDE HOLDER L/R <i>LH chld Dnd</i>	2	8.60	860 17.20
FRONT BUMPER SIDE HOLDER PIN L/R <i>LH or</i>	2	2.80	2.80 5.60
FRONT BUMPER SIDE RETAINER L/R <i>LH chld</i>	2	57.50	57.50 115.00
FRONT BUMPER UPPER SEAL <i>new</i>	1	54.80	+ 54.80
FRONT GRILLE <i>new</i>	1	349.10	+ 349.10
FRONT LH FENDER <i>Dented</i>	1	712.10	✓ <u>712.10</u>
FRONT LH FENDER 'VVTI' EMBLEM <i>new</i>	1	44.10	✓ 44.10
FRONT LH FENDER BRACKET <i>Best</i>	1	58.70	✓ 58.70
FRONT LH FENDER INNER SHIELD <i>torn</i>	1	196.50	✓ 196.50
FRONT LH HEADLAMP <i>chld</i>	1	821.30	✓ 821.30
FRONT LH HEADLAMP LOWER BRACKET <i>new</i>	1	32.00	+ 32.00
FRONT LH KNUCKLE ARM <i>new new</i>	1	628.40	+ 628.40

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TEO CHEW KUNG

BLK 646 JURONG WEST ST 61 #05-148

SINGAPORE 640646

ESTIMATE

Repair Code : CLM15322

Date in : 27/09/2021

Vehicle Num. : SLU4938R

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106114691/3ZZ4784862

Contact : 98193758

FRONT LH KNUCKLE ARM BEARING	<i>Dand</i>	1	120.60	✓	120.60
FRONT LH LOWER ARM	<i>Bend</i>	1	732.50	<i>581</i>	732.50
FRONT LH LOWER ARM BALL JOINT	<i>Men</i>	1	283.30	+	283.30
FRONT LH SHOCK ABSORBER	<i>Men</i>	1	438.30	+	438.30
FRONT LH STEERING TIE ROD END	<i>Men</i>	1	186.70	+	186.70
FRONT LH WHEEL HUB	<i>Dangd</i>	1	281.30	✓	281.30
			<i>4078.50</i>		
			<i>3058.87</i>		
Subtotal before discount					6,402.20
Percentage discount 25%					1,600.55
Sub-total 1					4,801.65
FRONT BUMPER CLIPS - SET	<i>Men</i>	1	50.00	<i>30</i>	50.00
FRONT BUMPER LOWER SPOILER	<i>Dangd</i>	1	900.00	<i>700</i>	900.00
FRONT GRILLE CLIPS - SET	<i>Men</i>	1	30.00	+	30.00
FRONT LH FENDER INNER SHIELD CLIPS - SET	<i>Men</i>	1	50.00	<i>30</i>	50.00
FRONT LH TYRE	<i>Men</i>	1	280.00	+	280.00
FRONT LH WHEEL RIM	<i>Get</i>	1	500.00	<i>450</i>	500.00
Subtotal before discount					1,810.00
Percentage discount 0%					0.00
Sub-total 2					1,810.00
Parts-total					6,611.65

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TEO CHEW KUNG

BLK 646 JURONG WEST ST 61 #05-148

SINGAPORE 640646

Contact : 98193758

ESTIMATE

Repair Code : CLM15322

Date in : 27/09/2021

Vehicle Num. : SLU4938R

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106114691/3ZZ4784862

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall front suspension undercarriage parts. (to FR)

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 60.00
150 200.00
80 100.00
600 1,000.00
500 800.00
✓ 50.00

15110

Labour Total

2,210.00

Parts & Labour Total

8,821.65

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Li

h/s 28/09/21

06 Days

total: 577887

L/s: 46K

4.6K.

06 Days