

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121010053/T1UF3N2**Date:** 03/12/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBG2745K**Insured Vehicle No :** SKQ8062Z

Date of Loss: 16/09/2021

Nature of Claim:

TP

Claim No: CDMPG21001818

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBG2745K**

Make & Model: PEUGEOT PARTNER, 1.6 D L2 (A)

Engine No: 10JBHW3009200

Reg. Date: 04/07/2017 (Man. Year: 2016)

Chassis No: VF37FBHYMGJ891311

Colour: White

Odometer: 114634 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,334.40	3,578.40	756.00	17.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	630.00	800.00	55.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,764.40	4,208.40	1,556.00	26.99
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	5,764.40	3,350.00	2,414.40	41.88
+ GST 7.00/7.00% (S\$)	403.51	234.50	169.01	41.88
Nett Amount (S\$)	6,167.91	3,584.50	2,583.41	41.88

INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 29/09/2021 Inspected At:

Em-1 Auto Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate Sector C, #01-68

Singapore 575643

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Dec 2021)	
Parts:	N/A	PEUGEOT PARTNER 1.6 D L2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG2745K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	980.00 FL	*980.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	Deformed	86.00 FL	*86.00 FL
3	1		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	450.00 FL	*450.00 FL
5	1		*FRONT BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT BUMPER SIDE PAD	N/s Cut/O/s Not Necessary	380.00 FL	*190.00 FL
7	1		*FRONT GRILLE	Cracked	420.00 FL	*420.00 FL
8	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
9	1		*FRONT GRILLE BADGE	Cracked	90.00 FL	*90.00 FL
10	1		*FRONT GRILLE SURROUND GARNISH	Cracked	295.00 FL	*295.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Deformed	330.00 FL	*330.00 FL
12	1		*FRONT BUMPER BASE GARNISH	Deformed	365.00 FL	*365.00 FL
13	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	45.00 FS	*45.00 FS
14	1		*HEADLAMPS	N/s Cracked/O/s Not Necessary	1,300.00 FL	*650.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,811.00	3,971.00
- List Item Discount on L Items 10.00/10.00% (\$)	476.60	392.60
Total Parts (\$)	4,334.40	3,578.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	600.00	200.00
3	CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$)			1,430.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >