

Our reference:

21-7838

Date:

16/6/2021

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 5/6/2021

Koh Chee Siong Derek

In accordance with your instructions received in this office on

8/6/2021

, we made arrangements to

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB

Singapore 41780 Hotline: 6385 1171

examine the vehicle on

8/6/2021

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Hyundai	Registration	SJT6478S
Model	Elantra	Chassis	KMHDU41BR9U771057
Colour	Silver	Gearbox	Auto
Odometer	214954km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	195/60R15	85% Firenza
Front right	195/60R15	85% Firenza
Rear left	195/60R15	85% Firenza
Rear right	195/60R15	85% Firenza

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$5,100.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7838

Date

16/6/2021

Page

2

Section A: Damaged Parts Assessment

Section A: I	Jamaged	Parts Assessm	ent	
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Front bumper	1	deformed	622.80	622.80
Front bumper side retainer @\$28.70	2	necessary	57.40	57.40
Front bumper reinforcement	1	bent	312.50	312.50
Front bumper sponge	1	damaegd	166.50	166.50
Front bumper lower grille	1	cracked	142.15	142.15
Radiator grille	1	holder cracked	225.60	225.60
Radiator grille logo	1	necessary	32.80	32.80
Head lamp @\$526.20	2	intact	1052.40	0.00
Boot lid	1	repair.respray	982.30	0.00
Boot lid top lock	1	bent-in	145.50	145.50
Boot lid logo	1	necessary	32.20	32.20
Boot lid emblem 'AVANTE'	1	necessary	33.60	33.60
Boot lid emblem 'S'	1	necessary	18.40	18.40
Boot lid weather strip	1	reuse	112.50	0.00
Rear bumper	1	deformed	653.70	653.70
Rear bumper side retainer @\$26.50	2	necessary	53.00	53.00
Rear bumper bracket @\$92.40	2	bent	184.80	184.80
Rear bumper sponge	1	damaegd	181.80	181.80
Rear bumper reinforcement	1	bent	302.10	302.10
Tail lamp @\$298.60	2	shifted	597.20	597.20
Rear end panel	1	dented	587.50	587.50
Rear end panel top garnish	1	reuse	152.40	0.00
	Sub- Total	costs	6649.15	4349.55
Percentage	e discount :	20%	1329.83	869.91
Suk	-Total costs	for parts	5319.32	3479.64

Special Subsidiaries of Impact Analysis Consultant:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385** 11**71**

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd
 www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

		Total costs for parts		5741.82	3902.14
		Sub- Total costs		0.00	0.00
		*	*	0.00	0.00
Parts Repair					
		Sub-Total cost	s for parts =	422.50	422.50
Reverse sensor		set	malfunction =	250.00	250.00
Rear end panel sea	alant	1	necessary	40.00	40.00
Rear bumper clip (@\$5.50	10	necessary	55.00	55.00
Radiator grille clip	@\$5.50	5	necessary	27.50	27.50
Front bumper clip	@\$5.00	10	necessary	50.00	50.00
Date	16/6/2021				
Our reference	21-7838				



Our reference

21-7838

Date

16/6/2021

Page

3

Section B: Labour Cost Calculation

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

	Но	urly rate	19	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	20	\$ 900.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.		Sub-contra	act work.	\$ 950.00
Apply rust proofing on the adjacent panels.		Sub-contra	act work.	\$ 50.00
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$	45.00	1.7	\$ 76.50
Wiring and bulb checking	\$	45.00	1	\$ 45.00
		Total lab	our cost	\$ 2,021.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

[●] Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

 [■] IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

21-7838

Date

16/6/2021

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$3,902.14	
Further discount	20%	\$780.43	
Recommended cost of parts replacement		\$3,121.71	(1)
Labour Cost Calculation (See section B)		\$2,021.50	(2)
Total Repair Cost (Round off to hundred)		\$5,100.00	(1) + (2)

We would recommend a sum of	\$5,100.00	and	6	working days for repair.
No further items will be approved v	vithout our expres	sed written agree	ement. Any sig	nificant additional
items will be subject to a suppleme	ntary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd www.iaconsultingsg.com


No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780


Hotline: 6385 1171












































































































































































SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/06/2021 15:32 (SGT) Date of Accident 05/06/2021 15:00 (SGT) Exact Location of Accident PIE, Singapore Additional Location Information (CHANGI)EXIT SLIP RD TWDS JLN EUNOS

Country/State of Loss

Singapore

Private hire

Private hire

No - Claiming third party

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJT6478S

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner KOH CHEE SIONG DEREK NRIC No. SXXXX596F Email Address D3R3KKOH@HOTMAIL.COM Mobile Phone No (Phone) +65-91827279 Alternative Phone No +65-91827279

VEHICLE PARTICULARS

Manufacturer Hyundai Model Avante Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission Auto CC 1591

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage ThirdParty Fleet Policy No Policy Number DMHCSNW00007222000 Cover Note Number

DRIVER

Name of Driver KOH CHEE SIONG DEREK NRIC No. SXXXX596F



Date Of Birth	07/11/1985	
Occupation	Outdoor	
Date Of Driving Pass	30/09/2005	
Driving experience	15 YEARS AND 9 MONTHS	
Gender	Male	
Mobile Number	(Phone) +65-91827279	
Alt. Phone Number	+65-91827279	
Email Address	D3R3KKOH@HOTMAIL.COM	
Address	BLK 897A TAMPINES ST 81	
Address complement	#05-706	
Postcode	521897	
Is the driver the policyholder?	Yes	
If No, Relationship of the Driver with the Insured		
Does Driver Own Other Vehicles?	No	
Vehicle Registration Number of Other Vehicle Owned by Driver	No	
Vehicle Registration Number of Other Vehicle Owned by Driver	2	
Insurance Company of Other Vehicle Owned by Driver		
GENERAL INFORMATION OF THE ACCIDENT		
Type of Accident	Chain Collision	
Weather Conditions	AFT RAIN	
Road Surface	Wet	

OTHER INFORMATION		
Was any foreign vehicle involved in the accident?	No	
Number of vehicles involved in the accident	3	
Was anybody injured in the Accident?	No	
Was any injured conveyed to hospital by ambulance?	-	
Was any other material or property damaged?	Yes	
Number of Passengers (Including Driver)	1	
Has the driver been approached by unknown person(s)	8	
soliciting/offering accident claims assistance?	No	
DETAILS OF POLICE ACTION		
Was the accident reported to the police?	No	
Was notice of intended Prosecution given?	No	
If yes, against whom?	•	
CIRCUMSTANCES OF ACCIDENT		
PLS REFER TO THE ATTACHED STATEMENT.		
ATTACHMENT(S)		
Are considered photos quellable for attacher and	V	
Are accident photos available for attachment?	Yes	
Was there any video captured by Car Camera?		
Was there any audio recorded?	No	
DETAILS OF OTHER	R VEHICLE PROPERTY 1	
Vahiola Registration Number	0177505	
Vehicle Registration Number	SH7750E	

Vehicle Registration Number	SH7750
Vehicle Manufacturer	1
Vehicle Model	=
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	X0020-700-07
Contact Number	-
Address	-
Address complement	4



Postcode	-
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1 7 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBJ1899R
Vehicle Manufacturer	-
Vehicle Model	150
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	19 00
Address	
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	(-)
Details of property damaged in accident	÷
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Oriver 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose Lunderstand, acknowledge, agree and consent that and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims,
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect.
- use, disclose and/or process my Personal Information for one or more of the above Purposes, and (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

obcyholder's Signature / Date &	Driver's Signature (E driver is not the policyholder) / & Time	Date Witnesded by Reporting Centre Personnel
ketch Plan	P	IE change exit slip and
537/4450		reduce charact
Veh A 57164115	An	euros
Veha SHTTGOE	-	
Vehc, GP51894R	N	
	TAVA	

ribe Circumstances of the Acci		Amount Menicic
	at about 1500 Arc I was	ansis vehicle
On the 5/6/	Chang Euros Exit stip raid I That a harmonical from my rec	Shoped may seems
CITE FUTOS ON PAG		
emond traffic, suddenly	I felt a hoseimpact from my real	4 ART 1899R and
Philips Typesti Survey of	and I had been part or	HARRY MY NEWSTE
ethicle and realised t	and and that wit valuete set	44.00
AND VERNILL TRANS THE		
par and from 15 dom	24. 28. C.	
	and the second second	
Vision in the second se		
Maria		
Declaration		
2/2/	and true in every respect.	
We declare the foregoing particulars	BIG Has a cra. 7	
The second secon		
		- 6
		stur moleute
tres		11
12.7		
. 14	Driver's Signature (If driver is not the policyholder) / Date	Witnessed by Reporting Centre Personnel