

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010056/AGA3Q2**Date:** 07/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800113050
Claimant Vehicle No :	SLN9459K	Insured Vehicle No :	SKC3862M
Date of Loss:	24/09/2021	Nature of Claim:	TP
		Claim No:	1222210958SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN9459K	Engine No:	LEB5918383
Make & Model:	HONDA VEZEL HYBRID, 1.5 x (A)	Chassis No:	RU31218372
Reg. Date:	23/05/2017 (Man. Year: 2016)	Odometer:	80464 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,147.60	6,202.40	4,945.20	44.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,180.00	2,120.00	64.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,447.60	7,382.40	7,065.20	48.90
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	14,447.60	5,900.00	8,547.60	59.16
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,207.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment:	27/09/2021	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	27/09/2021 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,440.00 FS	*1,000.00 FS
2	1		*FRONT BUMPER SIDE HOLDER	N/S Damaged	68.00 FL	*34.00 FL
3	1		*FRONT BUMPER LH SIDE GRILLE	Not Necessary	74.50 FL	*- FL
4	1		*FRONT LH HEADLAMP	Cut	1,962.90 FL	*1,962.90 FL
5	1		*FRONT LH FENDER	Repair	434.50 FL	*- FL
6	1		*FRONT LH FENDER SIDE GARNISH	Deformed	198.00 FL	*198.00 FL
7	1		*FRONT LH FENDER HYBRID EMBLEM	Necessary	84.20 FL	*84.20 FL
8	1		*FRONT LH FENDER INNER SHIELD	Torn	151.80 FL	*151.80 FL
9	1		*FRONT LH DOOR SIDE MIRROR ASSY	Damaged	840.50 FL	*840.50 FL
10	1		*FRONT LH KNUCKLE ARM	Damaged	375.00 FL	*375.00 FL
11	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	215.30 FL	*215.30 FL
12	1		*FRONT LH LOWER ARM	Bent	336.90 FL	*336.90 FL
13	1		*FRONT LH SHOCK ABSORBER	Bent	373.40 FL	*373.40 FL
14	1		*FRONT LH DRIVE SHAFT	Not Necessary	1,788.40 FL	*- FL
15	1		*LH ROCKER PANEL GARNISH	Deformed	698.50 FL	*698.50 FL
16	1		*REAR LH FENDER SIDE GARNISH	Deformed	310.00 FL	*195.00 FL
17	1		*REAR LH KNUCKLE ARM	Not Necessary	360.40 FL	*- FL
18	1		*REAR LH KNUCKLE ARM BEARING	Not Necessary	385.70 FL	*- FL
19	1		*REAR LH LOWER ARM	Not Necessary	384.40 FL	*- FL
20	1		*REAR LH SHOCK ABSORBER	Not Necessary	242.10 FL	*- FL
21	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
23	1		*FRONT LH SPORT RIM	Cut	800.00 FS	*400.00 FS
24	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS
25	1		*REAR LH SPORT RIM	Cut	800.00 FS	*400.00 FS
26	1		*REAR LH TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,004.50	7,295.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,856.90	1,093.10
Total Parts (\$)	11,147.60	6,202.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REFIX FRONT REPAIR SUSPENSION	New	500.00	0.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,300.00	500.00
4	RESPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (\$\$)			3,300.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >