



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2108932

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 29/12/2021
Reference CC4/FCI21010057/Ara3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLV 8931C
Insured Veh. GBG 538E
Claim No. D21002707MFCV/1
Policy No. D-21097582MFCV
Accident Date 27/09/2021
Inspection Date 29/09/2021

Description	Total
Survey Inspection	310.00
Digital Photographs	
Transportation	
Subtotal	310.00
GST (7%)	21.70
Grand Total	331.70

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21010057/Ara3q2	
			Date: 29/12/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 538E	Veh. Inspected	SLV 8931C	
Policy No.	D-21097582MFCV	Coverage (\$)	0.00	
Claim No.	D21002707MFCV/1	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	28/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT SCENIC	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF1RFA00758990843	Colour	BROWN	
Odometer	226428 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R20	GOODYEAR	6 mm	
L/H Front Tyre	195/55 R20	GOODYEAR	6 mm	
R/H Rear Tyre	195/55 R20	GOODYEAR	6 mm	
L/H Rear Tyre	195/55 R20	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2021	Inspection Date	29/09/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 8931C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,620.00	1,252.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	146.50	-
1	REAR BUMPER LOWER DIFFUSER	DEFORMED	816.00	425.00
1	REAR BUMPER LOWER DIFFUSER GARNISH	DEFORMED	1,056.00	698.00
2	REAR BUMPER O/S & N/S REFLECTOR	NOT NECESSARY	1,320.00	-
2	REAR BUMPER O/S & N/S RETAINER	NOT NECESSARY	386.20	-
1	REAR TAIL-GATE	DEFORMED	3,480.00	2,068.00
1	REAR TAIL-GATE WEATHERSTRIP	NOT NECESSARY	289.90	-
1	REAR TAIL-GATE EMBLEM	NECESSARY	131.70	131.70
1	REAR TAIL-GATE SCENIC EMBLEM	NECESSARY	128.90	128.90
1	REAR TAIL-GATE RENAULT EMBLEM	NECESSARY	82.60	82.60
1	REAR TAIL GATE LOCK	NOT NECESSARY	564.50	-
1	REAR ENFORCEMENT	NOT NECESSARY	1,568.60	-
1	REAR WINDSCREEN MOULDING	NECESSARY	365.40	158.00
4	REAR REVERSE SENSOR	DAMAGED (2 PCS ONLY)	1,360.00	500.00
	LESS 10% DISCOUNT		-1,331.63	-544.42
			11,984.67	4,899.78
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIPS (SN)	NECESSARY	120.00	30.00
2	REAR BUMPER SCREW REAR BUMPER	NOT NECESSARY	46.60	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	REAR REG NO.PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR REG NO.PLATE BRACKET (SN)	NOT NECESSARY	29.00	-
			320.60	110.00
<u>LABOUR</u>				
	TO REMOVE AND REPLACE REAR DAMAGE PARTS.		1,000.00	500.00
	TO SPRAY PAINTING.		800.00	500.00
	TO REMOVE AND REPLACE REAR TAIL-GATE FITTINGS.		120.00	80.00
	TO RE-SEAL ANTI-RUST .	NOT NECESSARY	50.00	-

Report Ref No. CC4/FCI21010057/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR WINDSCREEN .		180.00	120.00
	TO CHECK WIRING .	NOT NECESSARY	50.00	-
	TO CHECK AND RESET FAULT CODE.	NOT NECESSARY	150.00	-
	TO REMOVE AND REPLACE REAR REVERSE SENSOR .		50.00	50.00
			2,400.00	1,250.00
GRAND TOTAL			14,705.27	6,259.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC4/FCI21010057/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 8931C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

