


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *FBH 2252K*
at Workshop m/s: *BHH 10.*
of _____
Insured: *6x26274*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *£10K.*
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: *3* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *LTA 3258* Vehicle: IN / OUT

Date / Time Action / Instruction

ABS pump n/c

23/11/14 4/5 @ 900 cont. met with Raymond

red: 2124;70%

Veh No: *FBH 2252K* Yr Regn: *29/11/16*
Type: M/Car / ☒ Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda NC750X* C.C. *745*
Colour: *3/466* A/C: *Insured / Std / NI / NA*
Sp Reading: *86709* T/Radio: *Insured / Std / NI / NA*
Eng/No: _____

C/No: *JH2RC72B4EK002486*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Good* / Jammed / Leaked / Burnt or

Brake: *Good* / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: *F: 120/70 22 17*

R: 160/60 22 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front: *6* mm Rear: *6* mm
R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. *21/9/14* D.O.I. *29/9/14*

Survey held at _____

Des. of Damages: *Frt / Rear / O/S / N/S / U/C / Rooftop* or

o/s, n/s sat
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: *3*

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO : FBH2252K
MAKE/MODEL : HON / NC700XA

NO. : 39192

DATE : 24/09/2021
CLAIM NO. : 11797
POLICY NO. : MC/0575092/02

FROM : RAYMOND

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ARM MAIN STEP LH P/N: 57703 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$98.00	98.00
2	BOLT FOOTREST P/N: 41171 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00
3	BOX REAR (KAPPA) K-VENTURE 58L P/N: 66957 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$930.00	930.00
4	BOX TOOLS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	91.00
5	CRASH BAR SET P/N: 58653 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$330.00	330.00
6	DIAGNOSTIC (ECU/ABS/FI) P/N: 53340 - (REPORTED BY MECHANIC)	labour	1.00	\$91.00	91.00
7	FOOTREST REAR LH P/N: 57715 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$60.00	60.00
8	GUARD HANDLE BAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	91.00
9	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	6.00	\$63.00	378.00

*39192 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0183
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	MIRROR LH P/N: 57708 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$148.00	CU) 148.00 ✓
11	MUDGUARD FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$364.00	n 364.00 X
12	PEDAL BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$142.00	sub 142.00 ✓
13	PEDAL CHANGE COMP. P/N: 58561 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$184.00	n 184.00 X
14	PROTECTOR MUFFLER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$103.00	sub 103.00 ✓
15	RUBBER GEAR PEDAL P/N: 25818 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	n 6.00 X

SUB TOTAL

\$3,024.00

GST @ 7 %

\$211.68

GRAND TOTAL (SGD)

\$3,235.68

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*39192 *

bizSAFE₃